Ryder Auto Pte Ltd

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921
Email: ryderautoworkshop@gmail.com
Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : SLD9387L
Accident Date : 22/9/2024
Location : BLK 26 TECK WHYE LANE

Model: NISSAN QASHQAI 30/6/2016 - 29/6/2026
3P: SLD5812D (INCOME)

S/Nos.	Qty	Description	List $	S/Nett $	Nett $
1	1 pc	Front headlamp LH Cut			2,166.00
2	1 pc	Front headlamp bracket New			31.40
3	1 pc	Front bumper Dented			810.70
4	2 pcs	Front bumper side retainer R/L New			60.00
5	1 set	Front bumper clip New 4136.70		~~50.00~~ 30	
6	1 pc	Front bumper inner sponge New			175.00
7	1 pc	Front fender LH Dented 3723.03		677	~~983.40~~
8	1 pc	Front fender inner shield LH New S.N. 30			167.20
9	1 set	Front fender inner shield clip LH New		50.00	
10	1 pc	Front fender arch garnish LH Cut		483	~~642.70~~
11	1 set	Front fender arch garnish clip LH New		30.00	
		Sub Total:	0.00	130.00	5,036.40
			30%	0%	10%
		After Less %:	**0.00**	**130.00**	**4,532.76**
		Labour			
1		To remove & refix accident damaged parts & realign accident affected area.		~~500.00~~ 450	
2		To spray paint on affected area. 880		~~550.00~~ 400	
3		To check wiring & headlamp focus.		~~50.00~~ 30	
4		To rust proof affected area.		50.00	
		Sub Total:		**1,150.00**	
		Total:		**5,812.76**	

Total: 4633.03 Adrian C
L/S: 37K 2/s 25/09/24
04 Days

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Quotations are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Chan San Choon
Director
DipEng, AAE MBIM, MSAE(Aust)

SAFE

24 hr accident call 8778 1999

Mobil 1

3.71K