EUROKARS GROUP

REPAIR ESTIMATE

Name & Address
Motor Claims Department
CHINA TAIPING INSURANCE P/L
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

Email/Fax No: | Contact No:

Vehicle No: **SMZ7788Z**
Brand & Model: **Cayenne**
Chassis/VIN No: **WP1ZZZ9YZRDA03046**
WIP#: **12644**

Date: **25-Sep-24**
Franchise: **PORSCHE**
Contact Person (Eurokars): **FAIZ**
Contact No (Eurokars): **6331 0680**

Type of Claim: **THIRD PARTY** | YEAR MODEL: **02/04/2024**

PARTS / MATERIAL CHARGES — MARK = Survey Marking [Key "A" if item is approved]

NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	REAR BUMPER RH repair	P9Y0-807-418- -G2X	1		-	$ 2,594.60
2	REAR BUMPER LOWER SPOILER scr	P9Y0-807-543-H -OK1	1		-	$ 1,615.50
3	REAR BUMPER LOWER TRIM scr	P9Y0-807-834-AL-OK1	1		-	$ 1,143.00
4	EXHAUST TRIM LH nr	P9Y0-807-837-A -OK1	1		-	$ 183.70
5	EXHAUST TRIM RH nr	P9Y0-807-838-A -OK1	1		-	$ 183.70
6	SUPPORT SHIELD LH nr photo	P9Y0-825-715- -	1		-	$ 69.10
7	SUPPORT SHIELD RH nr photo	P9Y0-825-716- -	1		-	$ 69.10
8	REAR BUMPER SOUND ABSORBER RH xmn	P9Y0-807-248- -	1		-	$ 114.20
9	SPOILER SOUND ABSORBER LH nr photo	P9Y0-807-573- -	1		-	$ 71.60
10	SPOILER SOUND ABSORBER RH nr photo	P9Y0-807-574- -	1		-	$ 71.60
11	SENSOR GASKET nr	PSQ0-919-133- -989	4		-	$ 15.60
12	CLAMP nr	P9Y0-423-337- -	4		-	$ 23.20
13	EXPANSION RIVET nr	PPAF-038-549- -	4		-	$ 3.20
14	BLIND RIVET nr	PN -908-550-01-	8		-	$ 18.40
15	EXPANDER NUT nr	PWHT-004-935- -	4		-	$ 8.00
16	REAR BUMPER CENTER BRACKET ? ~~xmn~~ svc	P9Y0-807-863-A -	1		-	$ 214.50
17	REAR BUMPER RETAINER RH xmn	P9Y0-807-406-E -	1		-	$ 104.70
18	REAR BUMPER BRACKET RH ? xsvc	P9Y0-807-376-A -	1		-	$ 150.10
19	EXPANDER NUT ? xsvc	PN -106-213-01-	9		-	$ 24.30
20	REAR BUMPER REINFORCEMENT ? xsvc	P9Y0-807-309-D -	1		-	$ 1,646.80
21	CROSS MEMBER FOR REINFORCEMENT ? xsvc	P9Y0-807-235-A -	1		-	$ 145.10
22	GASKET LH REINFORCEMENT ? xsvc	P9Y0-807-669- -	1		-	$ 15.40
23	GASKET RH REINFORCEMENT ? xsvc	P9Y0-807-670- -	1		-	$ 15.40
24	COVER LOWER END xmn	P9Y0-807-587-A -	1		-	$ 279.10
25	LOGO CAYENNE nr	P9Y0-853-670- -L10	1		-	$ 450.90
26	TAIL PIPE RH scr	P9Y0-253-824- -	1		-	$ 929.40
27	TRIM PANEL FOR CAMERA REAR ? xsvc	P9Y0-807-644-B -OK1	1		-	$ 168.00

Sub-Total (Parts Price) $ - $ 10,328.20

LABOUR / SERVICES CHARGES

NO	DESCRIPTION	REVISED	PRICE
1	TO REMOVE /REPLACE REAR BUMPER RH, REAR BUMPER LOWER SPOILER & TRIM, REINFORCEMENT & ALL ACCIDENT DAMAGED BODY PARTS TO REPAIR TAILGATE & ALL AREAS AFFECTED BY THE ACCIDENT.	1720	$ 5,160.00

EUROKARS GROUP

REPAIR ESTIMATE

2	TO RESPRAY REAR BUMPER RH, TAILGATE		1800	$ 2,800.00
3	TO CARRY OUT BODY CAVITY PRESERVATION		nil X	$ 250.00
4	TO SUPPLY REAR LICENCE PLATE WITH CASING		nett	$ Xnil 70.00
5	TO TRANSFER THE REVERSE SENSORS		nett	250 50.00
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING		150	$ 250.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS		nett	$ 600.00
8	SUNDRIES		nett	$ 20 50.00

Survey Date & Time:	Repair Days:	Excess:
27/09/24	4 days	

Surveyor Remarks:

Rasm
Rec after repair

		REVISED	PRICE
Sub-Total (Labour Price)		$ -	$ 9,680.00
Parts Price		$ -	$ 10,328.20
Labour Price		$ -	$ 9,680.00
Total (Initial Estimate)		$ -	$ 20,008.20
Supp 1		$ -	$ -
Supp 2		$ -	$ -
Supp 3		$ -	$ -
Total (Before Excess)		$ -	$ 20,008.20
Less Excess		$ -	$ -
TOTAL (After Excess)		$ -	$ 20,008.20
GST	9%	$ -	$ 1,800.74
GRAND TOTAL		$ -	$ 21,808.94

Remarks:
- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- An administrative fee of 20% of the quotation value will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: