# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561  Fax: 6844-8805   Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

| | |
|---|---|
| **Our File No:** | CS/ICS24100069/TQP3E2 |
| **Date:** | 09/10/2024 |

REFERENCE

| | | | | | |
|---|---|---|---|---|---|
| Handling Insurer: | ECICS Limited | Policy No: | | | |
| **Claimant Vehicle No :** | SHD7277G | **Insured Vehicle No :** | SNA1947R | | |
| Date of Loss: | 02/10/2024 | Nature of Claim: | TP | Claim No: | DMCF2400070H/02/CT |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|---|---|---|---|
| Reg No: | **SHD7277G** | | |
| Make & Model: | TOYOTA PRIUS, 1.8 (A) | Engine No: | 2ZR2B82152 |
| Reg. Date: | 27/11/2018 (Man. Year: 2018) | Chassis No: | JTDKB3FU603077503 |
| Colour: | Blue | Odometer: | 699511 km |
| Engine Capacity: | 1798 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S$): | **Market Value/New Car Price** | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | | |
|---|---|---|---|---|---|
| General Condition: | | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: | |

CONDITION OF TYRES

| | | | |
|---|---|---|---|
| Front Tyre Size: | 195/75 R15 | Rear Tyre Size: | 195/75 R15 |
| Front Left Side: | West Lake  6 mm | Rear Left Side: | West Lake  6 mm |
| Front Right Side: | West Lake  6 mm | Rear Right Side: | West Lake  6 mm |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|---|---|---|---|
| Parts | 2,457.49 | 1,423.80 | 1,033.69 | 42.06 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 820.00 | 690.00 | 130.00 | 15.85 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| **Calculated Gross Total (S$)** | **3,277.49** | **2,113.80** | **1,163.69** | **35.51** |
| **Approved Total (Overridden) (S$)** | | **1,700.00** | | |
| **(S$)** | 3,277.49 | 1,700.00 | 1,577.49 | 48.13 |
| **+ GST 9.00/9.00% (S$)** | 294.97 | 153.00 | 141.97 | 48.13 |
| **Nett Amount (S$)** | **3,572.46** | **1,853.00** | **1,719.46** | **48.13** |

INSPECTION

| | | | |
|---|---|---|---|
| Date of Assignment: | 03/10/2024 | | |
| Date Inspected: | 03/10/2024 | Inspected At: | ComfortDelGro Engineering Pte Ltd (Loyang)<br>59 Loyang Drive<br>Singapore 508969 |
| Estimated Period of Repair: | 2.0 days | | |

| | | | |
|---|---|---|---|
| **Adjuster:** | MOHD TAUFIKH BIN HAMID | **Manager:** | SHIAU CHAN |

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Reference

| | | |
|---|---|---|
| **Part Source:** | MRM-SG | Version: 1.0 (Last Synchronised: 08 Oct 2024) |
| **Parts:** | 144 | TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0) |
| **Labour:** | Repairer's | (Price-denominated Standard List) |
| **Print Code:** | (Unsubmitted, no print-code for SHD7277G) | |
| **Validity:** | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| **Further Info:** | Items/values not in reference catalogue are prefixed with an asterisk *. | |

## Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|---|---|---|---|---|---|---|
| 1 | 1 | | **\*REAR BUMPER** | Deformed | 503.04 FL | \*503.04 FL |
| 2 | 1 | | **\*REAR BUMPER LOWER COVER-BLACK** | Deformed | 654.96 FL | \*654.96 FL |
| 3 | 1 | | **\*REAR BUMPER SIDE BRKT LH** | Not Necessary | 112.70 FL | \*- FL |
| 4 | 1 | | **\*REAR BUMPER REINFORCEMENT** | Not Necessary | 378.32 FL | \*- FL |
| 5 | 10 | | **\*REAR BUMPER CLIPS** | Necessary | 22.00 FL | \*22.00 FL |
| 6 | 1 | | **\*REAR BUMPER EXTENSION LH** | Deformed | 148.40 FL | \*148.40 FL |
| 7 | 1 | | **\*TAILLAMP UPPER LH** | Not Necessary | 557.90 FL | \*- FL |
| 8 | 1 | | **\*TAILLAMP LOWER LH** | Cracked | 570.00 FL | \*570.00 FL |
| 9 | 1 | | **\*REAR BUMPER SIDE UNDER COVER LH** | Not Necessary | 148.40 FL | \*- FL |
| 10 | 1 | | **\*REVERSE SENSORS** | Not Necessary | 135.70 FS | \*- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|---|---|---|
| **Sub Total (S$)** | **3,231.42** | **1,898.40** |
| **- List Item Discount on L Items 25.00/25.00% (S$)** | 773.93 | 474.60 |
| **Total Parts (S$)** | **2,457.49** | **1,423.80** |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items
**There are no new miscellaneous items selected.**

## Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|----|-------------|----------|-----------|--------|
| **Labour Items** | | | | |
| 1 | **PANEL BEATING** | New | 400.00 | 380.00 |
| 2 | **SPRAY PAINTING CHARGE** | New | 300.00 | 280.00 |
| 3 | **REMOVE / REFIX REVERSE SENSOR** | New | 120.00 | 30.00 |
| | **Gross Labour Cost (S$)** | | **820.00** | **690.00** |

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**