Not authorised
L/Sup ~~$ 1,250.00~~

$ 1,250.00

AAD2410- 074

Trans-cab Auto Services Pte Ltd
No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel No Fax No. : 62571330
CO./ GST Reg. No. 201019626G
SHB7996A

22 OCT 2024

Vehicle No.:	SHB7996A
Chassis No.:	JTDKB3FU903080363
Co UEN.:	200303878K
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS
Date of Accident:	21/10/2024
Third Party Insurer:	YQ5690P / III
Date of Registriation:	24/5/2019

	PART	LIST
1	COVER, REAR BUMPER	$ 558.39
1	COVER, REAR BUMPER, LOWER	$ 19.43
1	RETAINER, REAR BUMPER SIDE, RH	$ 148.58
1	RETAINER, REAR BUMPER SIDE, LH	$ 148.58
1	SEAL, REAR BUMPER SIDE, RH	$ 111.41
1	SEAL, REAR BUMPER SIDE, LH	$ 111.41
1	GUARD, REAR BUMPER, CENTER	$ 726.92
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	$ 419.90
1	FILLER, REAR BUMPER EXTENSION, RH	$ 155.72
1	FILLER, REAR BUMPER EXTENSION, LH	$ 155.72
1	COVER, FLOOR UNDER, RH	$ 220.50
1	COVER, FLOOR UNDER, LH	$ 304.92
1	COVER, REAR FLOOR	CNA $ 290.43
1	COVER, BACK DOOR TRIM	$ 31.50
1	PANEL SUB-ASSY, BODY LOWER BACK	$ 824.46
1	LENS & BODY, REAR COMBINATION LAMP, RH (UPPER)	$ 570.15
1	LENS AND BODY, REAR LAMP, RH	$ 634.73
1	COVER, REAR COMBINATION LAMP, RH	$ 81.48
1	LENS & BODY, REAR COMBINATION LAMP, LH	$ 559.13
1	LENS AND BODY, REAR LAMP, LH	$ 634.73
1	COVER, REAR COMBINATION LAMP, LH	$ 81.48
1	PANEL SUB-ASSY, BACK DOOR	$ 1,443.86
1	SPOILER SUB-ASSY, REAR	$ 1,986.92
1	SEAL, REAR SPOILER	$ 21.32
1	BOARD ASSY, BACK DOOR TRIM	$ 326.76
1	PANEL ASSY, BACK DOOR TRIM, UPPER	$ 65.73
1	BOARD, BACK DOOR TRIM	$ 284.55
1	STAY ASSY, BACK DOOR, LH	$ 305.66
1	STAY ASSY, BACK DOOR, RH	$ 305.66
1	HINGE ASSY, BACK DOOR, LH	$ 77.18

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No. : 62571330

CO./ GST Reg. No. 201019626G

AAD2410-

SHB7996A

1	HINGE ASSY, BACK DOOR, RH	$	R 77.18 X
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	$	Sn 1,171.38 X
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	$	NN 68.88 X
1	PLATE, BACK DOOR NAME, NO.1	$	NN 68.88 X
1	ORNAMENT SUB-ASSY, BACK DOOR	$	NN 90.30 X
	TOTAL	**$**	**13,083.74**
	25%	**$**	**3,270.93**
		$	**9,812.80**

SPECIAL NETT

1SET	PARKING AID	$	Sn 700.00 X
1	REAR BUMPER CLIP	$	Nkc 65.00 60 NN
1	REAR RH BUMPER RETAINER CLIP	$	NN 65.00 X
1	REAR NUMBER PLATE	$	Sn 180.00 X
1	REAR TAIL LAMP CLIP	$	NN 65.00 X
1	END PANEL INNER TRIM CLIP	$	NN 60.00 X
1	BOOT STICKER TRANSCAB	$	NN 100.00 X
1	BOOT STICKER TEL NO	$	NN 100.00 X
1	REAR BUMPER PROTECTOR	$	Na 180.00 30 NN
2	WINDSCREEN SEALANT	$	NN 150.00 X
1	WINDSCREEN MOULDING	$	NN 200.00 X
1	WINDSCREEN INNER SPONGE SEAL	$	NN 130.00 X
	TOTAL	**$**	**1,995.00**
	TOTAL PARTS	**$**	**11,807.80**

LABOUR

To rust-proofing of the affected areas.	$	NN 600.00 X	
Putty and spray painting of the affected portion.	$	1,200.00	220
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	$	2,000.00	200
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	$	NN 170.00 X	
To transfer of tailgate fittings and conduct water seepage test.	$	NN 170.00 X	

Trans-cab Auto Services Pte Ltd
No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel Nc Fax No. : 62571330
CO./ GST Reg. No. 201019626G
SHB7996A

AAD2410-

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	$	380.00	X
To reinstall rear bumper parking sensor.	$	170.00	X
To check steering geometry and computer wheel alignment	$	220.00	X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	$	170.00	X
TOTAL	**$**	**5,080.00**	
OVERALL TOTAL	**$**	**16,887.80**	

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: