JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com

JL PERFECT AUTOWORK PTE LTD

DATE : 10.06.2024

TO	: **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO	: **SMY2038T**
MODEL	: MERCEDES A200
DATE OF ACCIDENT	: 21.06.2024
TIME OF ACCIDENT	: 19:15 HOURS

WIK1771872J274955
Xiao Tony

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER Distorted	1	$ 2,055.00	$ 2,055.00
2	FRONT BUMPER LOGO new	1	$ 105.00	$ 105.00
3	FRONT BUMPER SIDE GRILLE new	2	$ 176.00	$ 352.00
4	FRONT BUMPER RADAR SENSOR Cond	1	$ 5,866.00	$ 5,866.00
5	FRONT BUMPER RADAR SENSOR HOLDER Cond	1	$ 486.00	$ 486.00
6	FRONT BUMPER RADAR SENSOR WIRE HARNESS new	1	$ 482.00	$ 482.00
7	FRONT BUMPER UPPER BEAM Cond	1	$ 256.00	$ 256.00
8	FRONT BUMPER UPPER BEAM SIDE SUPPORT new	2	$ 92.00	$ 184.00
9	FRONT BUMPER LOWER GRILLE Int	1	$ 385.00	$ 385.00
10	FRONT BUMPER REINFORCEMENT new	1	$ 568.00	$ 568.00
11	FRONT BUMPER REINFORCEMENT ABSORB PANEL	2	$ 325.00	$ 650.00
12	FRONT BUMPER IMPACT SENSOR new	2	$ 290.00	$ 580.00
13	FRONT BUMPER SPONGE Cond	1	$ 193.00	$ 193.00
14	FRONT BUMPER TOP RUBBER new	1	$ 78.00	$ 78.00
15	FRONT BUMPER BOTTOM COVER GARNISH Cond	1	$ 388.00	$ 388.00
16	FRONT NUMBER PLATE GARNISH Cond	1	$ 239.00	$ 239.00
17	FRONT HEADLAMP (LED) Int	2	$ 3,563.00	$ 7,126.00
18	FRONT HEADLAMP RING GARNISH new	2	$ 289.00	$ 578.00
19	FRONT HEADLAMP LOWER BRACKET new	2	$ 98.00	$ 196.00
20	FRONT GRILLE WITH CHROME Cond	1	$ 1,682.00	$ 1,682.00

1205

VEHICLE NO : **SMY2038T**
MODEL : MERCEDES A200
DATE OF ACCIDENT : 21.06.2024
TIME OF ACCIDENT : 19:15 HOURS

21	FRONT GRILLE LOGO	1	$ 198.00	$ 198.00	+
22	BONNET	1	$ 2,390.00	$ 2,390.00	+
23	BONNET HINGE	2	$ 248.00	$ 496.00	+
24	BONNET BOTTOM LOCK	1	$ 168.00	$ 168.00	+
25	BONNET STOPPER	4	$ 33.00	$ 132.00	+
26	FRONT RADIATOR TOP PANEL	1	$ 1,394.00	$ 1,394.00	= 865
27	FRONT SUPPORT BRACKET	1	$ 233.00	$ 233.00	+
28	FRONT RADIATOR TOP PANEL GARNISH	1	$ 78.00	$ 78.00	+
29	FRONT RADIATOR SUPPORT STAND PANEL	2	$ 537.00	$ 1,074.00	+
34	FRONT AIR GUARD (UPPER)	1	$ 215.00	$ 215.00	+
35	FRONT AIR GUARD (LOWER)	1	$ 192.00	$ 192.00	+
36	FRONT UPPER WIND SHUTTLE (AUTOR)	1	$ 865.00	$ 865.00	−
37	FRONT LOWER WIND SHUTTLE (AUTOR)	1	$ 632.00	$ 632.00	−
30	RADIATOR	1	$ 1,655.00	$ 1,655.00	+
31	RADIATOR MOUNTING	4	$ 68.00	$ 272.00	+
38	AIRCON CONDENSER	1	$ 1,527.00	$ 1,527.00	+
39	AIRCON PIPE	1	$ 486.00	$ 486.00	+
32	INTERCOOLER	1	$ 1,140.00	$ 1,140.00	+
33	INTERCOOLER PIPE	2	$ 258.00	$ 516.00	+
40	HORN	2	$ 279.00	$ 558.00	+
41	OUTSIDE TEMPERATURE SENOSR	1	$ 147.00	$ 147.00	+
42	FRONT FENDER	2	$ 1,219.00	$ 2,438.00	+
43	FRONT FENDER COWLING (FRONT)	2	$ 198.00	$ 396.00	+

16947
15252.30

TOTAL PRICE	$	39,651.00
LESS 10%	$	3,965.10
SUB TOTAL PRICE	**$**	**35,685.90**

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE	1	$ 50.00	$ 50.00	
2	FRONT BUMPER CLIP (SET)	1	$ 120.00	$ 120.00	30
3	FRONT BUMPER SIDE GRILLE CLIP (SET)	1	$ 50.00	$ 50.00	+
4	FRONT BUMPER BOTTOM COVER GARNISH CLIP (SET)	1	$ 50.00	$ 50.00	30
5	FRONT NUMBER PLATE GARNISH CLIP (SET)	1	$ 50.00	$ 50.00	10
6	SUPPORT PANEL UNDER COVER GARNISH CLIP (SET)	1	$ 50.00	$ 50.00	+

VEHICLE NO : **SMY2038T**
MODEL : MERCEDES A200
DATE OF ACCIDENT : 21.06.2024
TIME OF ACCIDENT : 19:15 HOURS

9	FRONT FENDER COWLING (FRONT) CLIP (SET)	1	$ 50.00	$ 50.00	+
10	FRONT FENDER COWLING (BACK) CLIP (SET)	1	$ 50.00	$ 50.00	+
11	COOLANT	1	$ 180.00	$ 180.00	+
			70 TOTAL	$ 520.00	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	$ 1,800.00	700
2	SPRAY PAINTING TO AFFECTED AREA	$ 1,600.00	600
3	TUFF COAT	$ 250.00	30
4	REFOCUS HEADLAMP BEAM	$ 80.00	x
5	WIRING CHECK	$ 650.00	30
6	REMOVE AND REFIX RADAR SENSOR AND REPROGRAMMING	$ 850.00	~~480~~ 480
7	REMOVE AND REFIX AIR COOLER	$ 120.00	60
8	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	$ 120.00	60
9	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	$ 80.00	60

VEHICLE NO : **SMY2038T**
MODEL : MERCEDES A200
DATE OF ACCIDENT : 21.06.2024
TIME OF ACCIDENT : 19:15 HOURS

10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	$	850.00	180

2200

TOTAL **$ 6,400.00**

Adrian Ng
2/S 24/06/24

TOTAL PARTS COST	: $	36,205.90	
TOTAL LABOUR COST	: $	6,400.00	
TOTAL REPAIR COST	: $	42,605.90	

08 Pays

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER,YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

total: 175230

HS : 14K

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

14K

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: