ASS. REC. BY: Kenneth | REF: LIP / CS | LIP 24110563 | knh3 | C

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Choon Boon Hock

of 820B

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: $ 79K

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMF 8214L Yr Regn: 11 / 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make: Toy Harrier (Aj) c.c 1998

Colour M-Black A/C: Insured / Std / NI / NA

Sp.Reading 106275 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTEKB3GH40J002517

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi : Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 235/55R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front		Rear	
R/Bal.	9 mm	R/Bal.	9 mm
L/Bal.	9 mm	L/Bal.	9 mm
D.O.A.	26/11/24	D.O.I.	27/11/2024

Survey held at _____

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
29/11	L/Lmp & 3250l. Calw (Red. @ 2880.55, 46%)

Date/Time, File Pass to?

1) _____

Date/Time, File Return to?

2) _____

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp ($ _____)

☐ : Interview ($ _____)

☐ Tech Invs ($ _____)

☐ Weekend ($ _____)

Survey Fee: _____

Transportation: _____ S + RS ___ SI

Photos _____

Others _____

TOTAL _____

Report Format :

Lump Sum / I.B.I: ($ _____)

CHOON HOCK MOTOR TRADING CO

Not Authorised
L/Rep $325/h
Resurvey After Paint
4 days

26 November 2024

ESTIMATE REPAIR BILL ON SMF8214L TOYOTA HARRIER AUTO

1 pce rear tailgate	Rp	$ 2,427.00
1 pce rear tailgate "HARRIER" plate	Rn	$ 85.00
1 pce rear tailgate "TURBO" plate	Rn	$ 85.00
1 pce rear bumper	Rn	$ 924.10
1 pce rear bumper reinforcement	R	$ 580.00
1 pce rear bumper lower spoiler	Cnt	$ 479.60
1 pce rear bumper sensor	Rn	$ 220.00
		$ 4,800.70
less ~~20~~ 25%		$ 960.15
		$ 3,840.55

LABOUR

Remove and refit tailgate	$ 150.00 6hl
Remove and refit rear windscreen	$ 220.00 12hl
1 set windscreen sealant	$ 80.00 40sn
Remove and refit rear bumper sensor	$ 120.00 3hl
Panel beating	$ 800.00 40hl
Spray painting	$ 800.00 40hl
Rustproofing	$ 120.00 3hl
Total amount :	$6,130.55 NETT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Mailing address : 28 Surrey Road #18-03 Singapore 307762 Reg No: 30568200L
Tel: (65) 64530778 Email: choonhockmotor@gmail.com