ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.
Tel: 6453 8686 (3 Lines) Fax: 6459 6550
Company Reg. No.: 201113667N
GST Reg. No.: 201113667N

No. : 07134

Vehicle Insured : SH9439S
Accident Date : 04-Aug-2024

Date : 06-Aug-2024

Our Ref : 024153 (FIRST) / CHAN

PAGE : 1

Not Withoin
c/Pay $5700/-
Resurvey After Paint
2 days

HUI SHOON CAR RENTAL
1 SIN MING INDUSTRIAL ESTATE
SECTOR C #01-125
Singapore 575636

ESTIMATED COST OF REPAIR FOR LEXUS ES250 SFK1125M

1 pc	Front bumper fascia	R	1,243.40
1 pc	Front o/s bumper side retaine	R	80.80
1 pc	Front o/s bumper nozzle cover	R	42.40
1 pc	Front o/s bumper nozzle motor 85207-33090	CM	965.90
1 pc	Front o/s bumper foglamp 81210-48051	R	619.20
1 pc	Front o/s bumper foglamp cover	R	229.10
1 pc	Front o/s bumper foglamp chrom	R	227.50
1 pc	O/s headlamp	CM	3,199.60
1 pc	Frt o/s bumper parking sensor 89341-33200-B1	R	638.80
1 pc	W/s glass washer tank 85355-33161	R	384.50
			7,631.20
	Less 10% :		763.12
			6,868.08
	To rewire damaged parts and refocus headlamp beam.		30.00
	To putty and spray replaced parts		500.00
	To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts		600.00
	Total :		S$ 7,998.08

Singapore Dollars Seven Thousand Nine Hundred and Ninety Eight and Cents Eight Only

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: