COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHB 4226J **DATE 23/11/2017 9;53**

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper			$ 603.60	
	Rear Bumper Clips 10 pcs			$ 22.00	
	Rear Door (LH) x repair			$ 1,351.10	
	Rear Wheel Hup-Cap (LH)			$ 150.70	
	Rocker Panel Garnish (LH) x repair				
	SUB TOTAL			**$ 2,127.40**	
	LESS 20%			$ 425.48	
	DISCOUNTED TOTAL			**$ 1,701.92**	
	Rear Bumper Rubber Mat			$ 50.00	**Nett**
	Rear Door Comfortdelgro & Apps Sticker (LH)			$ 80.00	**Nett**
				$ 130.00	
	Labour Charge				
	Panel Beating- Repair Rear Fender			$ ~~850.00~~	400
	Spray Painting Charge			$ ~~600.00~~	540
	Wiring Charge			$ ~~50.00~~	x
	Tuff Kote			$ ~~50.00~~	x
	Remove/Refix Reverse Sensor			$ ~~120.00~~	20
	Transfer of Door			$ ~~120.00~~	x
	TOTAL LABOUR			**$ 1,790.00**	
	ESTIMATE TOTAL			**$ 3,621.92**	

Kalau (LKK)
23/11/17 1400hrs
2 Days.
P/P
Before Paint photo

LKK Auto Consultants [illegible] notify the Repairer of the following [illegible]
- To resurvey the vehicle after spray painting
- To display damaged parts and bring for resurvey
- Parts prices are subject to confirmation
- Third party surveyors on a [illegible] basis
- Any illegal modification(s) is [illegible]
- Supplementary item(s) must be [illegible] and is subject to final approval from Insurance Company

Acknowledged by Repairer

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.