| | EDIT | SR NO | NAME | ACTION | AMOUNT | COMMENT | REMOVE |
|---|---|---|---|---|---|---|---|
| ☐ | ✎ | 20 | TAILLAMP CLIP RH | Reviewing | 5 | NECESSARY | 🗑 |
| ☐ | ✎ | 21 | TAILLAMP CLIP LH | Reviewing | 5 | NECESSARY | 🗑 |
| ☐ | ✎ | 22 | REAR WINDSCREEN SEALANT | Reviewing | 0 | NOT NECESSARY | 🗑 |
| ☐ | ✎ | 23 | WINDSCREEN MOULDING | Reviewing | 0 | NOT NECESSARY | 🗑 |
| ☐ | ✎ | 24 | REAR WINDSCREEN INNER SPONGE SEAL | Reviewing | 0 | NOT NECESSARY | 🗑 |
| ☐ | ✎ | 25 | SPARE TYRE RIM (ROUE 7J 16H 2547) | Reviewing | 0 | SERVICEABLE | 🗑 |
| ☐ | ✎ | 26 | SPARE TYRE | Reviewing | 0 | SERVICEABLE | 🗑 |

| | EDIT | SR NO | NAME | ACTION | AMOUNT | COMMENT | REMOVE |
|---|---|---|---|---|---|---|---|
| | | 5 | SET BUMPER BRACKET SIDE CLIP RH RR | Reviewing | 0 | NOT NECESSARY | |
| | | 6 | SET BUMPER RETAINER RH CLIP RR | Reviewing | 0 | NOT NECESSARY | |
| | | 7 | SET BUMPER BRACKET SIDE CLIP LH RR | Reviewing | 0 | NOT NECESSARY | |
| | | 8 | SET BUMPER RETAINER CLIP LH RR | Reviewing | 0 | NOT NECESSARY | |
| | | 9 | SET BUMPER LOWER REAR RIVET | Reviewing | 0 | NOT NECESSARY | |
| | | 10 | SET BUMPER LOWER REAR CLIP | Reviewing | 66 | NECESSARY | |
| | | 11 | EXHAUST MOUNTING REAR | Reviewing | 0 | SERVICEABLE | |

| | EDIT | SR NO | REPAIR/REPLACE (LABOUR) | PART NAME | LABOUR R&R | LABOUR REPAIR | PAINT | ACTION (LABOUR) | COMMENT |
|---|---|---|---|---|---|---|---|---|---|
| | | 13 | | TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST. | 0 | 0 | 0 | Reviewing | |
| | | 14 | | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT. | 0 | 0 | 0 | Reviewing | |

| | EDIT | SR NO | QUANTITY | MATERIAL | SIDE | PART NAME | PART NUMBER | REPAIR/REPLACE (PARTS) | CONDITION | LIST PRICE | DEPRJ BTTR% | DISCOUNT% | SALVAGE% | PART PRICE(NET) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | 36 | 1 | | | TAILLAMP RH (DISC 10%) | | | Cracked | 497.3 | | 0 | | 497.3 |
| | | 37 | 1 | | | TAILLAMP PANEL RH | | | Repair | 0 | | 0 | | 0 |
| | | 38 | 1 | | | TAILLAMP LH (DISC 10%) | | | Cracked | 497.3 | | 0 | | 497.3 |
| | | 39 | 1 | | | TAILLAMP PANEL LH | | | Repair | 0 | | 0 | | 0 |
| | | 40 | 1 | | | OUTER PANEL REAR (END PANEL) (DISC 10%) | | | Bent | 1324.59 | | 0 | | 1324.59 |
| | | 41 | 1 | | | OUTER PANEL REAR (END PANEL) TRIM (DISC 10%) | | | Dented | 364.1 | | 0 | | 364.1 |
| | | 42 | 1 | | | SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL) (DISC 10%) | | | Bent | 1970.89 | | 0 | | 1970.89 |
| | | 43 | 1 | | | SPARE WHEEL PANEL TRIM } | | | Serviceable | 0 | | 0 | | 0 |
| | | 44 | 1 | | | EXHAUST REAR } | | | Serviceable | 0 | | 0 | | 0 |
| | | 45 | 1 | | | EXHAUST CAP REAR (DISC 10%) | | | Missing | 207.44 | | 0 | | 207.44 |

Labour

Add Approve Deny

| | EDIT | SR NO | REPAIR/REPLACE (LABOUR) | PART NAME | LABOUR R&R | LABOUR REPAIR | PAINT | ACTION (LABOUR) | COMMENT |
|---|---|---|---|---|---|---|---|---|---|
| | | 1 | | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION. | 1100 | 0 | 0 | Reviewing | |

| | EDIT | SR NO | QUANTITY | MATERIAL | SIDE | PART NAME | PART NUMBER | REPAIR/REPLACE (PARTS) | CONDITION | LIST PRICE | DEPR./BTTR% | DISCOUNT% | SALVAGE% | PART PRICE(NET) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | 9 | 1 | | | BUMPER REFLECTOR LH (DISC 10%) | | | Cracked | 39.25 | | 0 | | 39.25 |
| | | 10 | 1 | | | BUMPER BEAM REAR (DISC 10%) | | | Bent | 699.77 | | 0 | | 699.77 |
| | | 11 | 1 | | | BUMPER BEAM BRACKET LH REAR (DISC 10%) | | | Bent | 203.36 | | 0 | | 203.36 |
| | | 12 | 1 | | | BUMPER BEAM BRACKET RH REAR (DISC 10%) | | | Bent | 203.36 | | 0 | | 203.36 |
| | | 13 | 1 | | | BOOT REAR (DISC 10%) | | | Bent | 2585.41 | | 0 | | 2585.41 |
| | | 14 | 1 | | | BOOT FINISHER | | | Serviceable | 0 | | 0 | | 0 |
| | | 15 | 1 | | | BOOT WEATHERSTRIP (DISC 10%) | | | Cut | 290.75 | | 0 | | 290.75 |
| | | 16 | 1 | | | BOOT REFLECTOR LAMP LH (DISC 10%) | | | Dented | 444.02 | | 0 | | 444.02 |
| | | 17 | 1 | | | BOOT REFLECTOR LAMP RH (DISC 10%) | | | Dented | 444.02 | | 0 | | 444.02 |
| | | 18 | 1 | | | BOOT BADGE 'RENAULT' (DISC 10%) | | | Necessary | 202.82 | | 0 | | 202.82 |
| | | 19 | 1 | | | BOOT BADGE (DISC 10%) | | | Necessary | 202.82 | | 0 | | 202.82 |
| | | 20 | 1 | | | BOOT STRUT LH | | | Serviceable | 0 | | 0 | | 0 |

## Detailed Assessment

Inspection Date *

12/19/2017

Total Loss

**Yes** **No**

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

## Condition of Vehicle at time of survey

General condition

Good

Steering (Serviceable)

Yes **No**

Footbrake (Serviceable)

Yes **No**

Handbrake (Serviceable)

Yes **No**

Engine Modification

**Yes** No

Pre-accident condition

Good

## Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

215/60R16

Rear Tyre Size

215/60R16

| | |
|---|---|
| FNOL INFORMATI... | BLK 222 LOR TOA PAYOH, 310222, Singapore |
| POST SURVEY INF... | |
| CATEGORY | Address type |
| FNOL INFORMATI... | Personal Correspondence |
| POST SURVEY INF... | |
| CATEGORY | Gender |
| FNOL INFORMATI... | Male |
| POST SURVEY INF... | |
| CATEGORY | Marital status |
| FNOL INFORMATI... | Unknown |
| POST SURVEY INF... | |
| CATEGORY | Identification # |
| FNOL INFORMATI... | S0376564D |

| | |
|---|---|
| CATEGORY | Make |
| POLICY INFORMAT... | HYUNDAI |
| ASSESSMENT INFO... | RENAULT |

| | |
|---|---|
| CATEGORY | Model |
| POLICY INFORMAT... | AVANTE 1.6 |
| ASSESSMENT INFO... | LATITUDE 2.0L DCI AUTO D/AB 4DR |

| | |
|---|---|
| CATEGORY | Type |
| POLICY INFORMAT... | Rented / hired |
| ASSESSMENT INFO... | |

| | |
|---|---|
| CATEGORY | Type of Paint |
| POLICY INFORMAT... | |
| ASSESSMENT INFO... | |

| | |
|---|---|
| CATEGORY | Chassis No |
| POLICY INFORMAT... | KMHDU41BR7U214146 |

| | |
|---|---|
| CATEGORY | Date of Birth |
| FNOL INFORMATI... | March 12, 1949 |
| POST SURVEY INF... | mm/dd/yyyy |

| | |
|---|---|
| CATEGORY | Age |
| FNOL INFORMATI... | 69 |
| POST SURVEY INF... | |

| | |
|---|---|
| CATEGORY | Occupation |
| FNOL INFORMATI... | Unknown |
| POST SURVEY INF... | |

| | |
|---|---|
| CATEGORY | Education Qualification |
| FNOL INFORMATI... | Other |
| POST SURVEY INF... | |

| | |
|---|---|
| CATEGORY | Driving Experience |

Pending verification - Direct Settlement

## Claim Handler

TAY Ernest
6568804835
ernest.tay@axa.com.sg

Additional Instructions

Messages Invoices History Documents

Assessment Metrics Notes Add

| CREATED USER | VERSION DATE | ESTIMATED AMOUNT | APPROVED AMOUNT | STATUS | SHARE | CLONE |
|---|---|---|---|---|---|---|
| TAY Ernest | 2/21/18 10:02 AM | 15653.12 | 15653.12 | Open | Share | Clone |

| NAME | TYPE | SUB-TYPE | AUTHOR | DATE UPLOADED |
|---|---|---|---|---|
| TP - DOCU TRANSFER FROM C0463903.msg | Letters and Correspondence | Internal | NIKAM Santosh Pandurang | December 27, 2017 |
| GA286324-Policy.pdf | Forms / Claim Documents | Policy Schedule / Covernote / Certificate of insurance | ONG Birdie | December 26, 2017 |
| GA286324-Certificate.pdf | Forms / Claim Documents | Policy Schedule / Covernote / Certificate of insurance | ONG Birdie | December 26, 2017 |
| TP SHC5845K GIA.pdf | Reports & Statement | GIA Report | ONG Birdie | December 26, 2017 |
| OD SGZ6993A-A GIA.PDF | Reports & Statement | GIA Report | SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | December 26, 2017 |

Pending verification - Direct Settlement

Claim Handler

TAY Ernest
6568804835
ernest.tay@axa.com.sg

Additional Instructions

Messages Invoices History Documents

Assessment Metrics Notes

Document Type

Document SubType

Upload Documents

| NAME | TYPE | SUB-TYPE | AUTHOR | DATE UPLOADED |
|---|---|---|---|---|
| LKK Resurvey Photo.pdf | Reports & Statement | Others | LKK AUTO CONSULTANTS PTE LTD (TP) | June 18, 2018 |
| LKK Survey Photo.pdf | Forms / Claim Documents | Others | LKK AUTO CONSULTANTS PTE LTD (TP) | May 31, 2018 |
| Immediate Advice with Mandate.pdf | Forms / Claim Documents | Others | LKK AUTO CONSULTANTS PTE LTD (TP) | May 31, 2018 |