COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 6778H **DATE 8/1/2018 14:33**

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid Dented			$ 1,349.50	
	Boot Lid Rubber deformed			$ 110.90	
	Boot Lid Lock Upper Bt			$ 132.10	
	Boot Lid Lock Lower Bt			$ 30.30	
	Boot Lid Sonata Plate New			$ 43.60	
	Boot Lid Hyundai Plate New			$ 24.20	
	Boot Lid 'H' Emblem New			$ 26.10	
	Boot Lid CRDI Plate New			$ 22.70	
	Rear Bumper Dented			$ 578.40	
	Rear Bumper Reinforcement ?			$ 483.30	?
	Rear Bumper Clip New			$ 22.00	
	Rear Bumper Sponge ?			$ 137.40	?
	Rear Bumper Under Cover deformed			$ 185.80	
	Rear Bumper Protector (LH/RH) Bt		$ 38.00	$ 76.00	
	Rear Panel Dented			$ 391.80	
	Rear Panel Garnish deformed			$ 95.80	
	Spare Tyre Holder New			$ 27.60	X
	Spare Tyre Panel New			$ 863.00	X
	Spare Tyre Panel Cushion New			$ 200.30	X
	Rear Towing Hook New			$ 135.30	X
	SUB TOTAL			**$ 4,936.10**	
	LESS 20%			$ 987.22	
	DISCOUNTED TOTAL			**$ 3,948.88**	
	Boot Lid Comfort Logo & Tel No. Sticker New			$ 30.00	Nett
	Boot Lid Advertisement Logo New			$ 100.00	Nett
	Rear No.Plate Svc			$ 25.00	Nett X
	Rear Bumper Reverse Sensor Dam			$ 135.70	Nett
	Rear Bumper Advertisement Logo New			$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH) New		$ 100.00	$ 200.00	Nett
				$ 540.70	
	Labour Charge 08/01/2018				
	Panel Beating			$ ~~1,600.00~~	700/-
	Spray Painting Charge			$ ~~800.00~~	600/-
	Wiring Charge			$ ~~50.00~~	30/-
	Tuff Kote			$ ~~50.00~~	40/-
	Remove/Refix Reverse Sensor			$ ~~120.00~~	40/-
	TOTAL LABOUR			**$ 2,620.00**	
	ESTIMATE TOTAL			**$ 7,109.58**	

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications are allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

LKK Auto
Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.