Surveyor Rasul | REF: III | 8153H

ASSIGNMENT

From: | Date: 30/1/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKL 3239R

at Workshop m/s Carcrafters

of 48 Toh Guan Road East #05-155

Insured:

Policy No.

Claims No.

Sum Insured: | Excess:

(Client's Record)

Make of Veh:

(Policy Condition) 11am owner waiting

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: | Consistent? : Yes or No

GIA / PR Seen: | Consistent? : Yes or No

Est. Repairs: days | Res.: Yes or No

Lum Sum: % | 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: | Person Contacted:

Veh No: SKL 3239R | Yr Regn: 2013 / OG

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Audi A5 2-0 | c.c 1984

Colour Grey | A/C: Insured / Std / NI / NA

Sp.Reading 42717 | T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WAUZZZ8T20A064716

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/40ZR18

R: - -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	15/01/18	D.O.I.	30/01/18

Survey held at Carcrafters

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or N/S FRT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
30/01/18	finalised with ryhp carcrafters fairzal at amnt of $1,900.00/ 3 days Lumpsum

Date/Time. File Pass to? 1) | Date/Time. File Return to? 2)

☐ : Preli. Report

☐ : Final Report

Report Format :

Lump Sum / I.B.I: ($)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp ($) ☐ Interview ($) ☐ Tech. Invs ($) ☐ Weekend ($)

Survey Fee:

Transportation: ___S + RS ___SI

Photos

Others

TOTAL