Rame | REF: III | 2091F

ASSIGNMENT

From: Date: 01.02.2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBM 3456G

at Workshop / s: Southern Motor

of: Blk 1006 Bukit Merah Lane 2 #01-10

Insured:

Policy No.:

Claims No.:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

after lunch.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: FBM 3456G Regn: 2017 88P

Type: M.Car / Coupe / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: YAMAHA CZD300A cc: 292

Colour: BLACK A/C: Insured / Std / NI / NA

Sp.Reading: 7869 T Radio: Insured / Std / NI / NA

Eng.No:

C.No.: MH3SH05L00001539U

Gen. Cond. Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/70-15

R: 140/70-14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	3 mm	R/Bal.	3 mm
L/Bal.	mm	L/Bal.	mm

D.O.A. 18/01/18 D.O.I. 01/02/18

Survey held at: SOUTHERN MOTOR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Date/Time File Pass to: ☐ : Preli. Report

☐ : Final Report

Date/Time File Return to:

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Stamp $ ☐ Other $ ☐ Other $ ☐ Other $

Report Format:

Lump Sum / LB / S

Survey Fee

Transportation

Photo

Other