Menu

-

3

REAR BUMPER REVERSE SENSOR

Reviewing

0

NOT NECESSARY

4

REAR BUMPER RUBBER MAT

Reviewing

50

NECESSARY

5

REAR BUMPER ADVERTISEMENT LOGO

Reviewing

Menu

Menu

Reviewing

4

TUFF KOTE.

0

0

0

Reviewing

5

REMOVE / REFIX REVERSE SENSOR.

0

0

Menu

1

REAR PANEL LOWER PANEL

Repair

0

20

0

Reviewing

Labour

Add Approve Deny

1

PANEL BEATING.

400

Menu

REAR BUMPER UNDER COVER

Cut

225

20

180

Reviewing

17

1

REAR PANEL

Repair

0

Menu

Serviceable

0

20

0

Reviewing

14

10

REAR BUMPER CLIPS

Necessary

2.2

20

Menu

603.6

20

482.88

Reviewing

11

1

REAR BUMPER REINFORCEMENT

Serviceable

0

20

0

Reviewing

Menu

0

Reviewing

8

1

BOOTLID I40 EMBLEM

Necessary

41

20

32.8

Reviewing

Menu

Reviewing

5

1

BOOT LID 'H' EMBLEM

Necessary

27.2

20

21.76

Reviewing

6

Menu

2

1

BOOT LID RUBBER

Serviceable

0

20

0

Reviewing

3

1

Menu

Menu

Handbrake (Serviceable)

Engine Modification

Pre-accident condition

Excellent

Tyre Condition

Age of Tyres

Front Tyre Size

Front left side

Front right side

Spare wheel

Rear Tyre Size

Rear left side

Rear right side

Menu

Driver License #

License Type

1

License Issue Date

mm/dd/yyyy

License Expiration Date

mm/dd/yyyy

Address

Singapore

Address type

Business Correspondence

Business Correspondence

Menu

Type

Listed on policy

Type of Paint

Chassis No

Engine No

Engine Capacity

Sum Insured

Menu

Menu

Model
I40

Service Address

9 KEW WALK, , , 466004

Primary Contact/Insured

LEONG SIEW WAH
9 KEW WALK, 466004, Singapore

JESSICA.LEONG@ST.COM

Claim Handler

LOH Cynthia
6568804843
cynthia.loh@axa.com.sg

Additional Instructions
(1)TP-CDGE: ARC (2) ID-H2R

Messages Invoices History Documents Assessment Metrics Notes

Add

LOH Cynthia

2/2/18 10:16 AM

$1,987.84

$1,987.84

Open

Share

Clone

Menu

Other

Other

DHIWAR Namrata

January 29, 2018

Menu

March 16, 2018

LOD.pdf

Forms / Claim Documents

Others

LKK AUTO CONSULTANTS PTE LTD (TP)

March 16, 2018

LKK Survey Photo.pdf

Reports & Statement

Others

LKK AUTO CONSULTANTS PTE LTD (TP)

March 9, 2018

LKK Resurvey Photo.pdf

Reports & Statement

Others

LKK AUTO CONSULTANTS PTE LTD (TP)

March 9, 2018

TP ESTIMATE - MARKED.pdf

Reports & Statement

Estimate / Quotation

LKK AUTO CONSULTANTS PTE LTD (TP)

Menu

Model
I40

Service Address

9 KEW WALK, , , 466004

Primary Contact/Insured

LEONG SIEW WAH
9 KEW WALK, 466004, Singapore

JESSICA.LEONG@ST.COM

Claim Handler

LOH Cynthia
6568804843
cynthia.loh@axa.com.sg

Additional Instructions
(1)TP-CDGE: ARC (2) ID-H2R

Messages Invoices History Documents Assessment Metrics Notes

Document Type	Document SubType

Upload Documents

LTA SEARCH.pdf

Forms / Claim Documents

Others

LKK AUTO CONSULTANTS PTE LTD (TP)

March 16, 2018

RENTAL RECEIPT.pdf