COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

LKK/Kalvin

VEHICLE NO : SHC 1109D

DATE 5/2/2018 14:45

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Bonnet			$ 1,151.80	
	Bonnet Moulding			$ 120.90	
	Bonnet Lock			$ 48.80	
	Radiator Grille			$ 282.10	
	Radiator Grille U Moulding			$ 108.90	
	Front Bumper Cover			$ 538.80	
	Front Bumper Sponge ?			$ 136.30	
	Front Bumper Reinforcement ?			$ 504.10	
	Front Bumper Bracket Top (LH/RH) ?		$ 22.40	$ 44.80	
	Front Bumper Protector (LH/RH) ?		$ 29.20	$ 58.40	
	Front Bumper Bracket (LH/RH) ?		$ 20.10	$ 40.20	
	Headlamp (LH)			$ 797.90	
	SUB TOTAL			**$ 3,833.00**	
	LESS 20%			$ 766.60	
	DISCOUNTED TOTAL			**$ 3,066.40**	
	Front Number Plate			$ 25.00	**Nett**
	Front No Plate Trim Cover			$ 30.00	**Nett**
				$ 55.00	
	Labour Charge				
	Panel Beating			$ ~~380.00~~ 200	
	Spray Painting Charge			$ ~~200.00~~ ~~400~~ 360	
	TOTAL LABOUR			**$ 580.00**	
	ESTIMATE TOTAL			**$ 3,701.40**	

Kalvin/LKK
5/2/18 1530 hrs
2 days
4s
After Repair pkto.

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.