4

陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SFQ6034C
Date of Accident : 19 February 2018

Not Agreed
NU
d/s $1,600
4 day
27/2/18
take photo after repair

Messrs Drew Ameroid (S) Pte Ltd

Date : 26 February 2018

Estimate To Repair FBF6794Y - Yamaha T135
Chassis No : 5YP012945

S/No	Quantity	Description	Amount	
		LIST ITEMS		
01	1 pc	rear wheel rim R	$ 380.00	X
02	1 pc	rear wheel mudguard R	$ 180.00	X
03	1 pc	rear exhaust pipe NS	$ 450.00	/
04	1 pc	rear exhaust pipe heat shield Bnd	$ 120.00	/
05	1 pc	chain guard RR	$ 150.00	X
06	1 pc	main park stand R	$ 250.00	X
07	1 pc	rear swing arm R	$ 460.00	X
08	1 pc	rider's foot rest pedal Bnd	$ 220.00	/
09	1 pc	n/s rider's foot rest pedal rubber Tom	$ 25.00	/
10	1 pc	foot gear selector pedal Bnd	$ 100.00	/
11	1 pc	n/s side fairing CNe	$ 380.00	/
12	1 pc	o/s side fairing R	$ 380.00	X
13	1 pc	~~front fairing~~ 1U unit CU7	$ 200.00	165S.N
14	1 pc	handlebar Bnd 165	$ 250.00	/
15	1 pc	n/s handlebar balancer SCR	$ 20.00	/
16	1 pc	n/s front wing mirror CU7	$ 80.00	/
17	1 pc	speedo-meter fairing RR	$ 150.00	X
18	1 pc	front license plate sticker NU	$ 30.00	105.N
			$ 3,825.00	
		Less 10 %	$ 382.50	1560
			$ 3,442.50	1404
		SPECIAL NETT ITEMS		
19	1 pc	rear luggage box with carrier CU7	$ 400.00	200S.N
20	1 pc	rear licence plate R	$ 30.00	X
			$ 430.00	
		LABOUR & MISC. CHARGES		
01		Panel beating and spray painting 250	$ 400.00	250
			$ 400.00	
		Total	$ 4,272.50	

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: