Surveyor: Tan

REF: EQZ

# ASSIGNMENT

From: Date: 01.03.2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFV 833B

at Workshop m/s Li Sheng

of Blk K Pandan Loop #01-18

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: Winsun

(Policy Condition) 3pm owner waiting

Remark: The veh had commenced its repair at the time of inspection.

| N/S | O/S |
|---|---|
| | |

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SFV833B Yr Regn: 2017 Oct.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Audi RS6 c.c 3993.

Colour Blue. A/C: Insured / Std / NI / NA

Sp.Reading 7371 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WUAZZZ4G0HN900326

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 285/30R21

R: 285/30R21

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

| Front | | Rear | |
|---|---|---|---|
| R/Bal. | 6 mm | R/Bal. | 6 mm |
| L/Bal. | 6 mm | L/Bal. | 6 mm |
| D.O.A. | | D.O.I. | 1/3/18 @ 3pm. |

Survey held at Li Sheng

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or o/s wing mirror

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|---|---|
| | |

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp ($ ) ___S + RS___SI

☐ : Interview ($ ) Photos

☐ : Tech. Invs ($ ) Others

☐ : Weekend ($ )

Report Format :

Lump Sum / I.B.I: ($ )

TOTAL