TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE   : ACCIDENT/BODY REPAIRS
WORKSHOP   : LENG KEE
CONTACT NO   : 67038511
REFERENCE   : 051/IC/TCAC/CCR/2018
DATE   : 05-MAR-2018

AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME   : GIOVANNI RINALDI
ADDRESS   : 79 FARRER DRIVE
                 #03-02
                 S(259283)
TELEPHONE NO   : 97564612/97478748

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO   : 2100470849-01000
VEHICLE NO   : SJW4142H
MODEL CODE   : FRLARBZJ11UEA--A--
MODEL/YEAR   : NISSAN QASHQAI 1.2
ENGINE NO   : HRA2284586A
CHASSIS NO   : SJNFEAJ11U1682485
MILEAGE   : 15974 KM
DATE IN   : 05/03/2018
LIABILITY   :   0.00
EXCESS CLAUSE :   0.00
ESTIMATE BY   : SHAWN CHUA CHU RONG
ACCIDENT DATE : 03/03/2018

Tanjin 97495749
'WP'
8/3/18 @ 130pm
3 days.
SunC Mkanto.com
Resurvey before paint

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJW4142H

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	CONI	PERFORM VEHICLE ELECTRONIC SYSTEM DIAGNOSIS, INTERROGATION & REPROGRAM MODULE WITH CONSULT	240.00	✓
2	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	✗
3	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	✓
4	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	✗
5	WHI	CHECK & INSPECT WIRE HARNESS FOR DAMAGE & OPEN/ SHORT CIRCUIT, REPAIR WHEN NECESSARY	240.00	✗
6	ZZ/001	RENEW REAR BUMPER,LEFT TAIL LAMP,REAR UPPER PANEL, ENERGY ABSORBER,REINFORCEMENT,WEATHERSTRIP,REAR		250.
7	ZZ/002	LEFT FENDER & TRIM ETC PANELS & REPAIR	1500.00	
8	ZZ/003	REMOVE & INSTALL SEATS,CARPETING & HEADLINER TO FACILIATE REPAIR	120.00	✗
9	ZZ/004	RENEW LEFT QUARTER GLASS TO FACILITATE REPAIR	150.00	✗
10	ZZ/005	RESPRAY REAR BUMPER IN 2 COLORS,REAR UPPER PANEL, LEFT FENDER ETC	1000.00	300
11	ZZ/006	QC, RETUNE & CONSULT CHECK		
12	ZZ/007	COMPLIMENTARY WASH & VACUUM		

```
                                                      ----------
                    TOTAL LABOUR CHARGES               3525.00
                                                      ----------
```

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJW4142H

			DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	LEFT QUARTER GLASS	83313-4EA0A			380.00	✘
2	LEFT FENDER TRIM	93829-4EA0A	483.00			✘
3	WEATHERSTRIP	90830-4EA0B	158.70			✗
4	LEFT REINFORCEMENT STAY	H5211-4EAMA	126.00			?
5	REINFORCEMENT	H5030-4EAMA	619.20			?
6	ENERGY ABSORBER	85090-4EA0B	126.40			?
7	LEFT BUMPER BRACKET	85221-4EA0A	35.90			nel ✓
8	LEFT BUMPER RETAINER	79185-4EA0A	23.80			nel ✓
9	CLIP ($1.20 EA X4)	01553-05933	4.80			nel ✓
10	REAR BUMPER	85022-4EA0H	717.00			de ✓
11	REAR UPPER PANEL	G9110-4EAMA	482.60			Ry
12	LEFT PROTECTOR	76749-4EA0A	186.40			✗
13	REAR LEFT FENDER	G8101-4EAMA	1169.40			✗
14	LEFT REFLECTOR	26565-JJ90A	55.00			?
15	LEFT TAIL LAMP (FENDER)	26555-4EA0A	323.70			cva ✓

		NETT	LIST	S/NETT
SUB TOTAL		4511.90	0.00	380.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		902.38	0.00	0.00
GRAND TOTAL		3609.52	0.00	380.00
OVERALL TOTAL		3989.52		

LEGEND: REMARKS(OK) = APPROVED,   REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SJW4142H

TOTAL LABOUR CHARGES   3525.00
TOTAL SPARE PARTS CHARGES   3989.52

GRAND TOTAL   7514.52 *
                              ----

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME   :
SURVEYED DATE   :
AUTHORIZED DATE   :
EXCESS CLAUSE   :   0.00
LIABILITY   :   0.00
REMARKS   :

PLS NOTE : This estimate is based on visual inspection of the
           affected vehicle. Should we require further labour
           charges & spare parts in the process of repairs, we
           shall inform you accordingly.