PEGASUS
ENGINEERING & TRADING PTE LTD

GST / ROC Company No : 201101753C

Third Party Insurer : INDIA
Insured's Veh No : SHD6762D
Date of accident : 11/03/2018

Not Authorised
Mk WP
14/3/18
Take photo before party.
4 day.

Grab Rentals Pte Ltd
18 Sin Ming Lane
#01-08 Midview City
Singapore 573960

Quotation No : AR/QO18/03-1012
Quotation Date : 13/03/2018

Estimate To Repair TOYOTA PRIUS
Vehicle No : SLT3448A
Chassis No : JTDKB3FU803574861

S/NO	QUANTITY	DESCRIPTION	AMOUNT
		SPARE PARTS	
1	1 PC	LH SIDE MIRROR NW 1283.90	$1,662.20
2	1 PC	LH SIDE MIRROR COVER BNW 90.40	$95.40
3	1 PC	FRT LH DOOR 20/Sep 1249.60	$1,349.00
4	3 PC	FRT LH DOOR TOP STICKER @$105 NEW	$315.00
5	1 PC	FRT LH DOOT OUTER MOULDING CUT	$98.60
6	1 PC	FRT LH FENDER "HYBRID" PLATE NEW	$81.00
			$3,601.20
		LESS 25%	$900.30
			$2,700.90
		LABOUR & MISC. CHARGES	
1		WIRE CHECKING 20	$30.00
2		TRANSFER DOOR COMPONENT FROM OLD TO NEW 60	$120.00
3		LABOUR CHARGE 280	$500.00
4		SPRAY PAINTING 480	$500.00
		Total	$1,150.00
		Sub Total	**$3,850.90**
		GST (7.00%)	**$269.56**
		Total	**$4,120.46**

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Please conduct the survey at
Pegasus Engineering @ SME c/o **1 Kaki Bukit Ave 6 Autobay@Kaki Bukit #02-15/16/17/18, Singapore 417883**