新福德車廠私人有限公司
NEW HOCK TECK MOTOR PTE. LTD.
1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883
Email: admin@nhtmotor.com Website: www.nhtmotor.com
Tel: 6747 9241 Fax: 6741 7276
UEN: 201718370K

PHYO WAI SOE
Blk 1 Kaki Bukit Ave 6
 # 01-43
Singapore 417883

TP Mindef
Xiaotong

13/03/2018

JMYSTCS3A5U022527

Accident date: 13/03/2018
Estimated repair cost for vehicle no: SJM4118G MITSUBISHI LANCER 1.6 A '09

S/n	Qty	Items	U/price	Amount
1	1	Front Bonnet Dented		$671.00
2	2	Front Bonnet Hinge	$84.00	$168.00
3	1	Front Bonnet Lock		$108.00
4	1	Front Bonnet Inner Rubber		$101.00
5	2	Front Head Lamp RH cracked	$652.00	~~$1,304.00~~ $572
6	2	Front Head Lamp Lower Clip	$8.00	~~$16.00~~ 8
7	1	Front R/H Fender Distorted		~~$573.00~~ 456
8	1	Front R/H Fender Cowling Torn		$128.00
9	10	Front R/H Fender Cowling Clip	$6.50	~~$65.00~~ 20
10	1	Front R/H Fender Signal Lamp		$79.00
11	1	Front Bumper Distorted		$738.00
12	10	Front Bumper Clip	$6.50	~~$65.00~~ 30
13	2	Front Bumper Side Retainer RH Bkd	$38.00	~~$76.00~~ 38
14	12	Front Bumper Side Retainer Rivet	$3.50	~~$42.00~~ 20
15	1	Front Bumper Grille Cracked		$146.00
16	2	Front Bumper Grille Side Cover RH Cracked	$91.00	~~$182.00~~ 91
17	8	Front Bumper Grille Clip	$6.50	~~$52.00~~ 20
18	1	Front Bumper Emblem Logo		$38.00
19	1	Front Bumper Number Plate Bent		$50.00
20	1	Front Bumper Number Plate Garnish Dented		$58.00
21	1	Front Bumper Reinforcement Distorted		$186.00
22	2	Front Bumper Centre Cover RH Dented	$88.00	~~$176.00~~ 88
23	1	Front Bumper Centre Inner Garnish Dented		$132.00
24	1	Front Bumper Lower Spoiler (Special Nett) Dented		$680.00
25	1	Front R/H Bumper Fog Lamp Cracked		$377.00
26	1	Front R/H Bumper Fog Lamp Cover Distorted		$65.00
27	1	Front Support Panel Buckled		$893.00
28	1	Front Wiper Tank Dented		$104.00

29	1	Front Air-Con Condenser Bent	$937.00
30	1	Front Air-Con Section Pipe Straight	$255.00
31	1	Front Air-Con Discharge Pipe	$246.00
32	1	Front Radiator Bent	~~$1,161.00~~ 890.
33	1	Front R/H Rim Cut	~~$650.00~~ 400(SW)
34	1	Front R/H Tyre Use a/w	$350.00
35	1	Front R/H Lower Arm Bent	$292.00
36	1	Front R/H Knuckle Arm Bent	$358.00
37	1	Front R/H Knuckle Arm Bearing Use	$259.00
38	1	Front R/H Shock Absorber Bent	$387.00
39	1	Front R/H Drive Shaft Straight	$1,386.00
40	1	Front Steering Rack	$1,833.00

8849
7864.10

Subtotal :- **$15,387.00**

S.W: 400

Labour charges

To remove & refit air-con condenser, radiator, fan motor & top up gas	~~$380.00~~ 120
To remove & refit front R/H undercarriage	~~$380.00~~ 220
To remove & refit front R/H drive shaft & steering rack	$450.00
To check wheel alignment	~~$150.00~~ 80
To check wiring	~~$100.00~~ 30
Towing fee	~~$100.00~~ 50
Tuff kote	~~$150.00~~ 40
Panel Beating	~~$1,800.00~~ 1000
Spray painting	~~$1,400.00~~ 1100

2640.

Adrian Lj
13/03/18.
06 Rmp.

Subtotal :- **$4,910.00**

Total:- **$20,297.00**

total: 14804.10
L/s: 8.8K
06 Rmp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party surveys on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

8.81c