Assessment Details

General & Workshop Details | Vehicle & Driver Details | Vehicle Condition | Taxes & Ratio | Parts & Labour | Miscellaneous | Summary

General Details

Involving
1 2011 VOLKSWAGEN TOURAN 1.4 TSI SPORT (SKD6704L)

Date of Loss
9 March 2018

Time of Loss
19.30

Loss Description
SKD6704L (INSD) C/W SDQ2219L (TP)

Comment

Workshop Details

Total Rebate Amount
37606

Nett Loss Amount
$11,394.00

Assigned Workshop
LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *
05/08/2018

Days of work completion *
55

Assessment Details

Vehicle & Driver Details

Vehicle Registration#
SKD6704L

Registration State
SINGAPORE

Mileage
131577

CATEGORY	Manufacturing Year
POLICY INFORMAT...	2011
ASSESSMENT INFO...	2011

Purchase Date
dd/mm/yyyy

Registration Date *
27/12/2011

Age of Vehicle
6

Driver Details

CATEGORY	Driver Name
FNOL INFORMATI...	WEE ENG PENG
POST SURVEY INF...	

CATEGORY	Make
POLICY INFORMAT...	VOLKSWAGEN
ASSESSMENT INFO...	VOLKSWAGEN

CATEGORY	Model
POLICY INFORMAT...	TOURAN 1.4 TSI SPORT
ASSESSMENT INFO...	TOURAN SPORT 1.4 TSI AT 1T34C4

CATEGORY	Type
POLICY INFORMAT...	
ASSESSMENT INFO...	

CATEGORY	Type of Paint
POLICY INFORMAT...	
ASSESSMENT INFO...	

CATEGORY	Chassis No
POLICY INFORMAT...	WVGZZZ1TZCW054450

CATEGORY	Date of Birth
FNOL INFORMATI...	17 June 1976
POST SURVEY INF...	dd/mm/yyyy

CATEGORY	Age
FNOL INFORMATI...	42
POST SURVEY INF...	

CATEGORY	Occupation
FNOL INFORMATI...	Unknown
POST SURVEY INF...	

CATEGORY	Education Qualification
FNOL INFORMATI...	Other
POST SURVEY INF...	

CATEGORY	Driving Experience

ASSESSMENT INFO... WVGZZZ1TZCW054450

CATEGORY Engine No

POLICY INFORMAT... CAV366963

ASSESSMENT INFO... CAV366963

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 1390

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO... 49000

FNOL INFORMATI... 13

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI... 1 January 2005

POST SURVEY INF... dd/mm/yyyy

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY Address

FNOL INFORMATI...	blk 299 bukit batok st 22 #12-12 singapore 650299, Singapore
POST SURVEY INF...	

CATEGORY	Address type
FNOL INFORMATI...	Personal Correspondence
POST SURVEY INF...	

CATEGORY	Gender
FNOL INFORMATI...	Male
POST SURVEY INF...	

CATEGORY	Marital status
FNOL INFORMATI...	Unknown
POST SURVEY INF...	

CATEGORY	Identification #
FNOL INFORMATI...	S7617613B

POST SURVEY INF...

Assessment Details

Detailed Assessment

Inspection Date *

20/03/2018

Total Loss

Yes No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good

Steering (Serviceable)

Yes **No**

Footbrake (Serviceable)

Yes **No**

Handbrake (Serviceable)

Yes **No**

Engine Modification

Yes No

Pre-accident condition

Good

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

205/55R16

Rear Tyre Size

205/55R16

Front left side

PIRELLI6mm

Rear left side

PIRELLI6mm

Front right side

PIRELLI6mm

Rear right side

PIRELLI6mm

Assessment Details

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Paint Material Ratio

80

Cash Loss

Yes No

Part Supplied by AXA

Yes No

Save

Assessment Details

General & Workshop Details | Vehicle & Driver Details | Vehicle Condition | Taxes & Ratio | Parts & Labour | Miscellaneous | Summary

Parts

Add | Approve | Deny | Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		1	1			FRONT BONNET (NPA)			Repair	0	0	0	0	0	Deny
		2	1			FRONT FENDER LH			Bent	230				230	Reviewing
		3	1			FRONT FENDER INNER SHIELD LH			Serviceable	0	0	0	0	0	Deny
		4	10			FRONT FENDER INNER SHIELD CLIPS			Serviceable	0	0	0	0	0	Deny
		5	1			HEADLAMP LH			Cut	260				260	Reviewing
		6	1			FRONT GRILLE			Repair	0	0	0	0	0	Deny
		7	10			FRONT GRILLE CLIPS			Serviceable	0	0	0	0	0	Deny
		8	1			FRONT BUMPER			Deformed	430				430	Reviewing
		9	10			FRONT BUMPER CLIPS			Necessary	0.2				2	Reviewing
		10	1			FRONT BUMPER SIDE RETAINER LH			Necessary	26				26	Reviewing

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)
		11	1			FRONT BUMPER LOWER GRILLE			Serviceable	0	0	0	0	0	Deny
		12	1			FRONT BUMPER LOWER GRILLE CHROME MOULDING			Serviceable	0	0	0	0	0	Deny
		13	1			FOG LAMP COVER LH			Missing	65				65	Reviewing
		14	1			FOG LAMP LH			Cut	110				110	Reviewing

Labour

Add | Approve | Deny | Submit All

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		LABOUR TO CARRY OUT FRONT REPAIR	400	0	0	Reviewing		
		2		TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	30	0	0	Reviewing		
		3		TO SPRAY PAINTING ON AFFECTED AREAS	400	0	0	Reviewing		

Assessment Details

General & Workshop Details | Vehicle & Driver Details | Vehicle Condition | Taxes & Ratio | Parts & Labour | Miscellaneous | Summary

Add | Approve | Deny | Submit All

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐	✎	1	DAYS OF REPAIR : 4 DAYS	Reviewing			🗑
☐	✎	2	FRONT NUMBER PLATE	Deny	0	NOT NECESSARY	🗑
☐	✎	3	FOG LAMP COVER CHROME RING	Reviewing	26	MISSING (SUPPLEMENTARY)	🗑

Assessment Details

General & Workshop Details | Vehicle & Driver Details | Vehicle Condition | Taxes & Ratio | Parts & Labour | Miscellaneous | Summary

Claim Amount $1,979.00

Claim Amount $1,979.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	$830.00	$830.00
Miscellaneous	$26.00	$26.00
Spare Parts	$1,123.00	$1,123.00

Submit for Review