22/03/2007

ASS. REC. BY: | REF: CS/MSG18005237/719d3 n2 | Special Instruction:

Surveyor: Taufikh Meirinen

ASSIGNMENT (Office)

From (Person): Revel Foo of MSIG Date/Time: 19/3/18 @ 2.28pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 1193D Insured: GBF 30894

at Workshop m/s: Premier Taxis Tel:

of: 23 changi south Ave 2 # 03-02

Policy No: 29U02413MKC Claim No: 552630

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 17/03/2018

21/3/18

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 4.11pm @ 20/3/18 Person Contacted: Vincent Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHD1193D - CS/III2006781/H/R2 D.O.A: 3/9/12
	GBF 30894 - X
26/3/18 @ 3.09pm	revised to Revel Foo via Meirinen
04/6/18 @ 5.47pm	confirmed with Gary US $1450, 3 days. by email.
	(Acct # 2437.94.647)
	5/6/18

Tan Ah Kit REF. MSIG.

ASSESSMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop / s:

of:

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of Inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpom: Consistent? : Yes or No

SIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Sum Sum: $ 3 Val.: Yes or No

DA / REV / REP. / 24 HRS "WP"

Vehicle: IN / OUT

Date: Person Contacted:

Date Time Action Instruction: Battery weak.

Veh No: SHD 1193D Reg: 2017 March.

Type: M/Car / M/Cycle / Bus / Van / Lorry / (Taxi) / Prime Mover

Truck / Trailer or:

Make: Hyundai i30 cc: 1582

Colour: Silver A/C: Insured / Std / NI / NA

Sp/Reading: — T/Pass: Insured / Std / NI / NA

Eng No:

Ch No: TMAD2814VHJ119060

Gen. Cond.: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size F: 205/65R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Maxxis

Front		Rear	
R.Bal.	6 mm	R.Bal.	6 mm
L.Bal.	6 mm	L.Bal.	6 mm
D.O.M.		D.O.M.	22/3/18 e 945

Survey held at: Primier Auto

Dmg. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

RECEIVED 05 JUN 2018

Date/Time File Passed to: 05/6 tm

Date/Time File Return to:

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 3

Resurvey No. of Trip:

Add Fee: ☐ Site Insp. $ ☐ Inspection $ ☐ Tech. Fee $ ☐ Admin Fee $

Survey Fee: 200

Transportation: 10

E-Filing:

Photos:

Total: 210

Report Received:

Survey Sum: $ 14/6

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Ref : CS/MSG18005237/T1qd3

Date : 21-03-2018

Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

	Insured Veh.	GBF 3089U	Veh. Inspected	SHD 1193D
	Policy No.	29002413MKC	Coverage ($)	0.00
	Claim No.	552630	Excess ($)	0.00
	Assign From	MERIMEN (FIEVEL FOO)	Assign Date	21/03/2018

2. Vehicle Particulars & Condition

	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			

3. Conditions of Tyres

		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm

4. Description of Damages

5. General Information

	Accident Date	17/03/2018	Inspection Date	
	Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wenyao

Date: 26 Mar 2018

Preliminary Advice

Insured Vehicle No	: GBF3089U		
TP Vehicle No	: SHD1193D	Accident Date	: 17/03/2018
Make	: HYUNDAI I40	Assignment Date	: 19/03/2018
Date of Inspection	: 22/03/2018	Est. Duration of Repair	: 3.00
Inspection At	: PREMIER TAXIS PTE LTD - CHANGI (HQ) 23 CHANGI SOUTH AVE 2 #03-02 SINGAPORE 486443		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S$	3,837.94
Revised Amount	:S$	1,791.51
Check Items (Estimated)	:S$	0.00
Total	:S$	1,791.51
Lump Sum Repair	:S$	

Total Loss Consideration

New for Old Value	:S$
Pre-Accident Value	:S$
COE / PARF Rebate	:S$
Salvage Value	:S$
Margin for Repair	:S$

Remarks

( ) The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Mar 2018		19 Mar 2018 14:28 Assign				**New Assignment** Cancel Case

Main | Reference | Claim Details | Documents | Show All

CLAIM SUBFOLDER DETAILS **[Created by insurer]**

Insured:	**SUN U AIR-CON WORKS**, Co. Reg. No.: 53121072C		
Main Claimant:	**PREMIER TAXIS PTE LTD**		
Vehicle Reg. No.:	**SHD1193D**	Date of Loss:	17/03/2018 13:00 - :59
Claim Type:	**TP** / 552630	Policy/Cover Note No.:	29002413MKC (Comprehensive) Coverage: 30/08/2017 - 29/08/2018
Vehicle Reg. No. (Insured):	**GBF3089U**	Policy No. (Claimant):	
		Excess:	
Repairer:	**Premier Taxis Pte Ltd - Changi (HQ)** 23 Changi South Ave 2 #03-02, 486443 Changi - Tel:		
Handling Insurer:	**MSIG Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: +65 6827 7888 ... [Handled by **Fievel Foo Wenyao** - 6643 1316]		
Adjuster:	**LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [**Imm.Advice** due 20/03/2018]		
Adj Asg. Remarks:	TO BE SURVEY AT UNIT NO: #01-02		

ASSOCIATED MAIL RECEIVED View All | Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?

No results.

Shiau Chan (LKKAuto)

From: Gary Shi <gary.shi@premiertaxi.com>
Sent: Monday, 4 June 2018 5:42 PM
To: Shiau Chan (LKKAuto)
Subject: RE: FINALISE OF VEHICLE SHD 1193D (DOA: 17/03/2018)

Dear Shiau Chan,

Agreed to Lump Sum $1400.00 3days.

Regards

Gary Shi
Senior Executive, Claims
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443
Tel: 6214 8880 Ext 069 | DID: 6544 6671 | Fax: 6214 1511
Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION

From: Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]
Sent: Monday, 4 June, 2018 5:18 PM
To: Gary Shi
Subject: FINALISE OF VEHICLE SHD 1193D (DOA: 17/03/2018)

Dear Gary,

Offer Lump Sum $1,400.00 before GST and 3 repair days.

Kindly confirm.

Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Text size + -

Enquire Vehicle Registration Details

Owner Particulars

NRIC/Passport/Company Cert No.:	200304975H
Owner ID Type:	Company
Owner Name:	PREMIER TAXIS PTE. LTD.
Registered Address:	23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443
Mailing Address:	-
Birth Date:	-

Vehicle Particulars

Vehicle No.:	SHD1193D
Previous Vehicle No.:	-
Effective Date of Ownership:	08 Mar 2017
Original Regn Date:	08 Mar 2017
Registration Date:	08 Mar 2017
Year of Manufacture:	2016
Vehicle Type:	Public Transport Taxi (Motor Car)
Vehicle Scheme:	Taxi (Company)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Make:	HYUNDAI
Vehicle Model:	I30 GDH 1.6 TCI 5DR DCT
Primary Colour:	Silver
Secondary Colour:	-
Passenger Capacity:	4
Chassis No.:	TMAD281UVHJ119060
Engine No.:	D4FBGZ095198
Engine Capacity/Power Rating:	1582 cc / -
Maximum Power Output:	100.0 kW (134 bhp)
Propellant:	Diesel
Max Unladen Weight:	1496 kg
Maximum Laden Weight:	1940 kg
Open Market Value:	$21,008.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Mar 2025
Minimum PARF Benefit:	$8,347.00
No. of Transfers:	0
IU Label No.:	1050704452
COE No.:	2017030801004152R
COE Expiry Date:	07 Mar 2025
COE Category:	A - Car (up to 1600cc & 97kW (130bhp))
COE Registration Category:	A - Car (up to 1600cc & 97kW (130bhp))

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

A: SHD1193D

B: GBF 3089U.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

19 MAR 2018

Premier Taxis Pte Ltd

Policyholder's Signature
Date & Time:

Driver's Signature S2508061J
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SHD1193D

Describe Circumstance of the Accident:

ON *17/03/2018 @ 1315HRS,* I WAS DRIVING MY TAXI (**SHD 1193 D**) TRAVELLING ALONG NORTH BRIDGE ROAD AT THE TRAFFIC LIGHT JUNCTION OF HIGH STREET, IN LANE 1 WITH 2 PASSENGERS ONBOARD.

I STOPPED MY TAXI AS VEHICLES AHEAD OF ME STOPPED DUE TO RED TRAFFIC LIGHT.

WHILE STATIONARY, SUDDENLYI FELT AN IMPACT FROM THE REAR.

WHEN INSPECTED, I DISCOVERED THAT VEHICLE B (**GBF 3089 U – TOYOTA VAN**) WHICH WAS BEHIND ME, FAILED TO STOP IN TIME, HAD COLLIDED ONTO THE REAR OF MY TAXI.

DUE TO THE IMPACT, MY TAXI HAD DAMAGES ON THE REAR PORTION AND I WAS NOT AWARE OF DAMAGES TO VEHICLE B.

NO INJURY INVOLVED.
NO PASSENGERS ONBOARD VEHICLE B.

*VIDEO FOOTAGE CAPTURED.

DAMAGES FOUND ON VEHICLE A & VEHICLE B



PREMIER TAXI THIRD PARTY VEHICLE

Chong Jun Le S2508061J

Driver's Signature & NRIC Number
@ 9:00:17 AM

(attended by)

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443
TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

19-Mar-17

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1193 D

1 pc	Emblem I30		$	27.80
1 pc	Emblem CRDI		$	29.40
1 pc	Emblem Hyundai		$	29.40
1 pc	Rear bumper		$	811.11
1 pc	Rear bumper sponge		$	79.20
1 pc	Rear bumper reinforcement		$	815.64
1 pc	Rear bumper reinforcement centre		$	79.20
2 pcs	Rear bumper n/s & o/s side bracket @ $52.20		$	104.40
2 pcs	Rear bumper n/s & o/s reflector @$107.50		$	215.00
1 pc	Tailgate lower garnish		$	362.61
			$	2,553.76
		Less 35%	$	893.85
			$	1,659.94

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

S/NETT

1 set	Rear bumper clips	$	48.00
1 set	Reverse sensor	$	280.00
1 set	Tailgate sticker	$	100.00
	Sundry	$	50.00
	To dismantle and replace reverse sensor and test system	$	80.00
	To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the end panel etc	$	850.00
	To putty and spray painting on the rear bumper, tailgate lower garnish, end panel	$	650.00
	To apply rustproofing on the repaired and replaced panels	$	120.00
	Total	$	3,837.94

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Tanfilah 97495749
WP
22/3/17 @ 945
Lumpsum
Resurvey after repair
Sur @ LKK Auto
3 days.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18005237/T1QD3N2
Date: 07/06/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	**Policy No:**	29002413MKC		
Claimant Vehicle No :	SHD1193D	**Insured Vehicle No :**	GBF3089U		
Date of Loss:	17/03/2018	**Nature of Claim:**	TP	**Claim No:**	552630

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	**SHD1193D**		
Make & Model:	HYUNDAI I30 GDH, 1.6 D TCI 5DR DCT (M)	**Engine No:**	D4FBGZ095198
Reg. Date:	08/03/2017 (Man. Year: 2016)	**Chassis No:**	TMAD281UVHJ119060
Colour:	Silver	**Odometer:**	0 km
Engine Capacity:	1582 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S$):	**Market Value/New Car Price**		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		**Steering (Serviceable):**	Yes	**Footbrake (Serviceable):**	Yes
Handbrake (Serviceable):	Yes	**Engine Modification:**	No	**Pre-accident Condition:**	

CONDITION OF TYRES

Front Tyre Size:	205/65 R16	**Rear Tyre Size:**	205/65 R16
Front Left Side:	Maxxis 6 mm	**Rear Left Side:**	Maxxis 6 mm
Front Right Side:	Maxxis 6 mm	**Rear Right Side:**	Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	**Repairer's**	**Adjuster's**	**Difference**	**Diff %**
Parts	2,137.94	961.51	1,176.43	55.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,700.00	830.00	870.00	51.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S$)	**3,837.94**	**1,791.51**	**2,046.43**	**53.32**
Approved Total (Overridden) (S$)		**1,400.00**		
(S$)	3,837.94	1,400.00	2,437.94	63.52
+ GST 7.00/7.00% (S$)	268.66	98.00	170.66	63.52
Nett Amount (S$)	**4,106.60**	**1,498.00**	**2,608.60**	**63.52**

INSPECTION

Date of Assignment: 19/03/2018
Date Inspected: 22/03/2018 **Inspected At:** Premier Taxis Pte Ltd - Changi (HQ)
23 Changi South Ave 2 #03-02
Singapore 486443

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID **Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:		(Last Synchronised: 07 Jun 2018)
Parts:	N/A	HYUNDAI I30 GDH 1.6 D TCI 5DR DCT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD1193D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*EMBLEM I30	Necessary	27.80 FL	*27.80 FL
2	1		*EMBLEM CRDI	Necessary	29.40 FL	*29.40 FL
3	1		*EMBLEM HYUNDAI	Necessary	29.40 FL	*29.40 FL
4	1		*REAR BUMPER	Deformed	811.11 FL	*811.11 FL
5	1		*REAR BUMPER SPONGE	Not Necessary	79.20 FL	*- FL
6	1		*REAR BUMPER REINFORCEMENT	Not Necessary	815.64 FL	*- FL
7	1		*REAR BUMPER REINFORCEMENT CENTRE	Not Necessary	79.20 FL	*- FL
8	2		*REAR BUMPER N/S & O/S SIDE BRACKET	Not Necessary	104.40 FL	*- FL
9	2		*REAR BUMPER N/S & O/S REFLECTOR	Not Necessary	215.00 FL	*- FL
10	1		*TAILGATE LOWER GARNISH	Repair	362.61 FL	*- FL
11	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS
12	1		*SET REVERSE SENSOR	Not Working	280.00 FS	*200.00 FS
13	1		*SET TAILGATE STICKER	Necessary	100.00 FS	*100.00 FS
14	1		*SUNDRY	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S$)	**3,031.76**	**1,275.71**
- List Item Discount on L Items 35.00/35.00% (S$)	893.82	314.20
Total Parts (S$)	**2,137.94**	**961.51**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE AND REPLACE REVERSE SENSOR AND TEST SYSTEM	New	80.00	30.00
2	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING TO KNOCK-OUT,STRAIGHTEN,REPAIR,RESHAPE OF THE END PANEL ETC	New	850.00	400.00
3	TO PUTTY AND SPRAY PAINTING ON THE REAR BUMPER,TAILGATE LOWER GARNISH,END PANEL	New	650.00	400.00
4	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	120.00	-
		Gross Labour Cost (S$)	**1,700.00**	**830.00**

Report was unsubmitted during this print-out.

< END OF ESTIMATES >