TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE	: ACCIDENT/BODY REPAIRS
WORKSHOP	: LENG KEE
CONTACT NO	: 67038511
REFERENCE	: 092/IC/TCAC/CCR/2018
DATE	: 11-APR-2018

EQ INSURANCE COMPANY LIMITED
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX S(069110)
TEL : 62239433
FAX : 62234190
ATTN : MOTOR CLAIM MANAGER

OWNER'S NAME	: MISS ENG SIEW CHOO
ADDRESS	: 30 TANAH MERAH KECHIL ROAD
	#02-09
	S(465558)
TELEPHONE NO	: 82883535/91080079

TYPE OF CLAIM	: COMPREHENSIVE CLAIM
POLICY NO	: DMPPHQ18-000365
VEHICLE NO	: SLA3535G
MODEL CODE	: FDRARBZJ11EWAFAJJ-
MODEL/YEAR	: NISSAN QASHQAI 2.0 MY2014
ENGINE NO	: MR20396266W
CHASSIS NO	: SJNFBAJ11U1582519
MILEAGE	: 30842 KM
DATE IN	: 11/04/2018
LIABILITY	: 0.00
EXCESS CLAUSE	: 500.00
ESTIMATE BY	: SHAWN CHUA CHU RONG
ACCIDENT DATE	: 09/04/2018

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLA3535G

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	CONI	PERFORM VEHICLE ELECTRONIC SYSTEM DIAGNOSIS, INTERROGATION & REPROGRAM MODULE WITH CONSULT	240.00	✓
2	FHI	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	✓
3	NPI	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS	60.00	✓
4	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	~~240.00~~	120
5	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	~~200.00~~	100
6	WHI	CHECK & INSPECT WIRE HARNESS FOR DAMAGE & OPEN/ SHORT CIRCUIT, REPAIR WHEN NECESSARY	240.00	X
7	ZZ/001	RENEW FRONT BUMPER,LEFT HEADLAMP,HOOD,FRONT LEFT FENDER,TRIM,GRILLE ETC. PANELS & REPAIR	~~1950.00~~	1170
8	ZZ/002	RESPRAY FRONT BUMPER,HOOD,FRONT LEFT FENDER,FRONT X LEFT DOOR ETC	~~1000.00~~	750
9	ZZ/003	QC, RETUNE & CONSULT CHECK		
10	ZZ/004	COMPLIMENTARY WASH & VACUUM		
		TOTAL LABOUR CHARGES	3978.00	

DAMAGED PARTS & PRICES

S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARK
1	FENDER TRIM	63811-4EA0A	483.00			?
2	NISSAN EMBLEM	62890-4EA0A	73.60			Rem ✓
3	HOOD REAR SEAL	65810-4EA0A	59.30			X
4	HOOD FRONT SEAL	65820-4EA0A	89.00			X
5	HOOD	F5100-4EAAA	961.40			BA ✓
6	LEFT FENDER	F3101-4EAMB	622.70			R
7	LEFT AIR GUIDE	21559-4EB6A	63.00			?
8	GRILLE	62310-4EA1A	498.30			CRA ✓
9	LEFT REINFORCEMENT STAY	F2215-4EAMA	123.70			?
10	RIGHT REINFORCEMENT STAY	F2214-4EAMA	173.10			?
11	REINFORCEMENT	F2030-4ENMA	675.40			?
12	ENERGY ABSORBER	62090-4EA1B	195.70			?
13	ARMATURE	62030-HV51A	337.70			?
14	LOWER ENERGY ABSORBER ($62.20 EA X 2)	62090-4EA0C	124.40			?
15	LEFT BUMPER BRACKET	62223-4EA0A	20.90			Re ✓
16	RIGHT BUMPER BRACKET	62222-4EA0A	20.90			?
17	FRONT BUMPER	62022-4EA0H	614.60			DC ✓
18	LEFT FOG LAMP COVER	62257-4EA0C	74.70			?
19	TOW HOOK COVER	622A0-4EA0A	19.30			? X
20	LEFT FOG LAMP	26150-8992B			258.00	?
21	LEFT HEADLAMP	26060-4EA0B	1617.00			CRA ✓
	SUB TOTAL		6847.70	0.00	258.00	
	LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		1369.54	0.00	0.00	
	GRAND TOTAL		5478.16	0.00	258.00	
	OVERALL TOTAL		5736.16			

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLA3535G

TOTAL LABOUR CHARGES	3978.00
TOTAL SPARE PARTS CHARGES	5736.16
GRAND TOTAL	9714.16 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	Rasul - Hp 90010068
SURVEYED DATE	:	19/04/18 @ 1030
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	500.00 6 days
LIABILITY	:	0.00
REMARKS	:	EXCESS: TBA

Revert

Resurvey b4 paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: