INS. CASE OWNER: ~~Forest~~ | CC 4/AXA1800 7441, Web352 | LKK: IDAC:

Surveyor: MARIUS DOI: 7/4/18 Date / Time: 7/4/18

Registered in Merimen:

ASSIGNMENT

Pre-assign / CCU / FTE

Insured Vehicle No. : SJX 1933G Claim No. : S8MOOETB | 41311

Name of Insured : PANG TAM PONG. Policy No. : GA18773771

Insured Tel No. : HP: Make / Model : PEUGEOT

Excess Sec II :S$ D.O.A : 14/4/18 Place of Accident : PIONEER RD NORTH AVE ROUNDABOUT

Is driver the owner? (YES / NO) Nature of Accident :

If NO. Driver Name / Age : MR YONG KANG KENNETH OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : (V/L: YES / NO) Insured Liability : % **Final ? Yes / No**

SFX 868R →



INSRS:
WSP: specialist.
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:

INSRS:
WSP:
Tel :
Liability :
RMKS:

INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time	
16/4/18	SFX 868R-Y SJX 1933G-X
Mahir	
	✱ Smartclaim
23.4.18 2.03	CALLED OID CONFIRMED ACCIDENT. OID REAR ENDED TP. INFORM TP CLAIM AGREED TO SETTLE AND ANSWER ABOUT NID ISSUE.
	EMAIL NSP LIABILITY CLEAR.
11.5.18	FILE PASS TO TYPIST TO PREPARE REPORT.

RECEIVED 17 MAY 2018

STAGE	DATE / PIC
Non-Reporting ltr (1st):	
Non-Reporting ltr (2nd):	
Non-Reporting ltr (Final):	
Notification ltr (if non-pickup):	
Call OI:	26.4.18 EMAIL.
After call ltr to OI:	

Documentation Check List:	Handler	Typist
Notification ltr (if non-pickup)		
After call ltr to OI:	✓	
Authorisation To Act:	✓	
Release Voucher:	✓	
Final Repair Bill:	✓	
Car Rental Invoice:		
Towing Invoice		
LTA / GIA :	✓	
Medical Bill:		
PIR:		
Mandate/~~Reject~~ Instruction:	✓	
LOD	✓	
Payment Breakdown Form:		
Post-Repair Photos:		
Others:		

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by: EKS

Repair Cost: P/P S$ 6,148.88 (6 days) Reduction: 53 % Email ✓ Call

FINAL SETTLEMENT Date/Time: 29.10.18 Confirm with IRENE Email ✓ Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : 27 If NO or B 28, Ass. Lia :

Repair Cost: W/Shop S$ 6,319.30 OID REAR ENDED TP

Loss of Rental (LOR): S$ - (days)

Loss of Use (LOU): S$ 540.00 ($ 60 x 9 days)

Loss of Income (LOI): S$ - ($ x days)

LOR only [ ] LOU only [✓] LOR + LOU [ ] LOR + LOI [ ] **[Tick only one]**

COPY SENT 7/11/18

GIA/LTA Search S$ 3.00

Medical: S$ -

Disbursement: S$ - (e.g. Tow/ Independent)

Legal Cost S$ -

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: $350

Total: S$ 7,131.30 **Global Sum S$:**

FINAL PAYMENT Date/Time: 29.10.18 Confirm with: IRENE Email ✓ Call

Payee 1:	S$ 7,131.30	Name 1:	SPECIALISTS MOTOR PTE LTD
Payee 2: (Strike if N.A.)	S$	Name 2:	
Payee 3: (Strike if N.A.)	S$	Name 3:	

(08/11/13) wef

ASS. REC. BY: Marcus

REF: AEA/2

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFX 868R

at Workshop m/s Sparkt. Section

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 6K

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA + PR Seen: ✓ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SFX 868R Yr Regn: 9 / 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or CA/

Make: mazda 2 c.c 1496

Colour purple A/C: Insured / Std / NI / NA

Sp.Reading 39776 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6DJ2HAA0110U470

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi : Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 195/55-R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front		Rear	
R/Bal.	f mm	R/Bal.	f mm
L/Bal.	f mm	L/Bal.	f mm
D.O.A.	19/4/18	D.O.I	23/4/18

Survey held at _____

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Ree

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	LTA: 47.654 Ref Ltr
	P/P: $6,148.88 (RED: $6,864.80 53%)

Date/Time, File Pass to?

1) _____

Date/Time, File Return to?

2) _____

☐ : Preli. Report

☐ : Final Report

Report Format : _____

Lump Sum / I.B.I: ($ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp ($ _____)

☐ : Interview ($ _____)

☐ : Tech. Invs ($ _____)

☐ : Weekend ($ _____)

Survey Fee:	
Transportation:	
___$ x RS___$	
Photos	
Others	
TOTAL	

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711
Tel: 67472112 (5 lines) Fax: 67438032
Email: cardoc@singnet.com.sg
Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SFX868R/1804076

20th April 2018

The Manager
Motor Claim Department
AXA Insurance Pte Ltd
8 Shenton Way,
#27-01 AXA Tower
Singapore 068811

...sultants hence notify
...following:
...spray painting
...during resurvey
...subject to confirmation
...Without Prejudice" basis
...is allowed
...must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Not Attend
abv
P/P = 6148.88
Tahp plus Behind pnly
6 dy.
23/4/18

Date of Accident : 19th April 2018

Location : AYE

Third Party Claim Vehicle No : SJX 1933 G

Repair Cost For Vehicle No : SFX 868 R Mazda 2

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Rear boot cover Rod/SD	1	911.70	$ 911.70
2	Rear boot cover emblem (logo) nil	1	58.00	$ 58.00
3	Rear boot cover emblem (mazda 2) nil	1	55.00	$ 55.00
4	Rear boot cover emblem (skyactiv) nil	1	64.00	$ 64.00
5	Rear boot cover reflector L&RH	2	221.00	$ 442.00 SVC
6	Rear boot lock Tan/Yin	1	202.00	$ 202.00
7	Rear boot cover catch 11	1	38.00	$ 38.00
8	Rear boot wiper motor 11	1	318.00	$ 318.00
9	Rear windscreen glass ~~with~~ moulding nil 88.00	1	878.00	$ 878.00
10	Rear lamp assy L&RH	2	728.00	$ 1,456.00 SVC
11	Rear end panel	1	380.00	$ 380.00 dented
12	Rear lamp panel inner garnish Tan	1	74.00	$ 74.00
13	Rear lamp panel inner garnish clips 11	1set	48.00	$ 48.00
14	Rear bumper fascia Dis	1	850.00	$ 850.00
15	Rear bumper clips nil	1set	48.00	$ 48.00
16	Rear bumper bracket L&RH Kap	2	18.00	$ 36.00
17	Rear bumper side retainer L&RH Bont	2	28.00	$ 56.00
18	Rear boot floor panel nil	1	836.00	$ 836.00
19	Rear tool tray Tan	1	143.00	$ 143.00
20	Rear exhaust silencer assy	1	1,053.00	$ 1,053.00 SVC
				$ 7,946.70
		Less	20%	$ 1,589.34
				$ 6,357.36

lock sensor etc

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711
Tel: 67472112 (5 lines) Fax: 67438032
Email: cardoc@singnet.com.sg
Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SFX868R/1804076

20th April 2018

No.	Particulars	Qty	Price	Amounts
	Balance b/f			$ 6,357.36
21	Rear bumper sensor (s/net)	1set	380.00	$ 380.00
22	Rear windscreen sealant (s/net)	1	60.00	$ 60.00
23	Rear end panel sealer (s/net)	1	80.00	$ 80.00
24	Rear number plate (s/net)	1	50.00	$ 50.00
25	Rear boot insulator shield (s/net)	1	380.00	$ 380.00
				$ 7,307.36

Labour Charges :-		Amounts
Towing fee		$ 80.00
Cut out, renew, knocking & welding rear boot cover, rear end panel, rear boot floor panel, rear fender L&RH, remove & install all damage parts, straighten & re-align body		$ 1,880.00
Remove & install rear windscreen glass		$ 120.00
Remove & refix rear bumper sensor		$ 80.00
Remove & install rear exhaust silencer to facilitate repairs		$ 100.00
Tuff-kote on damage parts		$ 120.00
Remove & install rear seats, upholstery & etc		$ 380.00
Spray painting on damage parts		$ 1,800.00
Diagnostic & reset	11	$ 320.00
Check all lighting after repairs		$ 40.00
Labour Charge		$ 4,920.00
Total Amount		$12,227.36

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711
Tel: 67472112 (5 lines) Fax: 67438032
Email: cardoc@singnet.com.sg
Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SFX868R/1804076

20th April 2018

The Manager
Motor Claim Department
AXA Insurance Pte Ltd
8 Shenton Way,
#27-01 AXA Tower
Singapore 068811

Date of Accident	:	19th April 2018
Location	:	AYE
Third Party Claim Vehicle No	:	SJX 1933 G
Repair Cost For Vehicle No	:	SFX 868 R Mazda 2

Supplementary Supply of Parts

No.	Particulars	Qty	Price	Amounts
1	Rear boot lock sensor	1	105.80	$ 105.80
2	Rear bumper centre bracket	1	5.10	$ 5.10
3	Rear boot camera	1	805.00	$ 805.00
4	Trim air cowling panel	1	67.00	$ 67.00
				$ 982.90
				20% 196.32

GST will be reflected in the final bills.

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711
Tel: 67472112 (5 lines) Fax: 67438032
Email: cardoc@singnet.com.sg
Bus. Reg No: 199502604 E GST No: 19-9502604-E

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SM/SFX868R/1804076

20th April 2018

The Manager
Motor Claim Department
AXA Insurance Pte Ltd
8 Shenton Way,
#27-01 AXA Tower
Singapore 068811

Not Attend
after
2/25
The plus Before party
60.
23/4/18

Date of Accident : 19th April 2018

Location : AYE

Third Party Claim Vehicle No : SJX 1933 G

Repair Cost For Vehicle No : SFX 868 R Mazda 2

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Rear boot cover Body SD	1	911.70	$ 911.70
2	Rear boot cover emblem (logo) NEC	1	58.00	$ 58.00
3	Rear boot cover emblem (mazda 2) NEC	1	55.00	$ 55.00
4	Rear boot cover emblem (skyactiv) NEC	1	64.00	$ 64.00
5	Rear boot cover reflector L&RH	2	221.00	$ 442.00 ?
6	Rear boot lock Twin/Grp	1	202.00	$ 202.00
7	Rear boot cover catch 〃	1	38.00	$ 38.00 ✗
8	Rear boot wiper motor 〃	1	318.00	$ 318.00 ✗
9	Rear windscreen glass ~~with~~ moulding NEC	1	878.00	$ 878.00
10	Rear lamp assy L&RH	2	728.00	$ 1,456.00 ?
11	Rear end panel	1	380.00	$ 380.00 ?
12	Rear lamp panel inner garnish Twin	1	74.00	$ 74.00
13	Rear lamp panel inner garnish clips 〃	1set	48.00	$ 48.00 ✗
14	Rear bumper fascia D.J	1	850.00	$ 850.00
15	Rear bumper clips NEC	1set	48.00	$ 48.00
16	Rear bumper bracket L&RH Repl	2	18.00	$ 36.00
17	Rear bumper side retainer L&RH Front	2	28.00	$ 56.00
18	Rear boot floor panel R	1	836.00	$ 836.00 ✗
19	Rear tool tray Twin x	1	143.00	$ 143.00
20	Rear exhaust silencer assy	1	1,053.00	$ 1,053.00 ?
				$ 7,946.70
		Less	20%	$ 1,589.34
				$ 6,357.36

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711
Tel: 67472112 (5 lines) Fax: 67438032
Email: cardoc@singnet.com.sg
Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SFX868R/1804076

20th April 2018

No.	Particulars	Qty	Price	Amounts
	Balance b/f			$ 6,357.36
21	Rear bumper sensor (s/net)	1set	380.00	$ 380.00
22	Rear windscreen sealant (s/net)	1	60.00	$ 60.00
23	Rear end panel sealer (s/net)	1	80.00	$ 80.00
24	Rear number plate (s/net)	1	50.00	$ 50.00
25	Rear boot insulator shield (s/net)	1	380.00	$ 380.00
				$ 7,307.36

Labour Charges :-	Amounts
Towing fee	$ 80.00
Cut out, renew, knocking & welding rear boot cover, rear end panel, rear boot floor panel, rear fender L&RH, remove & install all damage parts, straighten & re-align body	$ 1,880.00
Remove & install rear windscreen glass	$ 120.00
Remove & refix rear bumper sensor	$ 80.00
Remove & install rear exhaust silencer to facilitate repairs	$ 100.00
Tuff-kote on damage parts	$ 120.00
Remove & install rear seats, upholstery & etc	$ 380.00
Spray painting on damage parts	$ 1,800.00
Diagnostic & reset	$ 320.00
Check all lighting after repairs	$ 40.00
Labour Charge	$ 4,920.00
Total Amount	$12,227.36

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

Menu

Service Request Details

Claim
S8M00ETB

Reference
None

Loss Date
April 19, 2018

LKK AUTO CONSULTANTS PTE LTD (TP)

23042018 @ 1.07pm

Irene Wah in

Murrey.

Request Date
April 23, 2018

Due Date
April 30, 2018

Vendor Name
LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss
Third Party Vehicle Damage

Services
Pending verification - Direct Settlement

Actions

Next Step
Agree to perform service

Decline Work | Accept Work

Vehicle Information

Incident Vehicle Registration #
SFX868R

Make
TPVD MAZDA

Menu

Service Address

, , ,

Primary Contact/Insured

PANG TAU PONG
BLK 620, JURONG WEST STREET 65, #10-450, 640620, Singapore

MOTOR@IVANINSURANCE.COM

Claim Handler

TAY Ernest
6568804835
ernest.tay@axa.com.sg

Additional Instructions

Messages | Invoices | History | Documents | Assessment | Metrics | Notes

New Message

MANDATE REQUEST FOR S8M00ETB

Type
Question

Message
Liability: Insured rear ended third party vehicle. Spoken to insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost : $6,579.30 (w/GST) Loss of Use: $540.00 (6days x $90) LTA: $2.00 Total: $7,121.30 Revised Immediate Advice with Mandate uploaded for your easy referance. Please kindly let us have your approval / instruction if any. Thank you - Asher Sng (11/06/2018)

Reply

Re:RE: MANDATE REQUEST FOR S8M00ETB

Type
Question

Message
HI LKK, pls proceed as per mandate. Thank you.

Reply

THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)

Vehicle No:	**SJX 1933G (Insd veh)**	**Model:**	**MAZDA2 5-DOOR**
	SFX 868R (TP veh)		**HATCHBACK 1.5L SP.6EAT**
Date of Accident:	**19/04/2018**		

Global Sum Settlement	: [ ] Yes	[X] No		
Repair Estimate	: $	13,924.64		
Final Repair Cost	: $	6,579.30		
Loss of Use	: $	540.00	9	days at $60.00 per day
Rental (if any)	: $			days
LTA / GIA Search Fee	: $	2.00		

Others:	: $	

	: $	
Final Settlement Sum	: $	7,121.30

Is Third Party Workshop GIA Registered? [ ] **YES** [X] **NO** (Kindly indicate below)

A) For **Non GIA Registered Workshop:** Agreed Liability _____100_____(%)

B) For **GIA Registered Workshop:** BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: _____(%) Assessed Liability (*):_____(%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

_____

Payment Instruction: Payee's Breakdown			
1)	SPECIALISTS MOTOR PTE LTD	: $	7,121.30

NUR SHAQILAH BTE ABDOL WAHAB

04/12/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any)

Service Request Details

Claim S8M00ETB

Reference CC4/ASM18007441/Ueb3s2

Loss Date April 19, 2018

Request Date August 21, 2018

Due Date April 23, 2019

Vendor Name LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss Third Party Vehicle Damage

Services Pending verification - Direct Settlement

Actions

Next Step Finish the work

Complete Work

More

Document Type

Document SubType

Upload Documents

Vehicle Information

Incident Vehicle Registration # SFX868R

Make TPVD MAZDA

Model 2-1.5 SEDAN L SP.6EAT (A)

Service Address

Primary Contact/Insured

PANG TAU PONG
BLK 620, JURONG WEST STREET 65, #10-450,
640620, Singapore

MOTOR@IVANINSURANCE.COM

Claim Handler

ANG Richard

richard.angbs@axa.com.sg

Additional Instructions

Messages Invoices History Documents

Assessment Metrics Notes

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED

Service Request Details

Claim S8M00ETB

Reference

CC4/ASM18007441/Ueb3s2

Loss Date

April 19, 2018 Request Date

August 21, 2018 Due Date

April 23, 2019 Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP) Type of Loss

Third Party Vehicle Damage Services

Pending verification - Direct Settlement

Actions

Next Step Finish the work

Complete Work

Miss

Vehicle Information

Incident Vehicle Registration # SFX868R

Make

TPVD MAZDA

Model

2-1.5 SEDAN L SP,6EAT (A)

Service Address

Primary Contact/Insured

PANG TAU PONG
BLK 620, JURONG WEST STREET 65, #10-450,
640620, Singapore

MOTOR@IVANINSURANCE.COM

Claim Handler

ANG Richard

richard.angbs@axa.com.sg

Additional Instructions

Messages Invoices History Documents

Assessment Metrics Notes

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE

Assessment Details

General & Workshop Details | Vehicle & Driver Details | Vehicle Condition | Taxes & Ratio | Parts & Labour | Miscellaneous | Summary

Vehicle & Driver Details

Vehicle Registration#	SFX868R	Purchase Date	mm/dd/yyyy
Registration State	SINGAPORE	Registration Date *	09/25/2015
Mileage	39776	Age of Vehicle	2

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year		2015
Make	TPVD MAZDA	MAZDA
Model	2-1.5 SEDAN L SP.6EAT (A)	MAZDA2 5-DOOR HATCH
Type		
Type of Paint		
Chassis No		JM6DJ2HAA01100470
Engine No		P520314473
Engine Capacity		1496 cc

Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	TAN RENA	
Date of Birth	January 28, 1978	mm/dd/yyyy
Age	40	
Occupation	Unknown	
Education Qualification	Other	
Driving Experience	0	
Driver License #		

English (default) ▾ LRK AUTO CONSULTANTS PTE LTD (TP) ▾

SERVICE REQUESTS MESSAGES CLAIMS

Assessment Details

General & Workshop Details | Vehicle & Driver Details | Vehicle Condition | Taxes & Ratio | Parts & Labour | Miscellaneous | Summary

Detailed Assessment

Inspection Date *	04/23/2018
Total Loss	Yes No
Towing Charges	0
Voluntary Excess	0
Compulsory Excess	0
Young/Inexperienced/Unnamed Driver Excess	0
Other Excess	

Condition of Vehicle at time of survey

General condition	Good
Steering (Serviceable)	Yes No
Footbrake (Serviceable)	Yes No
Handbrake (Serviceable)	Yes No
Engine Modification	Yes No
Pre-accident condition	Good

Tyre Condition

Age of Tyres		Spare wheel	
Front Tyre Size	195/55R16	Rear Tyre Size	195/55R16
Front left side	TOYO 8mm	Rear left side	TOYO 8mm
Front right side	TOYO 8mm	Rear right side	TOYO 8mm

SERVICE REQUESTS MESSAGES CLAIMS

Assessment Details

General & Workshop Details | Vehicle & Driver Details | Vehicle Condition | Taxes & Ratio | Parts & Labour | Miscellaneous | Summary

Parts

Add | Approve | Deny | Submit All

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		1	1			REAR BOOT COVER			Damaged	911.7		20		729.36	Reviewing	
		2	1			REAR BOOT COVER EMBLEM (LOGO)			Necessary	58		20		46.4	Reviewing	
		3	1			REAR BOOT COVER EMBLEM (MAZDA 2)			Necessary	55		20		44	Reviewing	
		4	1			REAR BOOT COVER EMBLEM (SKYACTIV)			Necessary	64		20		51.2	Reviewing	
		5	2			REAR BOOT COVER REFLECTOR L&RH			Serviceable	0		20		0	Reviewing	
		6	1			REAR BOOT LOCK			Twisted	202		20		161.6	Reviewing	
		7	1			REAR BOOT COVER CATCH			Serviceable	0		20		0	Reviewing	
		8	1			REAR BOOT WIPER MOTOR			Serviceable	0		20		0	Reviewing	
		9	1			REAR WINDSCREEN GLASS MOULDING			Necessary	88		20		70.4	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
☐	✎	23	1			REAR BOOT CAMERA			Shorted	805		20		644	Reviewing	🗑
☐	✎	24	1			TRIM AIR COWLING PANEL			Cracked	67		20		53.6	Reviewing	🗑

Labour

Add | Approve | Deny | Submit As

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
☐	✎	1		TOWING FEE.	60	0	0	Reviewing		🗑
☐	✎	2		CUT OUT, RENEW, KNOCKING & WELDING REAR BOOT COVER, REAR END PANEL, REAR BOOT FLOOR PANEL, REAR FENDER L&RH, REMOVE & INSTALL ALL DAMAGE PARTS, STRAIGHTEN & RE-ALIGN BODY.	1000	0	0	Reviewing		🗑
☐	✎	3		REMOVE & INSTALL REAR WINDSCREEN GLASS.	120	0	0	Reviewing		🗑
☐	✎	4		REMOVE & REFIX REAR BUMPER SENSOR.	50	0	0	Reviewing		🗑
☐	✎	5		REMOVE & INSTALL REAR EXHAUST SILENCER TO FACILITATE REPAIRS.	60	0	0	Reviewing		🗑
☐	✎	6		TUFF-KOTE ON DAMAGE PARTS.	60	0	0	Reviewing		🗑
☐	✎	7		REMOVE & INSTALL REAR SEATS, UPHOLSTERY & ETC.	80	0	0	Reviewing		🗑
☐	✎	8		SPRAY PAINTING ON DAMAGED PARTS.	1200	0	0	Reviewing		🗑
☐	✎	9		DIAGNOSTIC & RESET.	0	0	0	Reviewing		🗑
☐	✎	10		CHECK ALL LIGHTING AFTER REPAIRS.	30	0	0	Reviewing		🗑

English (default) LKK AUTO CONSULTANTS PTE LTD (TP)

SERVICE REQUESTS MESSAGES CLAIMS

Assessment Details

General & Workshop Details | Vehicle & Driver Details | Vehicle Condition | Taxes & Ratio | Parts & Labour | Miscellaneous | Summary

Add | Approve | Deny | Submit All

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐	✎	1	DAYS OF REPAIR	Reviewing		6	🗑
☐	✎	2	SET REAR BUMPER SENSOR	Reviewing	200	SHORTED	🗑
☐	✎	3	REAR WINDSCREEN SEALANT	Reviewing	40	NECESSARY	🗑
☐	✎	4	REAR END PANEL SEALER	Reviewing	50	NECESSARY	🗑
☐	✎	5	REAR NUMBER PLATE	Reviewing	40	BENT	🗑
☐	✎	6	REAR BOOT INSULATOR SHIELD	Reviewing	0	NOT NECESSARY	🗑

English (default) LAX AUTO CONSULTANTS PTE LTD (TP)

SERVICE REQUESTS MESSAGES CLAIMS

Assessment Details

General & Workshop Details | Vehicle & Driver Details | Vehicle Condition | Taxes & Ratio | Parts & Labour | Miscellaneous | Summary

Claim Amount $6,148.88

Claim Amount $6,148.88

CATEGORY	ESTIMATE	REVISED AMOUNT
Spare Parts	$3,158.88	$3,158.88
Labour	$2,660.00	$2,660.00
Miscellaneous	$330.00	$330.00

Submit for Review