Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept **Tel: 6841 0055 / Fax: 6256 4315**	**Estimate No.** **Date** **Service Advisor** **Pages** **Regn No** **Model No**	PA/OD/0500/2018/GW 3-May-18 CHANG 1 of 1 SLJ 465 Y Audi A4 SEDAN 1.4 TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	FRONT REINFORCEMENT BEAM Bent	$ 702.00	$ 561.60
2	BONNET STOP BUFFER Swr	$ 17.00	$ 13.28
3	BONNET BUNGS	$ 36.00	$ 28.32
	TOTAL PARTS :	**$ 755.00**	$ 603.20
	GRAND TOTAL :	**$ 755.00**	

For Premium Automobiles Pte Ltd

Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0500/2018/GW
Date	:	26-Apr-18

Vehicle IN workshop. Kindly arrange for survey.

Hi Adrian
6 days - exclude 1 Sunday - ok -
jb 2 Jun 18

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	PREMIUM AUTOMOBILES PTE LTD
Address	:	55 Ubi Road 1 Singapore 408699
Telephone	:	HP +6568365223
Type of Claim	:	Own Damage Claim
Policy No.	:	999995082/100787785-00000
Vehicle No	:	**SLJ 465 Y**
Model Code	:	Audi A4 Sedan 1.4 TFSI S
Model / Year	:	Nov-16
Engine No	:	CVN 017657
Chassis No	:	WAUZZZF43HA024629
Mileage	:	-
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	25-Apr-18
Place of Accident	:	Adam Flyover

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLJ 465 Y.

S/N	Nature of Jobs			Estimated Charges		*Surveyor's Recommendation*
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N	$	360.00	$	*360.00*
2	To remove and transfer aircon condenser, radiaotor, charged air cooler, elctrical fans and control unit. To carry out vacuum/ regas and to pressurise cooling system.	S/N	$	1,000.00	$	*1,000.00*
3	To dismantle front bumper, both headlights and bonnet. Renew front lock carrier and align to position. Renew damaged panels. Re-organise front crash manegement components. Reinstall all parts removed. *(Added $250 for another Headlamp)*		$	4,200.00	$	*1,500.00*
4	To respray front bumper and bonnet.		$	1,500.00	$	*1,100.00*
5	To carry out diagnostic check.	S/N	$	192.00	$	*192.00*
	TOTAL LABOUR CHARGES	:	**$**	**7,252.00**	$	*4,152.00*

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLJ 465 Y.

S/N	Parts Description		Damage Parts & Prices S/NETT		REMARKS
1	FRONT BUMPER		$ 1,849.00	$	1,479.20
3	FRONT BUMPER SECURING STRIP	2	$ 60.00	$	47.84
4	FRONT BUMPER GRILLE-CENTRE		$ 171.00		
5	RADIATOR GRILLE		$ 972.00	$	777.20
6	FOAM FILLER PIECE		$ 107.00	$	85.20
7	FRONT BUMPER SUPPORT-LH/RH	2	$ 48.00	$	38.24
8	FRONT BUMPER LOCK CARRIER BRACKET		$ 118.00	$	94.00
9	FRONT BUMPER COVER		$ 109.00	$	87.20
10	RELEASE LEVER		$ 12.00		
11	BOWDEN CABLE		$ 50.00	$	40.00
12	SIGN "CAUTION"		$ 12.00	$	9.28
13	LED HEADLIGHT-LH/RH		$ 13,946.00	$	11,156.80
14	BONNET		$ 2,163.00	$	1,730.40
15	BONNET ATTACHMENT PARTS		$ 105.00		
16	IMPACT PROTECTION-LH		$ 24.00	$	18.88
17	IMPACT PROTECTION-RH		$ 24.00	$	18.88
18	IMPACT PROTECTION-CENTER		$ 24.00	$	18.88
19	BONNET STRIKER -LH/RH	2	$ 88.00	$	69.92
20	BONNET LID LOCK	2	$ 376.00		
	SUB- TOTAL SPARE PARTS :		**$ 20,258.00**	$	15,671.92

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLJ 465 Y.

S/N	Parts Description			Damage Parts & Prices S/NETT		REMARKS
		c/f			$	15,671.92
21	BONNET LOCK CARRIER		$	891.00		
22	AIR GUIDE-LH/RH	2	$	46.00		
23	RADIATOR INNER DUCT-LH/RH	2	$	20.00	$	15.36
24	AIR GUIDE-UPPER		$	14.00		
25	A/C CONDENSOR WITH FLUID RESERVOIR		$	540.00	$	432.00
26	COOLER FOR COOLANT		$	585.00	$	468.00
27	RUBBER BUSH-LOWER	4	$	38.00		
28	COOLANT CONCENTRATE	4	$	133.00		
29	FRONT NO.PLATE	S/N	$	25.00	$	25.00
30	SUPPLEMENTARY		$	755.00	$	603.20
31	SUNDRIES		$	400.00	$	42.16
	TOTAL SPARE PARTS	:	**$**	**23,705.00**	$	17,257.64
	TOTAL LABOUR CHARGES	:	**$**	**7,252.00**	$	4,152.00
	GRAND TOTAL	:	**$**	**30,957.00**	$	21,409.64

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLJ 465 Y

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0500/2018/MAS

20 Nov 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Dear Sir,

RE: INSURANCE CLAIM FOR SLJ 465 Y, Audi A4 Sedan 1.4 TFSI S-Tro

With reference to the above-mentioned vehicle, no **SLJ 465 Y,** claimant, **Premium Automobiles Pte Ltd,** please find the related document per attached.

1. A copy of the Original invoice no. 85013118 – S$19,698.31
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLJ 465 Y

Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408690
Telephone 6388 2323

Customer Service
Service Appointment 6366 2323
24 hour Breakdown Service 9828 1233
Email customercare@premiumauto.com.sg

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 1 09:58

Invoice: 85013118
Date : 12/11/2018
Order : SLJ0465Y
Term : 30

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SLJ0465Y (V 31165) Regn Date: 25/11/2016 Mileage: 23000 WIP No.: 63622

Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF43HA024629 Engine: CVN 017657 Dept: U

VSB No.:

You have been assisted by :- UB-Jiayee (87)

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	25.00	1.00	25.00
Q	EXC	M: 8888 Insurance Excess/Liability	-3000.00	1.00	-3,000.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	M: TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, CHARGED AIR COOLER, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM/REGAS AND TO PRESSURISE COOLING SYSTEM	1000.00	1.00	1,000.00
S	BODYWORK	M: TO DISMANTLE FRONT BUMPER, BOTH HEADLIGHT AND BONNET. REALIGN FRONT LOCK CARRIER TO POSITION. RENEW DAMAGED PANELS. REORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL	1500.00	1.00	1,500.00

Sub-Total	
7% GST	
Grand Total	

Customer

Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408680
Telephone 6388 2323
Telefax 6841 1023

Customer Service
Service Appointment 6366 2323
24 hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 2 09:58

Invoice: 85013118
Date : 12/11/2018
Order : SLJ0465Y
Term : 30

Account: A0006 (T 0)

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SLJ0465Y (V 31165) Regn Date: 25/11/2016 Mileage: 23000 WIP No.: 63622

Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF43HA024629 Engine: CVN 017657 Dept: U

VSB No.:

You have been assisted by :- UB-Jiayee (87)

		Details		Qty	Unit Price	Amount
		ALL PARTS REMOVED				
S	BODYWORK	M:		1100.00	1.00	1,100.00
		TO RESPRAY FRONT BUMPER AND BONNET				
S	BODYWORK	M:		192.00	1.00	192.00
		TO CARRY OUT DIAGNOSTIC CHECK				
X	A8W0853651 3FZ	GRILLE	Less 020%	1.00	971.50	777.20
X	A8W0941773A	HEADLIGHT	Less 020%	1.00	6973.00	5,578.40
X	A8W0941774A	HEADLIGHT	Less 020%	1.00	6973.00	5,578.40
X	A8W0807081	COVER	Less 020%	1.00	109.00	87.20
X	A8W0121251K	RADIATOR	Less 020%	1.00	585.00	468.00
X	A8W0816421H	CONDENSER	Less 020%	1.00	540.00	432.00
X	A8W0807550A	FOAM INSER	Less 020%	1.00	106.50	85.20
X	A8W0807113	BRACKET	Less 020%	1.00	702.00	561.60
X	A8W0823029A	HOOD	Less 020%	1.00	2163.00	1,730.40
X	A8W0807065C GRU	COVER	Less 020%	1.00	1849.00	1,479.20
X	A8W0807334	SUPPORT	Less 020%	1.00	23.90	19.12
X	A8W0807333	SUPPORT	Less 020%	1.00	23.90	19.12
X	A8W0823185B	CATCH	Less 020%	1.00	43.70	34.96

Sub-Total	
7% GST	
Grand Total	

Customer

Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Telephone 6388 2323

Customer Service
Service Appointment 6366 2323
24 hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 3 09:58

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85013118
Date : 12/11/2018
Order : SLJ0465Y
Term : 30

Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SLJ0465Y (V 31165) Regn Date: 25/11/2016 Mileage: 23000 WIP No.: 63622

Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF43HA024629 Engine: CVN 017657 Dept: U

VSB No.:

You have been assisted by :- UB-Jiayee (87)

		Details		Qty	Unit Price	Amount
X	A8W0823186B	CATCH	Less 020%	1.00	43.70	34.96
X	A4M0121095	BOLT	Less 020%	2.00	2.20	3.52
X	A8W0121673A	AIR DUCT	Less 020%	1.00	9.60	7.68
X	A8W0121674A	AIR DUCT	Less 020%	1.00	9.60	7.68
X	A8W0820536	BRACKET	Less 020%	1.00	15.60	12.48
X	A8W0807277	STRIP	Less 020%	2.00	29.90	47.84
X	A8W0823125	PROTECTION	Less 020%	1.00	23.60	18.88
X	A8W0823126	PROTECTION	Less 020%	1.00	23.60	18.88
X	A4E0260749A	WASHER	Less 020%	1.00	3.20	2.56
X	A3D0260749C	WASHER	Less 020%	1.00	3.80	3.04
X	A8P4803593A	PLUG	Less 020%	2.00	17.70	28.32
X	A8T0823433B	BUMPER	Less 020%	2.00	8.30	13.28
X	A8P0823433B	BUMPER	Less 020%	2.00	4.60	7.36
X	A8W0823529E	BOWD CABLE	Less 020%	1.00	50.00	40.00
X	A8W0010515A	STICKER	Less 020%	1.00	6.10	4.88
X	A8K0010520A	PLATE	Less 020%	1.00	11.60	9.28
X	A8W0807771	BRACKET	Less 020%	1.00	117.50	94.00
X	AN 91093901	RIVET	Less 020%	4.00	0.70	2.24

Sub-Total	
7% GST	
Grand Total	

Customer

Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408705
Telephone 6388 2323
Telefax 6844 1933

Customer Service
Service Appointment 6366 2323
24 hour Breakdown Service 0800 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 4 09:58

Invoice: 85013118
Date : 12/11/2018
Order : SLJ0465Y
Term : 30

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SLJ0465Y (V 31165) Regn Date: 25/11/2016 Mileage: 23000 WIP No.: 63622

Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF43HA024629 Engine: CVN 017657 Dept: U

VSB No.:

You have been assisted by :- UB-Jiayee (87)

		Details		Qty	Unit Price	Amount
X	AN 10226501	PLUG	Less 020%	4.00	1.90	6.08
X	A8W0823124	PROTECTION	Less 020%	1.00	23.60	18.88

Parts	17,232.64
Labour	0.00
Sublet	4,177.00
Menus	0.00
Lubricant	0.00

Sub-Total	18,409.64
7% GST	1,288.67
Grand Total	19,698.31

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLJ 465 Y

Norah Khai — from
6768 9828 — Telephone +65-
6841 1183 — Telefax +65-
Mobile +65-
Body Repair — Our department
Your Claim Ref
PA/OD/0500/2018/JT — Our Ref
10 May 2018 — Date
1 — total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model	:	Audi A4 Sedan 1.4 TFSI S-tronic
Vehicle Chassis No.	:	WAUZZZF43HA024629
Vehicle Regn No.	:	**SLJ 465 Y**
Vehicle Mileage	:	20,160km
Vehicle Owner	:	Premium Automobiles Pte Ltd
Certificate No	:	999994629/100787785-00000
Policy Excess	:	S$3,210.00 (inclusive GST)
Accident Date	:	25th April 2018
Place	:	**Adam Flyover**
Repair Cost	:	$ 19,698.31
WIP No.	:	**63622**
Repairer's Name	:	Premium Automobiles Pte Ltd

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

PREMIUM AUTOMOBILES PTE LTD

Owner / Insured Signature :

Time :

Date : 10/05/2018

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Apr 2018		26 Apr 2018 16:43 Edit Adj Rpt	**S$21,409.64** Edit Estimates	**S$21,409.64** View Rpt		**Pending for Survey Report** Cancel Case

Main | Reference | Claim Details | Documents | Show All

CLAIM SUBFOLDER DETAILS **[Created by insurer]**

Insured:	**PREMIUM AUTOMOBILES PTE LTD**, Co. Reg. No.: 199902271W		
Vehicle Reg. No.:	**SLJ465Y**	Date of Loss:	25/04/2018 19:00 - :59 [**17** Months From LTA Reg Date (Man Yr)]
Claim Type:	**OD** / 1909359392SG	Policy/Cover Note No.:	0999994629 (Comprehensive)
		Excess:	S$3,000.00
Repairer:	**Premium Automobiles Pte Ltd (UBI)** 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	**AIG Asia Pacific Insurance Pte. Ltd. (SG)** - Tel: 65-6419-3000 ... [Handled by **Loo, Tong Shing**] TongShing.Loo@aig.com		
Adjuster:	**LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **ADRIAN LING**] ... [**Final Rpt** due 08/05/2018]		
Driver/Custodian:	LIN FENGRONG (29 / Male), NRIC: S8817761D, Tel: +6590262586		

ASSOCIATED MAIL RECEIVED View All | Compose Case Mail

- AIG_SG (15/10/2018): **Alert - Adj Mandate Approved (S$21409.64) - SLJ465Y - Claim Handler: Loo, Tong S...**
- AIG_SG (24/07/2018): **Alert - Adj Mandate Maintained - SLJ465Y - Claim Handler: Loo, Tong Shing**
- AIG_SG (03/05/2018): **Alert - Adj Mandate Approved (S$16947.00) - SLJ465Y - Claim Handler: Loo, Tong S...**
- AIG_SG (02/05/2018): **Alert - Adj Mandate Maintained - SLJ465Y - Claim Handler: Loo, Tong Shing**
- AIG_SG (02/05/2018): **SLJ465Y / OD / 25/04/2018 / Coverage & Excess update**

ALL ASSOCIATED TASKS View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?

No results.

Claim Documents

***SLJ465Y (1909359392SG)**
OD
Apr 25 2018 7:00PM
[PREMIUM AUTOMOBILES PTE LTD]
Premium Automobiles Pte Ltd

View: View in Browser

Upload Documents | Upload Photos | Compose New Letter | Upload Video | Upload Audio

1 per page

Assessment Reports

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	02/05/18 11:03	**Adjuster Immediate Advice**	i	Load HTM	
2	20/07/18 10:01	**Adjuster Immediate Advice**	i	Load HTM	

3 per page

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	02/05/18 15:41	**General View**	i	Load JPG	✔
2	02/05/18 15:41	**Chassis Number**	i	Load JPG	✔
3	02/05/18 15:41	**General View**	i	Load JPG	✔
4	02/05/18 15:41	**General View**	i	Load JPG	✔
5	02/05/18 15:41	**General View**	i	Load JPG	✔
6	02/05/18 15:41	**General View**	i	Load JPG	✔
7	02/05/18 15:41	**General View**	i	Load JPG	✔
8	02/05/18 15:41	**General View**	i	Load JPG	✔
9	02/05/18 15:41	**General View**	i	Load JPG	✔
10	02/05/18 15:41	**General View**	i	Load JPG	✔
11	02/05/18 15:41	**General View**	i	Load JPG	✔
12	02/05/18 15:41	**General View**	i	Load JPG	✔
13	02/05/18 15:41	**General View**	i	Load JPG	✔
14	02/05/18 15:41	**General View**	i	Load JPG	✔
15	02/05/18 15:41	**General View**	i	Load JPG	✔
16	02/05/18 15:41	**General View**	i	Load JPG	✔
17	02/05/18 15:41	**General View**	i	Load JPG	✔
18	02/05/18 15:41	**General View**	i	Load JPG	✔
19	02/05/18 15:41	**General View**	i	Load JPG	✔
20	02/05/18 15:41	**General View**	i	Load JPG	✔
21	02/05/18 15:41	**General View**	i	Load JPG	✔
22	02/05/18 15:41	**General View**	i	Load JPG	✔
23	02/05/18 15:41	**General View**	i	Load JPG	✔
24	02/05/18 15:41	**General View**	i	Load JPG	✔
25	02/05/18 15:41	**General View**	i	Load JPG	✔
26	02/05/18 15:41	**General View**	i	Load JPG	✔
27	02/05/18 15:41	**General View**	i	Load JPG	✔
28	02/05/18 15:41	**General View**	i	Load JPG	✔
29	02/05/18 15:41	**General View**	i	Load JPG	✔
30	02/05/18 15:41	**General View**	i	Load JPG	✔
31	02/05/18 15:41	**General View**	i	Load JPG	✔
32	02/05/18 15:41	**General View**	i	Load JPG	✔

Assessment Reports

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
33	02/05/18 15:41	**General View**		Load JPG	
34	02/05/18 15:41	**General View**		Load JPG	
35	02/05/18 15:41	**General View**		Load JPG	
36	02/05/18 15:41	**General View**		Load JPG	
37	02/05/18 15:41	**General View**		Load JPG	
38	02/05/18 15:41	**General View**		Load JPG	
39	16/07/18 20:04	**Reinspection Photo**		Load JPG	
40	16/07/18 20:04	**Reinspection Photo**		Load JPG	
41	16/07/18 20:04	**Reinspection Photo**		Load JPG	
42	16/07/18 20:04	**Reinspection Photo**		Load JPG	
43	16/07/18 20:04	**Reinspection Photo**		Load JPG	
44	16/07/18 20:04	**Reinspection Photo**		Load JPG	
45	16/07/18 20:04	**Reinspection Photo**		Load JPG	
46	16/07/18 20:04	**Reinspection Photo**		Load JPG	
47	16/07/18 20:04	**Reinspection Photo**		Load JPG	
48	16/07/18 20:04	**Reinspection Photo**		Load JPG	
49	16/07/18 20:04	**Reinspection Photo**		Load JPG	
50	16/07/18 20:04	**Reinspection Photo**		Load JPG	
51	16/07/18 20:04	**Reinspection Photo**		Load JPG	
52	16/07/18 20:04	**Reinspection Photo**		Load JPG	
53	16/07/18 20:04	**Reinspection Photo**		Load JPG	
54	16/07/18 20:04	**Reinspection Photo**		Load JPG	
55	16/07/18 20:04	**Reinspection Photo**		Load JPG	
56	16/07/18 20:04	**Reinspection Photo**		Load JPG	
57	16/07/18 20:04	**Reinspection Photo**		Load JPG	
58	16/07/18 20:04	**Reinspection Photo**		Load JPG	
59	16/07/18 20:04	**Reinspection Photo**		Load JPG	
60	16/07/18 20:04	**Reinspection Photo**		Load JPG	
61	16/07/18 20:04	**Reinspection Photo**		Load JPG	
62	16/07/18 20:04	**Reinspection Photo**		Load JPG	
63	16/07/18 20:04	**Reinspection Photo**		Load JPG	
64	16/07/18 20:04	**Reinspection Photo**		Load JPG	
65	16/07/18 20:04	**Reinspection Photo**		Load JPG	
66	16/07/18 20:04	**Reinspection Photo**		Load JPG	
67	16/07/18 20:04	**Reinspection Photo**		Load JPG	
68	16/07/18 20:04	**Reinspection Photo**		Load JPG	
69	16/07/18 20:04	**Reinspection Photo**		Load JPG	
70	16/07/18 20:04	**Reinspection Photo**		Load JPG	
71	16/07/18 20:04	**Reinspection Photo**		Load JPG	
72	16/07/18 20:04	**Reinspection Photo**		Load JPG	
73	16/07/18 20:04	**Reinspection Photo**		Load JPG	
74	16/07/18 20:04	**Reinspection Photo**		Load JPG	
75	16/07/18 20:04	**Reinspection Photo**		Load JPG	
76	16/07/18 20:04	**Reinspection Photo**		Load JPG	
77	16/07/18 20:04	**Reinspection Photo**		Load JPG	
78	16/07/18 20:04	**Reinspection Photo**		Load JPG	
79	16/07/18 20:04	**Reinspection Photo**		Load JPG	
80	16/07/18 20:04	**Reinspection Photo**		Load JPG	

Assessment Reports 1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
81	16/07/18 20:04	**Reinspection Photo**		Load JPG	
82	16/07/18 20:04	**Reinspection Photo**		Load JPG	
83	16/07/18 20:04	**Reinspection Photo**		Load JPG	
84	16/07/18 20:04	**Reinspection Photo**		Load JPG	
85	16/07/18 20:04	**Reinspection Photo**		Load JPG	
86	16/07/18 20:04	**Reinspection Photo**		Load JPG	

Documentation 1 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	30/04/18 08:58	**Driver's Driving License**		Load PDF	
2	30/04/18 08:58	**Driver's Passport**		Load PDF	
3	02/05/18 10:35	**ESTIMATE - MARKED**		Load PDF	
4	20/07/18 09:45	**ESTIMATE MARKED**		Load PDF	
5	20/07/18 09:55	**SUPPLEMENTARY**		Load PDF	
6	03/12/18 16:08	**WORKSHOP INVOICE**		Load PDF	
7	03/12/18 16:08	**DISCHARGE VOUCHER**		Load PDF	

Linked Accident Report Documents

View View in Browser

Assessment Reports 1 per page

No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	26/04/18 09:46	**Accident Statement**		Load HTM	

Photos/Images 3 per page

No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	26/04/18 09:16	**Accident Photo**		Load JPG	
2	26/04/18 09:16	**Accident Photo**		Load JPG	
3	26/04/18 09:16	**Accident Photo**		Load JPG	
4	26/04/18 09:16	**Accident Photo**		Load JPG	
5	26/04/18 09:16	**Accident Photo**		Load JPG	
6	26/04/18 09:16	**Accident Photo**		Load JPG	
7	26/04/18 09:16	**Accident Photo**		Load JPG	
8	26/04/18 09:16	**Accident Photo**		Load JPG	
9	26/04/18 09:16	**Accident Photo**		Load JPG	
10	26/04/18 09:16	**Accident Photo**		Load JPG	

Documentation 1 per page

No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	26/04/18 09:33	**Sketch Plan**		Load JPG	
2	26/04/18 09:33	**Sketch Plan #2**		Load JPG	

Documents Checklist

Reset Save Print

DOCUMENTS CHECKLIST

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18007720/ASBS2
Date: 03/12/2018

REFERENCE

Insured/Claimant: PREMIUM AUTOMOBILES PTE LTD
Policy No: 0999994629
Date of Loss: 25/04/2018
Nature of Claim: OD
Claim No: 1909359392SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLJ465Y**
Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A)
Reg. Date: 25/11/2016 (Man. Year: 2016)
Colour: Silver
Engine Capacity: 1395 cc
Market Value/New Car Price: S$135,000.00
Sum Insured (S$): **Market Value/New Car Price**

Engine No: CVN017657
Chassis No: WAUZZZF43HA024629
Odometer: 20148 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good
Steering (Serviceable): Yes
Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes
Engine Modification: No
Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16
Front Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm

Rear Tyre Size: 205/60R16
Rear Left Side: Bridgestone 6 mm
Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,553.20	17,257.64	6,295.56	26.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,252.00	4,152.00	3,100.00	42.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S$)	**30,805.20**	**21,409.64**	**9,395.56**	**30.50**
+ GST 7.00/7.00% (S$)	2,156.36	1,498.67	657.69	30.50
Nett Amount (S$)	**32,961.56**	**22,908.31**	**10,053.25**	**30.50**

INSPECTION

Date of Assignment: 26/04/2018
Date Inspected: 26/04/2018
Estimated Period of Repair: 6.0 days

Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Adjuster: ADRIAN LING
Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,849.00 FS	*1,479.20 FS
2	2		*FRONT BUMPER SECURING STRIP	Damaged	60.00 FS	*47.84 FS
3	1		*FRONT BUMPER GRILLE - CENTRE	Not Necessary	171.00 FS	*- FS
4	1		*RADIATOR GRILLE	Cracked	972.00 FS	*777.20 FS
5	1		*FOAM FILLER PIECE	Cracked	107.00 FS	*85.20 FS
6	2		*FRONT BUMPER SUPPORT - LH/RH	Damaged	48.00 FS	*38.24 FS
7	1		*FRONT BUMPER LOCK CARRIER BRACKET	Cracked	118.00 FS	*94.00 FS
8	1		*FRONT BUMPER COVER	Deformed	109.00 FS	*87.20 FS
9	1		*RELEASE LEVER	Not Necessary	12.00 FS	*- FS
10	1		*BOWDEN CABLE	Damaged	50.00 FS	*40.00 FS
11	1		*SIGN CAUTION	Necessary	12.00 FS	*9.28 FS
12	2		*LED HEADLIGHT - LH/RH	O/s Chipped / N/s Cracked	13,946.00 FS	*11,156.80 FS
13	1		*BONNET	Distorted	2,163.00 FS	*1,730.40 FS
14	1		*BONNET ATTACHMENT PARTS	Not Necessary	105.00 FS	*- FS
15	1		*IMPACT PROTECTION - LH	Necessary	24.00 FS	*18.88 FS
16	1		*IMPACT PROTECTION - RH	Necessary	24.00 FS	*18.88 FS
17	1		*IMPACT PROTECTION - CENTER	Necessary	24.00 FS	*18.88 FS
18	2		*BONNET STRIKER - LH/RH	Damaged	88.00 FS	*69.92 FS
19	2		*BONNET LID LOCK	Not Necessary	376.00 FS	*- FS
20	1		*BONNET LOCK CARRIER	Not Necessary	891.00 FS	*- FS
21	2		*AIR GUIDE - LH/RH	Not Necessary	46.00 FS	*- FS
22	2		*RADIATOR INNER DUCT - LH/RH	Deformed	20.00 FS	*15.36 FS
23	1		*AIR GUIDE - UPPER	Not Necessary	14.00 FS	*- FS
24	1		*A/C CONDENSER WITH FLUID RESERVOIR	Dented	540.00 FS	*432.00 FS
25	1		*COOLER FOR COOLANT	Dented	585.00 FS	*468.00 FS
26	4		*RUBBER BUSH - LOWER	Not Necessary	38.00 FS	*- FS
27	4		*COOLANT CONCENTRATE	Not Necessary	133.00 FS	*- FS
28	1		*FRONT NO. PLATE	Necessary	25.00 FS	*25.00 FS
29	1		*SUNDRIES	Necessary	400.00 FS	*42.16 FS
30	1		*FRONT REINFORCEMENT BEAM	Bent	561.60 FS	*561.60 FS
31	2		*BONNET STOP BUFFER	Necessary	13.28 FS	*13.28 FS
32	3		*BONNET BUNGS	Necessary	28.32 FS	*28.32 FS
				Total Parts (S$)	**23,553.20**	**17,257.64**

F=Franchise part, S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
	Labour Items			
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	New	360.00	360.00
2	TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, CHARGED AIR COOLER, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM / REGAS AND TO PRESSURE COOLING SYSTEM.	New	1,000.00	1,000.00
3	TO DISMANTLE FRONT BUMPER, BOTH HEADLIGHTS AND BONNET. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW DAMAGED PANELS. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	4,200.00	1,500.00
4	TO RESPRAY FRONT BUMPER AND BONNET.	New	1,500.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
		Gross Labour Cost (S$)	**7,252.00**	**4,152.00**

Report was unsubmitted during this print-out.

< END OF ESTIMATES >