CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 8148E **DATE : 27.04.2018**

MAKE : **TEL : 6542 5119**

MODEL : HYUNDAI i40 **FAX : 6542 6039** INDIA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Bumper Cover Dented			$ 562.30	
	Front Bumper Grille (RH) NN			$ 40.30	×
	Front Bumper Bracket Top (RH) S/C			$ 22.40	×
	Front Bumper Bracket (RH) S/C			$ 24.60	×
	Front Bumper Retainer Mounting broken			$ 9.20	
	Headlamp Support Panel Assy broken			$ 1,067.50	
	Headlamp (RH) moniting broken			$ 1,388.00	
	Front Fender (RH) Dented			$ 619.00	
	Front Fender Apron Panel (RH) Dented			$ 1,575.50	×
	Front Fender Shield (RH) deformed			$ 169.80	
	Front Wheel Rim (RH) 2 bt			$ 351.90	2
	Front Wheel Hub Cap (RH) Crt			$ 150.70	
	Front Wheel Bearing 2 Dam			$ 258.50	2
	Front Shock Absorber (Assy) (RH) 2 distorted			$ 342.20	2
	Front Shock Absorber Mounting (RH) NN			$ 75.10	×
	Front Drive Shaft (RH) distorted			$ 1,069.55	×
	Rack & Pinion Assy distorted			$ 2,184.00	×
	STG Tie End NN			$ 69.50	×
	Front Suspension Lower Arm (LH) 2 distorted			$ 715.10	2
	Knuckle Arm (RH) 2 distorted			$ 582.95	2
	SUB TOTAL			**$ 11,278.10**	
	LESS 20%			**$ 2,255.62**	
	DISCOUNTED TOTAL			**$ 9,022.48**	
	Front Tyre (RH) S/C			**$ 216.00**	**Nett** ×
	Labour Charge				
	Panel Beating			$ ~~1,500.00~~	800/-
	Spray Painting Charge 30/04/2018 @ 1330hrs			$ ~~600.00~~	500/-
	Wiring Charge Not done			$ ~~50.00~~	30/-
	Tuff Kote 4/5mm			$ ~~50.00~~	30/-
	Towing Charge			$ 60.00	NN
	Remove/Refix Undercarriage (FRT) Pya	6 days		$ ~~400.00~~	200/-
	FRT Wheel Alignment LKK done			$ ~~120.00~~	60/-
	Remove/Refix Aircon & Refill Gas			$ ~~150.00~~	80/-
	TOTAL LABOUR			**$ 2,930.00**	
	ESTIMATE TOTAL			**$ 12,168.48**	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.