LIM TAN MOTOR

ESTIMATE TO REPAIR

SURVEYOR NAME	:
DATE OF SURVEY	: 18 - 05 - 2018
TIME OF SURVEY	: 3 . 35pm

VEHICLE NO. : PA 9421 P
MAKE : NISSAN
MODEL : URVAN MICROBUS 3.0 4DR 5MT ABS AIRBAG
YEAR : 2010
CHASSIS NO : JN1TG4E25Z0786093

DATE : 27-Apr-18
DATE OF ACCIDENT : 25-Apr-18
THIRD PARTY REF : GBF 9018 K / AXA

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper Cnt	Nett			$ 632.70
1 pc	N/S Rear Bumper Retainer Brk	Nett			$ 18.50
1 pc	N/S Taillamp broken	Nett			$ 233.50
1 pc	N/S Rear Fender Dented	Nett			$ 2,010.00
1 pc	N/S Rear Sliding Door Rail bt	Nett			$ 455.00
					$ 3,349.70
	Less 10%				$ 334.97
					$ 3,014.73
1 tube	N/S Rear Frnder Glass Sealant Nkc	S.Nett			$ 40/- ~~80.00~~
1 set	Rear Company Logo Sticker Nkc	S.Nett			$ ~~480.00~~ 300/-
	To putty & spray painting.				$ ~~600.00~~ 500/-
	To remove and refix N/S rear fender glass.				$ ~~200.00~~ 120/-
	To remove and refix cushion seat, trining and roof lining.				$ ~~400.00~~ 120/-
	To anti-rust.				$ 40/- ~~80.00~~
	Labour Charges.				$ 600/- ~~900.00~~
	18/05/2018 @ 1545hr Not Antirust L/Smnl 5 days LKK Auto		Photo after repair		
1G-RA/-	TOTAL				$ 5,754.73

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Lim Tan Motor Pte Ltd
Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
Tel:65-64520893 Fax:65-64589127 Website : www.LTM.sg
Co.Reg No.199307277D GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd