新福德車廠私人有限公司 ADRIAN

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883
Email: admin@nhtmotor.com Website: www.nhtmotor.com
Tel: 6747 9241 Fax: 6741 7276
UEN: 201718370K

KHAN ATIQUR RAHMAN
Blk 1 Kaki Bukit Ave 6
 # 01-43
Singapore 417883

07/05/2018

Accident date: 05/05/2018
Estimated repair cost for vehicle no: WWH9682 TOYOTA HILUX

S/n	Qty	Items	U/price	Amount
1	1	Front Bonnet Buckled		$980.20 ✓
2	1	Front Bonnet Lock Damaged		$150.50 ✓
3	2	Front Bonnet Hinges Not New	$105.00	$210.00 ✗
4	1	Front Bonnet Toyota Cover Cracked		$265.00 ✓
5	1	Front Bonnet Insulator Not New		$288.50 ✗
6	15	Front Bonnet Insulator Clips New	$3.00	~~$45.00~~ 30
7	1	Front Bonnet Inner Rubber Not New		$65.50 ✗
8	2	Front Head Lamp LH cracked	$456.70	~~$913.40~~ 456.70
9	2	Front Head Lamp Lower Bracket LH Damaged	$96.80	~~$193.60~~ 96.80
10	1	Front Grille Cracked		$351.60 ✓
11	1	Front Grille Emblem Logo New		$71.60 ✓
12	1	Front Grille Top Rubber Not New		$105.00 ✗
13	1	Front Grille Outer Chrome cracked		$116.60 ✓
14	1	Front Bumper Detached		$595.70 ✓
15	2	Front Bumper Side Retainer New	$44.20	$88.40 ✓
16	1	Front Bumper Number Plate Cracked		$50.00 ✓
17	1	Front Bumper Center Garnish cracked		$189.20 ✓
18	1	Front Bumper Fog Lamp L/H Cracked		$385.80 ✓
19	1	Front Bumper Fog Lamp L/H Cover Detached		$61.70 ✓
20	1	Front Bumper Side Cover L/H Not New		$74.20 ✗
21	1	Front Bumper Lower Reinforcement Bent		$373.20 ✓
22	2	Front Bumper Lower Reinforcement Bracket Bent	$75.40	$150.80 ✓
23	10	Front Bumper Clips New	$3.00	$30.00 ✓
24	1	Front Support Panel Assy Buckled		$645.00 ✓
25	2	Front Support Panel Side Air-Duct Cover Detached	$35.00	$70.00 ✓
26	2	Front Horn Not New	$48.00	$96.00 ✗
27	1	Front Air-Con Condenser Bent		$1,145.00 ✓
28	1	Front Radiator Bent		$2,108.00 ✓
29	1	Front L/H Fender Buckled		$625.40 ✓

30	1	Front L/H Fender Protector Cover Dented		$145.50
31	1	Front L/H Fender Side Mirror Assy cracked		$259.40
32	1	Front L/H Fender Cowling		$185.00
33	10	Front L/H Fender Cowling Clips	$3.00	$30.00
34	1	Front Wiper Tank		$124.10
35	1	Front Wiper Tank Motor		$85.10
36	1	Rear Tailgate Distorted		$1,114.70
37	2	Rear Tailgate Hinges Bent	$54.80	$109.60
38	1	Rear Tailgate Toyota Logo		$68.20
39	1	Rear Tailgate Hilux Logo		$67.40
40	1	Rear Tailgate C Logo		$28.60
41	1	Rear Tailgate Center Lamp cracked		$124.90
42	1	Rear Tailgate Outer Handle Dented		$58.80
43	1	Rear Tailgate Outer Handle Inner Lock Jammed		$78.40
44	1	Rear Tailgate Inner Cover Deformed		$385.00
45	2	Rear Tailgate Side Lock	$275.60	$551.20
46	2	Rear Tail Lamp LH cracked RH cut	$354.00	$708.00
47	2	Rear Tail Lamp Panel Repair	$241.00	$482.00
48	1	Rear Tailgate Lower Member Dented		$777.20
49	1	Rear L/H Fender Repair		$2,490.00
50	1	Rear Bumper Distorted		$974.00
51	1	Rear Bumper Top Rubber Cover Dislodged		$332.80
52	1	Rear Bumper Number Plate Cracked		$60.00
53	2	Rear Bumper Number Plate Lamp cracked	$69.60	$139.20
54	1	Rear Bumper Number Plate Garnish Dislodged		$58.50
55	1	Rear Bumper Number Plate Cover		$39.40
56	2	Rear Bumper Bracket - Bent	$.140	$280.00
57	1	Rear Floor Panel Repair		$2,985.00
58	1	Rear Floor Panel Cover NEW		$554.00
59	1	Rear Spare Tyre Lock NEW		$195.00
60	1	Rear Exhaust NEW		$851.20
61	1	Rear Center Exhaust NEW		$785.00
62	2	Rear Fender Commonrail Turbo Sticker (set) NEW	$30.00	$60.00
63	2	Rear Fender Lower Sticker (set) NEW	$20.00	$40.00

14906-80

1118010

Subtotal :- **$25,672.10**

Labour charges

To remove & refit front air-con condenser, radiator, fan motor & $380.00 120

top up gas

To remove & refit reverse sensor		$100.00 X
To remove & refit rear & center exhaust		$380.00 X
To remove & refit floor panel & tailgate cover		~~$1,500.00~~ X 150
To check wiring	5090	~~$100.00~~ 60
Tuff kote		~~$150.00~~ 100
Towing Fees		~~$100.00~~ 60
Panel beating		~~$3,800.00~~ 2400
Spray painting		~~$2,800.00~~ 2700
	Subtotal :-	**$9,310.00**
	Total:-	**$34,982.10**

Total ~~16345.05~~ 16270.10

2/s 13K

110 c/s

13K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: