LIM TAN MOTOR

ESTIMATE TO REPAIR

SURVEYOR NAME	:
DATE OF SURVEY	: 22. 05. 2018
TIME OF SURVEY	: 11. 25am

VEHICLE NO. : SLP 4165 E
MAKE : HONDA
MODEL : CIVIC 1.8L A
YEAR : 2008
CHASSIS NO : JHMFD16308S219694

DATE : 21-May-18
DATE OF ACCIDENT : 20-May-18
THIRD PARTY REF : SLR 7937 E / AIG

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper				$ 638.00
2 pcs	Rear Bumper Bracket		$ 13.90		$ 27.80
2 pcs	Rear Bumper Retainer		$ 14.90		$ 29.80
1 pc	Rear End Panel				$ 300.80
1 pc	Rear End Panel Garnish				$ 60.80
1 pc	Rear Boot Lid				$ 610.70
1 pc	Rear Boot Lock				$ 194.50
1 pc	Rear Boot Rubber				$ 97.60
1 pc	Rear Boot Centre Emblem				$ 25.70
1 pc	Rear Boot CIVIC Emblem				$ 29.10
1 pc	Rear Boot 1.8 I-VTEC Emblem				$ 34.10
					$ 2,048.90
	Less 20%				$ 409.78
					$ 1,639.12
1 set	Rear Bumper Sensor	S.Nett			$ 200.00
	To putty & spray painting.				$ 600 ~~800.00~~
	To check rear wiring and water leakage.				$ 30.00
	To anti-rust.				$ 40 ~~60.00~~
	Labour Charges.				$ 600 ~~680.00~~
TG-RA/-	**TOTAL**				**$ 3,409.12**

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Resue
Hp 90010068
6 days
4S
22/05/18 @1130
Resurvey after repair

Lim Tan Motor Pte Ltd
Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
Tel:65-64520893 Fax.65-64589127 Website : www.LTM.sg
Co.Reg No.199307277D GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd