CHUNNI MOTOR WORK PTE LTD

To Survey by (LKK)

REPAIR ESTIMATE*

VEHICLE NO : SHC 8961M

MAKE :

MODEL : HYUNDAI i40

DATE : 31.05.2018

TEL : 6542 5119

FAX : 6542 6039 INDIA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Bumper Cover distorted			$ 1,052.20	
	Front Bumper Bracket (LH) SVC			$ 24.60	X
	Headlamp Support Panel Assy ? broken			$ 1,067.50	?
	Headlamp (LH) monthly crack			$ 1,388.00	? photo
	Front Fender (LH) Dented			$ 619.00	
	Front Fender Apron Panel (LH) NA			$ 1,575.50	X
	Front Fender Shield (LH) ? SVC			$ 169.80	? X
	Front Wheel Rim (LH) ? bent			$ 351.90	?
	Front Wheel Hub Cap (LH) cut			$ 150.70	
	Front Wheel Bearing ? Dam			$ 258.50	?
	Front Shock Absorber (Assy) (LH) ? distorted			$ 342.20	?
	Front Shock Absorber Mounting (LH) NA			$ 75.10	X
	STG Tie End ? distorted			$ 69.50	?
	Front Suspension Lower Arm (LH) ? distorted			$ 715.10	?
	Knuckle Arm (LH) ? distorted			$ 582.95	?
	ABS Sensor NA			$ 261.50	X
	Wiring-Engine ~~Not~~ broken			$ 3,326.00	?
	SUB TOTAL			**$ 12,030.05**	
	LESS 20%			$ 2,406.01	
	DISCOUNTED TOTAL			**$ 9,624.04**	
	Front Tyre (LH) SVC			**$ 216.00**	**Nett** X
	Labour Charge 05/06 pure e 1115 km				
	Panel Beating			$ ~~1,000.00~~	500/-
	Spray Painting Charge Not done			$ ~~650.00~~	400/-
	Wiring Charge			$ ~~50.00~~	30/-
	Tuff Kote 2/5mm			$ ~~50.00~~	20/-
	Towing Charge			$ 50.00	NA
	Remove/Refix Undercarriage (FRT)	4 days.		$ ~~180.00~~	? 150/-
	FRT Wheel Alignment			$ ~~100.00~~	60/-
	Remove/Refix Dashboard 2 KK done			$ ~~180.00~~	~~NA~~ 150/-
	TOTAL LABOUR			**$ 2,260.00**	
	ESTIMATE TOTAL			**$ 12,100.04**	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.