TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS

EUROKARS GROUP

AXA INSURANCE PTE LTD		**NAME :**	**Ms Wong Mei-Yi Vivian**	**WIP :**	19044
8 SHENTON WAY		**ADDRESS :**	Blk 9 Simei Street 4	**EXCESS :**	
#24-01 AXA TOWER			#11-03	**DATE:**	5-Jun-18
SINGAPORE 068811			Singapore 529865		
ATTN. :	MOTOR CLAIMS	**TEL :**			
FAX :					

VEH NO :	**SLD8507P**	**DATE IN :**		**CONTACT PERSON :**	Vion 63957877
CHASSIS NO :	MM6DL2SAAGW192154	**MILEAGE :**		**TYPE OF CLAIM :**	Third Party Claim
MODEL :	MAZDA2	**DATE REG.:**	29-Jun-16	**POLICY NO. :**	

NATURE OF WORKS

Parts Description

NO		QTY			REVISED	PRICES
1	REAR BUMPER	1	MDB7A-50-221BBB	RD/RE	—	$ 909.00
2	REFLECTOR LHS	1	MD350-51-5L0E	LH	X	$ 50.40
3	REFLECTOR RHS	1	MD350-51-5M0E	RH	X	$ 50.40
4	RETAINER LHS	1	MDB7A-50-2J1	LH	X	$ 21.70
5	RETAINER RHS	1	MDB7A-50-2H1	RH	X	$ 21.70
6	BRACKET LHS, REAR BUMPER	1	MDB7H-50-251	LH	X	$ 23.20
7	BRACKET CENTER, REAR BUMPER	1	MKD53-50-251	LH	X	$ 5.10
8	STAY BRACKET,REAR BUMPER	2	MDB7A-50-271	RH	X	$ 24.60
9	FASTENER, REAR BUMPER	7	MB45A-56-146A	NS	—	$ 19.60
10	GROMMET, REAR BUMPER	4	MBHN1-50-0Z1A	NS	—	$ 10.00
11	GROMMET, REAR BUMPER	1	M9991-00-501	NS	—	$ 2.80
12	TAPE,PROTECTOR, REVERSE SENSOR	3	MGS1D-50-EM1A	NS	—	$ 24.30
13	BOOTLID	1	MDAY0-52-61X	LH	X	$ 820.70
14	WEATHERSTRIP, BOOTLID	1	MDB7A-56-951	LH	X	$ 107.50
15	LOCK, BOOTLID	1	MDB7A-56-820A	RH	X	$ 181.80
16	ORNAMENT, MAZDA2	1	MDB7G-51-721	NS	—	$ 55.10
17	MASCOT, REAR	1	MDB7G-51-730	NS	—	$ 55.40
18	ORNAMENT, SKYACTIVE	1	MDB7G-51-771	NS	—	$ 64.30
19	REAR END PANEL	1	MDBYA-70-75Z	NS	X	$ 624.70
20	**ANTENNA, SMART KEYLESS**	**1**	**MKD47-67-6NXA**	BN	—	**$ 105.80**
21	**CLIP, ANTENNA**	**1**	**MKD45-67-6NYA**	EM	—	**$ 2.50**
22	**CORD, SHORT ANTENNA**	**1**	**MK1Y9-67-SH3**	RH	X	**$ 17.30**
23	**GASKET(LHS),TAILLAMP**	**1**	**MDB7A-51-163**	NS	—	**$ 31.90**
24	**GASKET(RHS),TAILLAMP**	**1**	**MDB7A-51-153**	NS	—	**$ 31.90**
25	**GASKET(LHS), BOOTLID**	**1**	**MDB7A-51-3J8**	NS	—	**$ 46.20**
26	**GASKET(RHS), BOOTLID**	**1**	**MDB7A-51-3H8**	NS	—	**$ 46.20**
			TOTAL PARTS			$ 3,354.10
			LESS 10%			$ 335.41
			TOTAL PARTS COST			**$ 3,018.69**

		Labour Description		
1		TO REPLACE REAR BUMPER, REAR END PANEL AND BOOT LID.REPAIR ALL AREAS AFFECTED BY THE ACCIDENT. 660 2.5	1650	$ 2,640.00
2		TO RESPRAY REAR BUMPER, REAR END PANEL, BOOT LID.	1890	$ 2,520.00
3	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.	330	$ 660.00
4	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA. 11	X	$ 660.00
5	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING 11	X	$ 350.00
6	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION. 11	X	$ 250.00
7	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION. 11	X	$ 660.00
8	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120	$ 250.00
9	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	150	$ 350.00
10	MZ-BR-SUNDRI	SUNDRIES. ner 30	NETT	$ 100.00

TOTAL LABOUR	$ -	**$ 8,440.00**
TOTAL PARTS	$ -	**$ 3,018.69**
TOTAL	$ -	**$ 11,458.69**
LESS EXCESS	$ -	$ -
TOTAL AFTER EXCESS	$ -	
GST 7%	$ -	$ -
GRAND TOTAL	$ -	$ -

not Authorised
Dhanmarcus
2/7/18
Tel: 62863561
Take photo before painting.
6 Ly.

REMARKS:
*THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING,YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF $400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.*

TRANS EUROKARS PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorised Signature

Acknowledged by Repairer

Signature:

Date: