LIM TAN MOTOR

ESTIMATE TO REPAIR

SURVEYOR NAME	:
DATE OF SURVEY	: 13 JUL 2018
TIME OF SURVEY	:

VEHICLE NO. : SKB 6555 K
MAKE : PORSCHE
MODEL : 981 BOXSTER PDK WO SES
YEAR : 2014
CHASSIS NO : WP0ZZZ98ZDK103454

DATE : 5-Jun-18
DATE OF ACCIDENT : 23-May-18
THIRD PARTY REF : SLL6616D / AXA

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper			Bu/lcm	$ 1,920.00
1 pc	Rear Bumper Lower Spoiler			Spr	$ 355.00
2 pcs	Rear Bumper Sensor		$ 130.00	Sn	$ 260.00
					$ 2,535.00
	Less 10%				$ 253.50
					$ 2,281.50
					3201
	To putty & spray painting.				$ 350.00
	To check rear wiring and replace sensor.			Sa	$ 150.00
					250
	Labour Charges.				$ 300.00
	Not authorised Resurvey B4 paint				
TG-RA/-	**TOTAL**				**$ 3,081.50**

Lim Tan Motor Pte Ltd
Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
Tel:65-64520893 Fax:65-64589127 Website : www.LTM.sg
Co.Reg No.199307277D GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: