COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

AIG / LKK
REAR

F2

VEHICLE NO : SHA 7854U **DATE 6/6/2018 10:26**

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Licence Lamp Lower Garnish X repair			$ 380.80	
	Rear Bumper — Retend			$ 603.60	
	Rear Bumper Reinforcement X see			$ 504.35	
	Rear Bumper Clips 10 pcs — ne			$ 22.00	
	Rear Bumper Sponge X see			$ 143.40	
	Rear Bumper Under Cover X see			$ 225.00	
	SUB TOTAL			**$ 1,879.15**	
	LESS 20%			$ 375.83	
	DISCOUNTED TOTAL			**$ 1,503.32**	
	Rear No.Plate — ok			$ 25.00	**Nett**
	Rear Bumper Reverse Sensor X ok			$ 135.70	**Nett**
	Rear Fender Advertisement Logo (LH/RH) — ne		$ 100.00	$ 200.00	**Nett**
				$ 360.70	
	Labour Charge				
	Panel Beating (Repair)			$ ~~350.00~~ 200	
	Spray Painting Charge			$ ~~250.00~~ 200	
	Wiring Charge			$ ~~30.00~~ X ok	
	Remove/Refix Reverse Sensor			$ ~~120.00~~ X ok	
	Rear Wheel Alignment			$ ~~80.00~~ X ok	
	TOTAL LABOUR			**$ 830.00**	
	ESTIMATE TOTAL			**$ 2,694.02**	

Kahin 1(1(1(
6/6/18 1400 hrs.
2 Days
P/P
Before Paint pls

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.