COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 7285Z **DATE 11/6/2018 10:00**

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Fender (RH) X Repair			$ 2,020.10	
	Rear Fender Inner Lining (RH) X			$ 164.40	
	Rear Windscreen Moulding X			$ 60.00	
	Rear Wheel Hub Cap,RH —			$ 150.70	
	Rear Bumper X Repair				
	SUB TOTAL			**$ 2,395.20**	
	LESS 20%			$ 479.04	
	DISCOUNTED TOTAL			**$ 1,916.16**	
	Rear Bumper Rubber Mat X			$ 50.00	**Nett**
	Rear Windscreen Sealant X			$ 46.00	**Nett**
				$ 96.00	
	Labour Charge			200	
	Panel Beating			$ ~~850.00~~	
	Spray Painting Charge			$ ~~500.00~~ 400	
	Wiring Charge			$ ~~50.00~~ X	
	Tuff Kote			$ ~~50.00~~ X	
	Remove/Refix Cushion & Upholstery Rear			$ ~~150.00~~ X	
	Remove/Refix Rear Windscreen Glass			$ ~~120.00~~ X	
	Remove/Refix Reverse Sensor			$ ~~120.00~~ X	
	Rear Wheel Alignment			$ ~~80.00~~ X	
	TOTAL LABOUR			**$ 1,920.00**	
	ESTIMATE TOTAL			**$ 3,932.16**	

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Kahi 1CCK
11/6/18 1200 hr.
2 Days
4s After Repair pt.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.