22/03/2002

ASG. REC. BY: | REF: CS/III8012548/Urbn2 | Special Instruction:

Surveyor : Marcus.

ASSIGNMENT (Office)

From (Person): Gabriel Wee of III Date/Time: 07072018 11:27am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SCU 1817H Insured: SHD 4774H

at Workshop m/s Yi Heng Tel: 6509 0052.

of Blk 1 Kaki Bukit Ave 6 #02-19

Policy No: Claim No:

Sum Insured: Excess:

Make of Veh: D.O.A. 06072018
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10072018 9:57am Person Contacted: Wan Ang Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate	
	SCU 1817H - CCQ/AZLH11017JLT/Nsmtk2	DOA: 300811
	SHD 4774H - N8/INC16000619/Highsm2	DOA: 080416

(08/11/13) wef

ASS. REC. BY: Marcus.

REF: CH

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SCU1817H

at Workshop m/s Yihing

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: S/L.

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: ✓ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 30/4/2019

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SCU1817H Yr Regn: 10/91

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or CAR

Make: Toyota corolla c.c 1587

Colour S.Iver A/C: Insured / Std / NI / NA

Sp.Reading 459447 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: AE101300482Y

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi : NIL / S/Rim / STD A/Rim or _____

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	6/7/18	D.O.I.	10/7/18

Survey held at _____

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
23/7/18	LYA311 9mth plug 2011 4689 L/S @ 3500 Confirmed with AH buy. Rcd: $998.31, 63%.

RECEIVED 31 JUL 2018

Date/Time, File Pass to?

1) typist

Date/Time, File Return to?

2) _____

☐ : Preli. Report

☒ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp ($ _____)

☐ : Interview ($ _____)

☐ : Tech. Invs ($ _____)

☐ : Weekend ($ _____)

Report Format : TP

Lump Sum / ~~I.B.~~: ($ 3500)

Survey Fee:	
Transportation:	
___S + RS___SI	250
Photos	10
Others	
TOTAL	260

Catherine Chong (LKK Auto)

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Sent: Tuesday, 10 July, 2018 9:47 AM
To: assignments
Subject: FW: PRE-REPAIR INSPECTION FOR VEHICLE NO. SCU1817H (Accident involving SCU1817H and SHD4774H on 06.07.2018)
Attachments: 4632_001.pdf; shc4774h_20180709111434.pdf

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Motor Claim - III [mailto:motorclaim@iii.com.sg]
Sent: Monday, 9 July 2018 4:00 PM
To: SUR <sur@lkkauto.com>
Subject: FW: PRE-REPAIR INSPECTION FOR VEHICLE NO. SCU1817H (Accident involving SCU1817H and SHD4774H on 06.07.2018)

From: Motor Claim - III
Sent: Monday, 9 July, 2018 11:27 AM
To: Anna Tan <annatan@visionlawllc.com>; 'ct-admin@visionlawllc.com' <ct-admin@visionlawllc.com>
Cc: Sundari Nagarajan - III <sundari@iii.com.sg>
Subject: FW: PRE-REPAIR INSPECTION FOR VEHICLE NO. SCU1817H (Accident involving SCU1817H and SHD4774H on 06.07.2018)

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SCU1817H and let us have your report urgently.

This claim will be handled by Ms Sundari.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee
Motor Claims Dept.
India International Insurance Pte Ltd
64 Cecil Street | #05 IOB Building | Singapore 049711
Tel: 6347 6100, Ext - 248

From: Motor Claim - III
Sent: 09 July, 2018 8:54 AM
To: 'ct-admin@visionlawllc.com' <ct-admin@visionlawllc.com>; 'Anna Tan' <annatan@visionlawllc.com>
Subject: PRE-REPAIR INSPECTION FOR VEHICLE NO. SCU1817H (Accident involving SCU1817H and SHD4774H on 06.07.2018)

Dear Sir / Mdm,

We acknowledge receipt of your email.

We proprose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee
Motor Claims Dept.
India International Insurance Pte Ltd
64 Cecil Street | #05 IOB Building | Singapore 049711
Tel: 6347 6100, Ext - 248

From: ct-admin@visionlawllc.com [mailto:ct-admin@visionlawllc.com]
Sent: 06 July, 2018 5:10 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Scan Image

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:
This email is intended solely for the person to whom it has been addressed.
It may contain confidential and/or legally privileged information.
If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful.
Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.
Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.
Print this email only if it is absolutely necessary and help in preservation of environment.
India International Insurance Pte Ltd.
Registration No. 198703792-K

VISION LAW LLC

Advocates & Solicitors · Notary Public · Commissioner for Oaths
Agents for Trade Marks
(Incorporated with limited liability)
Company Registration No. 200721148H

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALLI D/O MUNIANDY
SEGA PARAM
ONG BOCK KEE
DIANE ANG KIM NOI
RAVENDRA KRISHNASAMY
TAY HAO RAN
JANICE HAN JIA LIN
TAN YINGXIAN SELWYN

Head Office:
133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413
Branch:
490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

HEAD OFFICE:
TEL : 65342811 (Hunting)
FAX : 65356802 (General)

E-MAIL: annatan@visionlawllc.com

BRANCH
TEL : 63580703
FAX : 63580448(conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE – Please reply to HEAD OFFICE for this matter

OUR REF: AKN-atv-INS-Y44-SCU 1817H-2018 - please reply to: annatan@visionlawllc.com
YOUR REF: ~~SHD 4774 H~~

9 JULY 2017

INDIA INTERNATIONAL INSURANCE PTE LTD
64 Cecil Street
#04/06-00 IOB Building
Singapore 049711
Attn: Motor Claims Department

BY FAX: 6224 4174 &
motorclaim@iii.com.sg

Dear Sirs

NAME OF CLAIMANT: ONG HOCK CHWEE
VEHICLE NUMBER: SCU 1817 H
YOUR INSURED VEHICLE NUMBER: SHD 4774 H
ACCIDENT ALONG KAKI BUKIT ROAD 5 (BEFORE TURNING LEFT TO BEDOK NORTH) ON 6 JULY 2018 AT ABOUT 1120HOURS

We refer to your email dated 9 July 2018 informing that you wish to conduct a pre-repair survey and your List of Surveyors

Our client confirmed appointment of **Adrian, LKK Auto Consultant Pte Ltd** as the Single Joint Expert for this matter.



Please be informed that the said vehicle can be inspected at :

YI HENG MOTOR WORKSHOP
1 KAKI BUKIT AVENUE 6
#02-19 AUTOBAY @ KAKI BUKIT
SINGAPORE 417883
Contact Person: **TEL: 6509 0052 (WAN PING)**

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

(Head Office)
cc. **SCU 1817 H** – By fax 6747-9402 only

FOR SURVEYOR
Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :
(Name & Signature) :

Date & Time of Inspection :

CONFIDENTIALITY
THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATEDABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

SGCARMART.COM
THE ONLY PLACE FOR SMART CAR BUYERS

Toyota Corolla 1.6M (COE till 04/2019)

Price	**$5,000**
Reg date	25-Aug-1992
Manufactured	1992
Mileage	-
Transmission	Manual
Engine Capacity	1,587 cc
Road Tax	$1,104 per year
Features	-
Accessories	-
Description	Port And Polish 4AFE Running 125hp On Dyno-tuned With Unichip, Open Pod CAI, Full Mark 2 Body Kit, Fully Done Up Leather Interior, ICE, Sscus Semi Bucket Seat, Upgraded Front Brake VTTR Mini 6pot, Rear From Drum To Disc. Rota Concave 16inch Rims. Alternator/battery Newly Change, Air Con Full System Change Super Cold. And Many More, View To Believe. Able To Renew For Another 5 To 10 Years.
COE	$3,864
OMV	$16,163
ARF	$24,245
Depreciation	$6,210 / year
No. of owners	More than 6
Type of Vehicle	Mid-Sized Sedan
Availability	**Available**



Seiier Information

Contact Person(s)	Lim Choon Yong
Contact No.	91185174

DIRECT OWNER

Posted on : 10-Jul-2018

Last Updated : 10-Jul-2018

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	2581Z

Vehicle Details

Vehicle No.:	SCU1817H
Vehicle to be Exported:	No
Intended De-registration Date:	10 Jul 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA 1.6A
Primary Colour:	White
Manufacturing Year:	1991
Engine No.:	4A4498600
Chassis No.:	AE1013005824
Maximum Power Output:	-
Open Market Value:	$16,887.00
Original Registration Date:	03 Oct 1991
First Registration Date:	03 Oct 1991
Transfer Count:	5
Actual ARF Paid:	$25,331.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	$0.00

Intended COE Rebate Details

COE Expiry Date:	30 Apr 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	$3,864.00
COE Rebate Amount:	$311.00
Total Rebate Amount:	**$311.00**

The information contained herein is correct as at 10 Jul 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/07/2018 17:24
Date Of Accident	06/07/2018 11:20
Exact Location Of Accident	KAKI BUKIT RD 5 (BEFORE TURNING LEFT TO BEDOK NORT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCU1817H

Insured/Policyholder

Name Of Registered Owner	ONG HOCK CHWEE
NRIC No	S1392581Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90028000
Alternative Phone No	OFFICE-90028000

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5045886945-07
Cover Note Number	

Driver

Name of Driver	ONG HOCK CHWEE
NRIC No	S1392581Z
Date Of Birth	18/07/1959
Occupation	INDOOR
Date Of Driving Pass	28/08/1978
Driving Experience	39 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90028000
Fax Number	
Contact Number	OFFICE-90028000
EMail Address	NOEMAIL

Address	BLK 909 HOUGANG ST 91 #01-94
Postcode	530909
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NG WUQUAN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes,Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes,against whom?	

Circumstances of Accident

ON 06/07/2018 AT ABOUT 11.20AM, I WAS DRIVING MY VEHICLE A WITH MY STAFF ALONG KAKI BUKIT ROAD 5 TOWARDS BEDOK NORTH ROAD AT THE EXTREME LEFT LANE. I CAME TO A STOP WHEN TRAFFIC LIGHT IS ON RED. SUDDENLY, VEHICLE B DID NOT STOP IN TIME AND COLLIDED ONTO MY VEHICLE REAR (MORE TO REAR RH PORTION) THUS MY VEHICLE SURGED FORWARD AFTER THE STOP LINE. I CAME DOWN AND CHECK MY VEHICLE. ONE WAS INJURED AT THAT TIME. THAT'S ALL.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD4774H
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	85106467
Address	
Postcode	
Insurance Company Name	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

   I understand, acknowledge, agree and consent that:

   (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of

   (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

   (ii) investigating the accident and/or my claims;

   (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

   (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

   (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes",

   (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

   (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

   (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

   (e) the information so collected under (d) above may be shared / disclosed:

   (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

   (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time: 6/7/18 4.15 pm

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

YC Heng

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On ~~dd~~ 06/7/2018 at about 11.20am. my vehicle (A) I was driving with my staff along kaki bukit Rd 5 toward Bedok North Rd at the extreme left Lane.

I came to a stop when traffic light is on Red. Suddenly vehicle (B) did not stopped in time and collided to my vehicle rear (more to rear rh) portion, thus my vehicle surged forward after I came down and check my vehicle & the stop line. No one was injured at that time. That's all.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 6/7/2018 4.15pm

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6
#02-19, SINGAPORE 417883
TEL: 6 5090052 FAX: 6 7479402

10/07/2018

OUR REF NO. SCU 1817 H

ONG HOCK CHWEE
BLK 909 HOUGANG ST 91,
#01-94
SINGAPORE 530909

ESTIMATE BILL FOR VEHICLE NO. SCU 1817 H
MODEL : TOYOTA COROLLA

LIST ITEM			
1) BOOT LID		687.90	
2) BOOT LID REFLECTOR		417.10	
3) BOOT LID EMBLEM - 1.6		33.00	
4) BOOT LID INNER LOCK		75.60	
5) BOOT LID LOCK STRIKER		75.10	
6) BOOT LID LOCK CABLE		36.10	
7) BOOT LID STOPPER	2 PCS @ $ 8.90	17.80	
8) BOOT LID HINGE	2 PCS @ $ 58.00	116.00	
9) BOOT LID BADGE		36.90	
10) REAR BUMPER		334.10	
11) REAR BUMPER CLIP	6 PCS @ $ 8.90	53.40	
12) REAR BUMPER SIDE ATTACHMENT	2 PCS @ $ 23.90	47.80	
13) REAR BUMPER BEAM		95.10	
14) REAR BUMPER SIDE CLIP	2 PCS @ $ 12.80	25.60	
15) REAR BUMPER BRACKET	2 PCS @ $ 55.60	111.20	
16) REAR LICENCE PLATE LAMP	2 PCS @ $ 69.10	138.20	
17) TAIL LAMP ASSY (RH)		363.95	
18) TAIL LAMP PANEL (RH)		466.00	
19) TAIL LAMP CLIP	2 PCS @ $ 12.90	25.80	
20) REAR PANEL INNER GARNISH		79.10	
21) REAR PANEL INNER BOARD		69.10	
22) REAR PANEL INNER BOARD CLIP	3 PCS @ $ 8.90	26.70	

YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6
#02-19, SINGAPORE 417883
TEL: 6 5090052 FAX: 6 7479402

23) SPARE TYRE BOARD		1 1	189.10	X
24) REAR FLOOR PANEL		1	780.10	X
25) REAR FENDER INNER BOARD (RH)		1 1	185.90	?
26) REAR FENDER INNER BOARD CLIP (RH)	5PCS @ $ 8.90	1 set	44.50	
27) REAR EXHAUST SILENCER		1 set	720.15	?
28) REAR EXHAUST MOUNTING	2 PCS @ $ 48.10	1 set	96.20	?
29) REAR EXHAUST HEAT SHIELD		1 set	68.25	?
			5,415.75	
	LESS DISCOUNT - 25%		1,353.94	
				4,061.81

SPECIAL NETT ITEM

1) REAR LICENCE PLATE (EMBOSS)	1 1	33.00	X
2) REAR INSULATOR CLOTH	1 1	120.00	X
3) REAR EXHAUST CHROME PIPE	NIL	120.00	X
			273.00

LABOUR CHARGE

1) TO CHECK WIRING SYSTEM	30.00	
2) TO APPLY UNDER SEALING ON AFFECTED AREAS	150.00	50
3) TO REMOVE AND REFIX REAR TRIM, FLOORBOARD, ROOF LINING,UPHOLSTERY ETC	150.00	80
4) TO REMOVE AND REFIX REAR EXHAUST SILENCER	150.00	60
5) TO REPLACE NEW PARTS, STRAIGHTEN CHASSIS FRAME, CUT, WELD, KNOCK ETC	1,100.00	1000
6) TO RESPRAY ON THE AFFECTED AREAS	1,100.00	900
		2,680.00
GRAND TOTAL		**7,014.81**
		7498.81

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

3019.65
2264.73
4384.73
3507

YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6
#02-19, SINGAPORE 417883
TEL: 6 5090052 FAX: 6 7479402

10-07-18

OUR REF NO. SCU 1817H

ONG HOCK CHWEE
BLK 909, HOUGANG
ST 91, #01-94
SINGAPORE 530909

SUPPLEMENTARY BILL FOR VEHICLE NO. SCU 1817H
MODEL : TOYOTA COROLLA

LIST ITEM

1)	REAR FENDER (RH)	1	1,124.00	
2)	REAR WINDSCREEN MOULDING	1	214.00	
			1,338.00	
	LESS DISCOUNT - 25%		334.50	
				1,003.50

SPECIAL NETT ITEM

1)	REAR WINDSCREEN INNERSEAL	1	60.00	
2)	REAR WINDSCREEN GUM	1	60.00	
				120.00

LABOUR CHARGE

1)	TO REPLACE NEW PARTS, CUT, WELD, KNOCK ETC - REAR FENDER (RH)	1	700.00	
2)	TO RESPRAY ON REAR FENDER RH	1	440.00	
3)	TO REPLACE REAR WINDSCREEN	1	220.00	
				1,360.00
	GRAND TOTAL			2,483.50

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III18012548/URBN2
Date: 03/08/2018

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	**Policy No:**			
Claimant Vehicle No :	SCU1817H	**Insured Vehicle No :**	SHD4774H		
Date of Loss:	06/07/2018	**Nature of Claim:**	TP	**Claim No:**	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	**SCU1817H**		
Make & Model:	TOYOTA COROLLA, 1.6 (A)	**Engine No:**	4A4498600
Reg. Date:	03/10/1991 (Man. Year: 1991)	**Chassis No:**	AE1013005824
Colour:	Silver	**Odometer:**	459447 km
Engine Capacity:	1587 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S$):	**Market Value/New Car Price**		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		**Steering (Serviceable):**	Yes	**Footbrake (Serviceable):**	Yes
Handbrake (Serviceable):	Yes	**Engine Modification:**	No	**Pre-accident Condition:**	

CONDITION OF TYRES

Front Tyre Size:	205/55R16	**Rear Tyre Size:**	205/55R16
Front Left Side:	Yokohama 6 mm	**Rear Left Side:**	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	**Rear Right Side:**	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,458.31	2,264.74	3,193.57	58.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,040.00	2,120.00	1,920.00	47.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S$)	**9,498.31**	**4,384.74**	**5,113.57**	**53.84**
Approved Total (Overridden) (S$)		**3,500.00**		
Nett Amount (S$)	**9,498.31**	**3,500.00**	**5,998.31**	**63.15**

INSPECTION

Date of Assignment: 09/07/2018
Date Inspected: 10/07/2018 **Inspected At:** Yi Heng Motor Workshop (HQ)
Blk 1 Kaki Bt Ave 6 #02-19
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA **Manager:** Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Aug 2018)
Parts:	143	TOYOTA COROLLA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCU1817H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Repair	687.90 FL	*- FL
2	1		*BOOT LID REFLECTOR	Cracked	417.10 FL	*417.10 FL
3	1		*BOOT LID EMBLEM-1.6	Necessary	33.00 FL	*33.00 FL
4	1		*BOOT LID INNER LOCK	Not Necessary	75.60 FL	*- FL
5	1		*BOOT LID LOCK STRIKER	Not Necessary	75.10 FL	*- FL
6	1		*BOOT LID LOCK CABLE	Not Necessary	36.10 FL	*- FL
7	2		*BOOT LID STOPPER	Not Necessary	17.80 FL	*- FL
8	2		*BOOT LID HINGE	Repair	116.00 FL	*- FL
9	1		*BOOT LID BADGE	Necessary	36.90 FL	*36.90 FL
10	1		*REAR BUMPER	Distorted	334.10 FL	*334.10 FL
11	6		*REAR BUMPER CLIP	Necessary	53.40 FL	*53.40 FL
12	1		*REAR BUMPER SIDE ATTACHMENT	O/s Bent	47.80 FL	*23.90 FL
13	1		*REAR BUMPER BEAM	Bent	95.10 FL	*95.10 FL
14	2		*REAR BUMPER SIDE CLIP	Necessary	25.60 FL	*25.60 FL
15	1		*REAR BUMPER BRACKET	O/s Bent	111.20 FL	*55.60 FL
16	2		*REAR LICENCE PLATE LAMP	Not Necessary	138.20 FL	*- FL
17	1		*TAIL LAMP ASSY RH	Cracked	363.95 FL	*363.95 FL
18	1		*TAIL LAMP PANEL RH	Dented	466.00 FL	*466.00 FL
19	2		*TAIL LAMP CLIP	Not Necessary	25.80 FL	*- FL
20	1		*REAR PANEL INNER GARNISH	Not fitted	79.10 FL	*- FL
21	1		*REAR PANEL INNER BOARD	Not Necessary	69.10 FL	*- FL
22	3		*REAR PANEL INNER BOARD CLIP	Not Necessary	26.70 FL	*- FL
23	1		*SPARE TYRE BOARD	Not Necessary	189.10 FL	*- FL
24	1		*REAR FLOOR PANEL	Repair	780.10 FL	*- FL
25	1		*REAR FENDER INNER BOARD RH	Torn	185.90 FL	*185.90 FL
26	5		*REAR FENDER INNER BOARD CLIP RH	Necessary	44.50 FL	*44.50 FL
27	1		*REAR EXHAUST SILENCER	Bent/Twisted	720.15 FL	*720.15 FL
28	2		*REAR EXHAUST MOUNTING	Necessary	96.20 FL	*96.20 FL
29	1		*REAR EXHAUST HEAT SHIELD	Bent	68.25 FL	*68.25 FL
30	1		*REAR FENDER RH	Repair	1,124.00 FL	*- FL
31	1		*REAR WINDSCREEN MOULDING	Not Necessary	214.00 FL	*- FL
32	1		*REAR WINDSCREEN INNERSEAL	Not Necessary	60.00 FS	*- FS
33	1		*REAR WINDSCREEN GUM	Not Necessary	60.00 FS	*- FS
34	1		*REAR LICENCE PLATE (EMBOSS)	Not Necessary	33.00 FS	*- FS
35	1		*REAR INSULATOR CLOTH	Not Necessary	120.00 FS	*- FS
36	1		*REAR EXHAUST CHROME PIPE	Not fitted	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S$)	**7,146.75**	**3,019.65**
- List Item Discount on L Items 25.00/25.00% (S$)	1,688.44	754.91
Total Parts (S$)	**5,458.31**	**2,264.74**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING SYSTEM	New	30.00	30.00
2	TO APPLY UNDER SEALING ON AFFECTED AREAS	New	150.00	50.00
3	TO REMOVE AND REFIX REAR TRIM,FLOORBOARD,ROOF LINING,UPHOLSTERY ETC	New	150.00	80.00
4	TO REMOVE AND REFIX REAR EXHAUST SILENCER	New	150.00	60.00
5	TO REPLACE NEW PARTS,STRAIGHTEN CHASSIS FRAME,CUT,WELD,KNOCK ETC	New	1,100.00	1,000.00
6	TO RESPRAY ON THE AFFECTED AREAS	New	1,100.00	900.00
7	TO REPLACE NEW PARTS,CUT,WELD,KNOCK ETC-REAR FENDER RH	New	700.00	-
8	TO RESPRAY ON REAR FENDER RH	New	440.00	-
9	TO REPLACE REAR WINDSCREEN	New	220.00	-
		Gross Labour Cost (S$)	**4,040.00**	**2,120.00**

Report was unsubmitted during this print-out.

< END OF ESTIMATES >