COMFORTDELGRO ENGINEERING PTE LTD

VEHICLE NO : SHC 2582M

DATE 7/17/2018 16:43

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid			$ 1,349.50
	Boot Lid Lock Upper			$ 132.10
	Boot Lid Lock Lower			$ 30.30
	Boot Lid Sonata Plate			$ 43.60
	Boot Lid Hyundai Plate			$ 24.20
	Boot Lid 'H' Emblem			$ 26.10
	Boot Lid CRDI Plate			$ 22.70
	Rear Bumper			$ 578.40
	Rear Bumper Reinforcement ?			$ 483.30
	Rear Bumper Clip			$ 22.00
	Rear Bumper Bracket (LH/RH) ?		$ 49.00	$ 98.00
	Rear Bumper Sponge ?			$ 137.40
	Rear Bumper Under Cover ?			$ 185.80
	Rear Bumper Protector (LH/RH)		$ 38.00	$ 76.00
	Rear Panel			$ 391.80
	Rear Panel Garnish			$ 95.80
	SUB TOTAL			$ 3,697.00
	LESS 20%			$ 739.40
	DISCOUNTED TOTAL			$ 2,957.60
	Boot Lid Comfort Logo & Tel No. Sticker			$ 30.00 Nett
	Rear Bumper Reverse Sensor			$ 135.70 Nett
	Boot Lid Comfort Logo Sticker			$ 10.00 Nett
	TOTAL			$ 175.70
	Labour Charge			
	Panel Beating			$ ~~350.00~~ 400
	Spray Painting Charge			$ ~~750.00~~ 400
	Wiring Charge			$ ~~30.00~~
	Tuff Kote			$ ~~5.00~~ 20
	Remove/Refix Reverse Sensor			$ ~~120.00~~
	TOTAL LABOUR			$ 1,755.00
	ESTIMATE TOTAL			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Kalin Clay

17/7/18 1530h

2 days

L/S

After Repair pls

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.