(08/11/13) Surveyor Pasu | REF: III | C 0309m

# ASSIGNMENT

From: | Date: 30.07.2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLU 9383H

at Workshop m/s Hua Hong

of 25D Sungei Kadut St 1

Insured:

Policy No.

Claims No.

Sum Insured: | Excess:

(Client's Record)

Make of Veh:

(Policy Condition) 10am - 10.30 am owner working

Remark: The veh had commenced its repair at the time of inspection.

| N/S | O/S |
|---|---|
| | |

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLU 9383H Yr Regn: 2017 / Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: TOYOTA SIENTA 1.5 X HB c.c 1496

Colour Red A/C: Insured / Std / NI / NA

Sp.Reading 55920 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: NHP170 7075625

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

| Front | | Rear | |
|---|---|---|---|
| R/Bal. | 5 mm | R/Bal. | 5 mm |
| L/Bal. | 5 mm | L/Bal. | 5 mm |
| D.O.A. | 15/07/18 | D.O.I. | 30/07/18 |

Survey held at Hua Hong

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or O/S FRT

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|---|---|
| | |

Date/Time, File Pass to? [ ] : Preli. Report

1) [ ] : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: ($ )

Days Of Repair:

Resurvey No. of Trip:

Add Fee: [ ] : Site Insp ($ )

[ ] : Interview ($ )

[ ] : Tech. Invs ($ )

[ ] : Weekend ($ )

Survey Fee:

Transportation: ___S + RS.___SI

Photos

Others

TOTAL