LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia Shi Yi

Date: 03 Aug 2018

Preliminary Advice

Insured Vehicle No	: YN7046C		
TP Vehicle No	: SLV3299C	Accident Date	: 22/07/2018
Make	: KIA CARENS	Assignment Date	: 31/07/2018
Date of Inspection	: 31/07/2018	Est. Duration of Repair	: 24.00
Inspection At	: LIAN HONG SENG MOTOR WORKS - ANG MO KIO (HQ) BLK 5035 ANG MO KIO IND.PARK 2 #01-345 SINGAPORE 569537		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion. The undercarriage and body structure affected due to collision and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S$	122,295.89
Revised Amount	:S$	36,933.89
Check Items (Estimated)	:S$	80,071.03
Total	:S$	117,004.92
Lump Sum Repair	:S$	

Total Loss Consideration

New for Old Value	:S$
Pre-Accident Value	:S$
COE / PARF Rebate	:S$
Salvage Value	:S$
Margin for Repair	:S$

Remarks

( ) The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.