COMFORTDELGRO ENGINEERING PTE LTD

AXA

CLC

REPAIR ESTIMATE*

VEHICLE NO : SHD 7132R **DATE : 10.08.2018**

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover X repair			$ 544.50
	Front Bumper Bracket Top (RH) X sur			$ 22.40
	Front Bumper Retainer Mounting X sur			$ 9.20
	Headlamp (RH) X sur			$ 1,388.00
	Front Wheel Hub Cap (RH) — horizontal			$ 107.10
	Front RH Fender X repair			
	SUB TOTAL			**$ 2,071.20**
	LESS 20%			$ 414.24
	DISCOUNTED TOTAL			**$ 1,656.96**
	Labour Charge			
	Panel Beating			$ ~~350.00~~ 200
	Spray Painting Charge			$ ~~500.00~~ 400
	Wiring Charge			$ ~~30.00~~ X
	Tuff Kote			$ ~~50.00~~ X
	FRT Wheel Alignment			$ ~~120.00~~ X
	TOTAL LABOUR			**$ 1,050.00**
	ESTIMATE TOTAL			**$ 2,706.96**

Kahin LKK 10/8/18 1400hr. 2 Days P/P After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.