AIG
LKK - 11:00 am

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLH 5426 M

Not Authorised
L.B.I
Resurvey B4 paint

Parts	(a) Cost / List Price Items	$	1,744.40
	Plus/Less 25%	$	436.10
	Total of Cost / List	$	1,308.30
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) **Special Nett Items**	$	200.00
Total Parts Cost		$	1,508.30
Labour		$	1,520.00
Total		$	3,028.30

The above total will be subjected to 7% G.S.T.

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Name of Surveyor : Kenneth

Company : LKK

Survey conducted on : 18/9/18 at

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess :$

(e) Signature of surveyor : Date: 18/9/18

ESTEEM PERFORMANCE

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. :	**SLH 5426 M**	Submit By :	**Carmen Lim**
Make & Model :	TOYOTA PRIUS	Year Manufacture :	2016
Chassis No :	JTDKB3FU703536716	Engine No. :	

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	1	$200.00	S.N	?
2	Rear bumper Bu/Nd	1	$497.50		—
3	Rear bumper clip	10	$40.00		—
4	Rear bumper side retainer LH	1	$112.70		X
5	Rear bumper side retainer RH	1	$112.70		X
6	Rear bumper reinforcement	1	$398.90		?
7	Rear bumper lower garnish centre Nd	1	$582.60		✓
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

ESTEEM PERFORMANCE

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLH 5426 M** Submit By : **Carmen Lim**

Make & Model : TOYOTA PRIUS Year of Manufacture : 2016

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT		
	REPAIR AREA. (REAR BUMPER,END PANEL)	$600.00	250
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT		
	REPAIR AREA. (REAR BUMPER,END PANEL)	$600.00	220
3	To check wiring	$50.00	10
4	Toremove & refit reverse sensor	$120.00	50
5	To tuff coat ~~	$150.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.