REF: CC3/AIG18017655/Albert

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TF RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess: $1200/-

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 232K.

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 33 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLN 3721S. Yr Regn: 2017 April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Audi Q7 c.c 1984

Colour: Black. A/C: Insured / Std / NI / NA

Sp.Reading: 32771 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WAUZZZ4MA1HP044597

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inoder / Jammed / Leaked / Burnt or

Brake: Inoder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/55R18.

R: 255/55R19.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front			Rear		
R/Bal.	06	mm	R/Bal.	06	mm
L/Bal.	06	mm	L/Bal.	06	mm

D.O.A. D.O.I. 27/09/18.

Survey held at: Premium.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	OD AIG.
	26/9 - Revert via memmen
	1/10 - authorise repair by victoria
	INV: 232
	PV: 105K
	Net: 127K
	2/10 - 9.51am email to premium authorise repair excess $1200/-

RECEIVED 25 JUL 2019

Part by Part $82,289.56 (Red: 39771.60 (32%))

RECEIVED 10 MAY 2019

Date/Time: File Pass to? 1) 24/7 Typist

Date/Time: File Return to? 2)

☐ : Preli. Report

☑ : Final Report

Days Of Repair: 33

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format :

Lump Sum / I.B.I: ($)

Survey Fee	200
Transportation	
Photos	
Others	10
TOTAL	210

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2967Z
Vehicle Details	
Vehicle No.:	SLN3721S
Vehicle to be Exported:	Yes
Intended Deregistration Date:	27 Sep 2018
Vehicle Make:	AUDI
Vehicle Model:	Q7 2.0 TFSI QU (252 BHP)
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	CYR034825
Chassis No.:	WAUZZZ4M4HD044597
Maximum Power Output:	185.0 kW (248 bhp)
Open Market Value:	$60,804.00
Original Registration Date:	28 Apr 2017
First Registration Date:	28 Apr 2017
Transfer Count:	0
Actual ARF Paid:	$81,448.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Apr 2027
PARF Rebate Amount:	$61,086.00
Intended COE Rebate Details	
COE Expiry Date:	27 Apr 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	$54,405.00
COE Rebate Amount:	$43,524.00
Total Rebate Amount:	**$104,610.00**

The information contained herein is correct as at 27 Sep 2018

OK

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 2 October 2018 9:56 AM
To: Claims; Admin-D (LKKAuto)
Cc: SUR
Subject: RE: Request Certificate Insurance for vehicle no. SLN 3721S

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLN 3721S (Excess $1,200/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto)
Sent: Monday, 1 October 2018 5:28 PM
To: Claims <claims@premiumauto.com.sg>; Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: Request Certificate Insurance for vehicle no. SLN 3721S

Dear Tony,

Still waiting for AIG to give approval

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>
Sent: Monday, 1 October 2018 5:21 PM
To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>

View Received Message

This mail is associated with :

***SLN3721S (1913342376SG)**
OD
Sep 22 2018 9:00AM
[WONG SHIN YI]
Premium Automobiles Pte Ltd

Reply | Reply All | Mark as Unread | Print Message | Delete Message | Forward

From **AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG)**, sent on **01/10/2018 18:21 PM.**
To LKK_HQ
Subject **Alert - Adj Mandate Approved (S$85000.00) - SLN3721S - Claim Handler: Mohd Zawaye, Norsazani**

Approved:85000.00:to commence repairs. All replaced, check and supplementary items to be justified with clear photographs.

DOCUMENTS SUMMARY

There are no documents.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mohd Zawaye, Norsazani

Date: 28 Sep 2018

Preliminary Advice

Vehicle No	: SLN3721S	Accident Date	: 22/09/2018
Make	: AUDI Q7	Policy No.	: 2100507396
Assignment Date	: 28/09/2018	Excess	: S$0.00
Date of Inspection	: 27/09/2018	Est. Duration of Repair	: 21.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S$	113,532.00
Revised Amount	:S$	76,408.00
Check Items (Estimated)	:S$	23,264.00
Total	:S$	99,672.00
Lump Sum Repair	:S$	

Total Loss Consideration

New for Old Value	:S$	
Pre-Accident Value	:S$	232,000.00
COE / PARF Rebate	:S$	104,610.00
Salvage Value	:S$	
Margin for Repair	:S$	127,390.00

Remarks

(x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( ) Other comments :

PREMIUM DEALER 2018

ANNOUNCING Autotrust Traders Pte Ltd
as sgCarMart Premium Dealer for the 2nd Consecutive Year

Autotrust Traders Pte Ltd

FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just
$58 until it's SOLD!

Post an Ad | Advertiser Login | Ways of Selling

Beautiful 2012 Land Rover Discovery 4 At $105800.
Fully Maintained By Agent. Low Mileage 70Km New 2014 Facelift.Low Interest 2.28%
StarAd

ABWIN ONE-STOP

Browse by Category | Save Search | Print | Sort by Date Posted | 20 results/page

4 vehicles | Search audi q7 | Advanced Search | Search | View All

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	audi q7		Any	Any	2017	Any	Any	Any	Available

Audi Q7 2.0A TFSI Quattro | $237,999 | $22,960 /yr | 25-May-2017 | 1,984 cc | 16,000 km | SUV | Available

Management Unit! AUDI Approved Plus 300 Points Certification, Fully Serviced And Maintained By Premium Automobiles. Extended Warranty Up To 5 Years From Date Of Registration For Selected Unit. Arrange...

Premium Automobiles

Posted: 05-Sep-2018 Tags: 2017 Audi Q7, 2017 audi q7, Audi Q7, audi q7, Audi, Q7, q7, Used Audi

Audi Q7 2.0A TFSI Quattro | $229,800 | $21,790 /yr | 31-May-2017 | 1,984 cc | 29,000 km | SUV | Available

In House Finance And 7 Years Loan Available! Come With Agent 5 Years Warranty And 5 Years/75,000km Free Servicing! Buy With Peace On Mind! Road Tax Till Nov 2018. Lowest Depreciation. High Trade In. C...

Speedo Motoring

Posted: 11-Sep-2018 Tags: 2017 Audi Q7, 2017 audi q7, Audi Q7, audi q7, Audi, Q7, q7, Used Audi

Audi Q7 2.0A TFSI Quattro | $251,999 | $23,880 /yr | 25-Aug-2017 | 1,984 cc | 11,491 km | SUV | Available

(Latest Facelift 7 Seater Model! 5 Years Audi Agent Warranty Till August 2022! Fully Audi Agent Servicing Since Day One! One Management Owner! Low Mileage!) High Loan Available! Lowest Bank Interest...

Premium Automobiles

Posted: 03-Sep-2018 Tags: 2017 Audi Q7, 2017 audi q7, Audi Q7, audi q7, Audi, Q7, q7, Used Audi

Audi Q7 2.0A TFSI Quattro | $255,999 | $24,070 /yr | 06-Sep-2017 | 1,984 cc | 13,500 km | SUV | Available

Additional Options Worth $10k! Management Unit! Immaculate White Exterior/Black Interior. AUDI Approved Plus 300 Points Certification. 5 Years From Date Of Registration For Selected Unit. Arrange For ...

Premium Automobiles

Posted: 05-Sep-2018 Tags: 2017 Audi Q7, 2017 audi q7, Audi Q7, audi q7, Audi, Q7, q7, Used Audi

Save this search criteria, to get email alerts whenever a match is found. Save Search

Make | Model | Price | Depreciation | Reg Date | Eng Cap | Mileage | Veh Type | Status

For old advertisements, view Expired ads

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars to stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car trims, low mileage cars, car brands, carpark rates & car insurance. Find buy used audi q7, audi q7 Singapore, used audi q7 Singapore, used audi q7, used vehicles Singapore or even buy used audi q7 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

Download on the App Store | GET IT ON Google play

©2004-2018 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	22/09/2018 11:24
Date Of Accident	22/09/2018 08:45
Exact Location Of Accident	ALONG CTE BEF BALESTIER ROAD EXIT
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLN3721S
Insured/Policyholder	
Name Of Registered Owner	WONG SHIN YI
NRIC No	S7832967Z
Email Address	WONG.SHINYI@GMAIL.COM
Mobile Phone No	(LOCAL) +65-93374033
Alternative Phone No	OTHERS-93374033
Vehicle Particulars	
Manufacturer	AUDI
Model	Q7 2.0 TFSI QU
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	
Driver	
Name of Driver	WONG SHIN YI
NRIC No	S7832967Z
Date Of Birth	05/11/1978
Occupation	INDOOR
Date Of Driving Pass	28/11/2012
Driving Experience	5 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-93374033
Fax Number	
Contact Number	OTHERS-93374033
EMail Address	WONG.SHINYI@GMAIL.COM

Address	BLK 711 PASIR RIS STREET 72 #05-57
Postcode	510711
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : LENYGRACE GENDER: : FEMALE
Passenger 2	NAME: : KAELYN CHEW GENDER: : FEMALE
Passenger 3	NAME: : KAYVEN CHEW GENDER: : MALE
Passenger 4	NAME: : KYLA CHEW GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes,Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes,against whom?	

Circumstances of Accident

TH LORRY IN FRONT OF ME SUDDENLY STOP, I COULD NOT BRAKE IN TIME AND COLLIDED WITH IT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD2361A
Vehicle Make/Model/Colour	
Details Of Properties	LORRY
Vehicle Category	COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

   I understand, acknowledge, agree and consent that:

   (a) My insurer, my workshop and the General Insurance Association of Singapore ("**GIA**") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

   (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

   (ii) investigating the accident and/or my claims;

   (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

   (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

   (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")

   (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

   (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

   (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

   (e) the information so collected under (d) above may be shared / disclosed:

   (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

   (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time: 22/9/18	Driver's Signature (If driver is not the policyholder) Date & Time:	Reporting Centre Personnel's Signature Name: TOH ENG SOU NRIC/FIN No.: G5554904K

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

The lorry infront of me suddenly stop, I could not brake in time and collided with it.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 22/9/18

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Bintang
NRIC/FIN No.: E3524904P

PREMIUM AUTO SERVICES PTE LTD

Accident Photo

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S7832967Z

Name

WONG SHIN YI
(HUANG XINYI)

黄 欣 怡

Race
CHINESE

Date of birth
05-11-1978

Sex
F

S7832967Z

Country of birth
SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number S7832967Z

Name

WONG SHIN YI
(HUANG XINYI)

Birth Date 05 Nov 1978

Issue Date 28 Nov 2012

002127195E

4387110

NRIC No. S7832967Z

Date of issue
10-03-2009

Address
APT BLK 711 PASIR RIS STREET 72
#05-57
SINGAPORE 510711

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

		EFFECTIVE DATE
Class 3A	Motor cars without clutch pedals (Auto) =< 3000kg with =< 7 passengers, exclusive of the driver; and other motor vehicles without clutch pedals =< 2500kg	28 Nov 2012

Licence No. S7832967Z

NP 429A

AIG

CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder	: WONG SHIN YI(HUANG XINYI)	**Vehicle No.**	: SLN3721S
Period of Insurance	: 28 Apr 2018 To 27 Apr 2019	**Policy No.**	: 2100507396-01
Engine No.	: CYR034825	**Endorsement No.**	:
Chassis No.	: WAUZZZ4M4HD044597	**Issued Date**	: 26 Mar 2018

ABOUT THE COVER

Make/Model	: AUDI Q7 2.0 TFSI				
Engine Capacity/Tonnage	: 1,984.00 CC	Sum Insured	: Market Value	First Year of Registration	: 2017
Driver Restriction	: NA	Off Peak Car	: No	Insuring with COE/PARF	: Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition

You have to pay an additional sum of $3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings

EXCESS

Section 1
Fire - $0 Own Damage - $1200 Theft - $0 Flood Cover - $0

Section 2
Property Damage - $0

Windscreen : $100

Named Driver and Excess (where applicable)

WONG SHIN YI(HUANG XINYI) - $1200 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia)

0504125210

PREMIUM LEASING - VL
281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938
Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

24-HOUR AIG AUTO HOTLINE: 1800 6336 6200

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Writ/Summons/Correspondences from third party(ies) to AIG immediately.

If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number **(65) 6419-3000** for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within **5** working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the **original** insurance policy and schedule issued by AIG, a copy of the Accident Report from **Audi Customer Service Centre** must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.
Activation Hotline: 67428888
501 Guillemard Road Singapore 399840
Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc).

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is IMPORTANT and MUST be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1121/2018/GW
Date	:	26-Sep-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms. Wong Shin Yi
Address	:	Blk 711 Pasir Ris Street 72 #05-57 Singapore 510771
Telephone	:	HP +65 93374033
Type of Claim	:	Own Damage Claims
Policy No.	:	
Vehicle No	:	**SLN 3721 S**
Model Code	:	Audi Q7 2.0 TFSI Qu
Model / Year	:	Apr-17
Engine No	:	CYR 034825
Chassis No	:	WAUZZZ4M4HD044597
Mileage	:	-
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	22-Sep-18
Place of Accident	:	Along CTE BEF Balestier Road Exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLN 3721 S.

S/N	Nature of Jobs			Estimated Charges
1	To tow and recover vehicle from scene of accident.			NA
2	To remove, check and reinstall front wire harness for headlights, horns, dog lamps, outside temperature sensor, headlight washer assy front parking aid and front vehicle enviroment camera assy. Inspect for damges and renew accordingly.	S/N	$	580.00
3	To remove and renew, aircon condenser, turbocooler, radiaotors. Check electrical fans anc control unit.Pressuries cooling system. To carry out vacuum and regas.	S/N	$	1,400.00
4	To remove center console, instrument panels and closters. Renew dashboard, both frontal air bags, seat belts, pillar trims, roof lining, both curtain air bags, control unit and battery central protection.	S/N	$	3,600.00
5	To remove and reinstall engine assy with subframe to facillitate car-o-liner repairs.	S/N	$	3,200.00
6	To remove and reinstall front suspension assy with subframe to facillitate car-o-liner repairs	S/N	$	2,800.00
	SUB- TOTAL LABOUR CHARGES	:		**$ 11,580.00**

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLN 3721 S.

S/N	Nature of Jobs			Estimated Charges
7	To place vehicle on car-o-liner.	S/N	$	2,400.00 ?
8	To dismantle front bumper, bonnet and both front fender. Align both front chassis frames to specificaton of origin. Renew front lock carrier and align to position. Renew danaged panels. Re-organise front crash management components. Reinstall all parts removed.	S/N	$	10,000.00 800 x 6 = 480 5600
9	To dismantle both front door panel trims, remove and reinstall both mirror assy.	S/N	$	800.00
10	To respray front bumper, lower spoiler, both fenders, bonnet hinges , engine compartment, both A- pillars, both front wheel arch trims and both front doors.		$	600 x 6 = 3600 Wheel Cover x 2 = 200 x 2 = 400 9,500.00 4000. 4600
11	To carry out wheel alignment.	S/N	$	240.00 ?
12	To carry out diagnostic check.	S/N	$	384.00
	TOTAL LABOUR CHARGES	:	**$**	**34,904.00**

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 3721 S

S/N	Parts Description			Damage Parts & Prices S/NETT	REMARKS
1	FRONT BUMPER Distorted		$	2,252.00	1801.60
2	FRONT BUMPER FIXING PARTS		$	382.00	X
3	FRONT BUMPRE AIR GUIDE-LH/RH Bend	2	$	114.00	90.56
4	FRONT BUMPER END CA-LH/RH	2	$	60.00	47.84
5	FRONT BUMPER LOWER CENTRE GRILLE Cracked		$	180.00	143.60
6	FRONT BUMPER UNDERRUN BAR Bent		$	700.00	559.60
7	FRONT BUMPER CLOSING ELEMENT Torn		$	180.00	143.60
8	FRONT BUMPER SPOILER-LH/RH Damaged	2	$	366.00	292.80
9	RADIAOTOR GRILLE Cracked		$	2,027.00	1621.60
10	FRONT BUMPER UPPER CLOSING ELEMENT Damaged		$	237.00	189.60
11	RADIATOR GRILLE COVER } Cracked		$	60.00	47.52
12	RADIATOR GRILLE UPPER COVER		$	54.00	42.80
13	RADIATOR GRILLE OVER CAP } Distorted		$	89.00	94.80
14	RADIATOR BRAKCET		$	9.00	6.72
15	FRONT CAMERA Damaged		$	1,023.00	817.40
16	ADAPTER CABLE LOOM ~~Damaged~~ Not Nec		$	358.00	X
17	FRONT SENSOR Damaged	4	$	842.00	673.60
18	FRONT SENSOR SEALRING ~~Not~~ Nec	4	$	14.00	X
19	FOAM FILLER PIECE Cracked		$	147.00	117.60
20	FRONT BUMPER CARRIER Bent		$	753.00	602.40
	SUB-TOTAL SPARE PARTS :		**$**	**9,847.00**	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

7874

4257.80

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 3721 S

S/N	Parts Description				Damage Parts & Prices S/NETT	REMARKS
21	FRONT BUMPER SUPPORT-LH/RH	Dmgd	2	$	62.00	48.64
22	FRONT BUMPER GUIDE SECTION-LH/RH	Not	2	$	74.00	59.20
23	FRONT BUMPER COVER	Cracked		$	112.00	89.60
24	FRONT FENDER -LH/RH	Cracked	2	$	2,844.00	2275.20
25	FRONT FENDER ATTACHEMENT PARTS	Nil	2	$	108.00	105.76
26	FRONT FENDER BRACKET -LH.RH	Not Nec	2	$	112.00	X
27	FRONT FENDER UPPER BRACKET -LH/RH	Not Nec	2	$	106.00	X
28	FRONT FENDEER BRACE-LH/RH	[illegible] Best.	2	$	179.00	142.48
29	FRONT WHEEL HOUSING LINER-LH/RH	Not a	2	$	430.00	X
30	WHEEL HOUSING LINER ATTACHEMENT PARTS	Not a	2	$	93.00	X
31	FRONT WHEEL COVER-LH/RH	Nil	2	$	1,004.00	802.40
32	LED HEADLIGHT	Cracked.	2	$	17,698.00	14,158.40
33	HEADLIGHT CONTROL UNIT-LH/RH	Dmgd	2	$	1,314.00	525.60
34	HEADLIGHT POWER MODULE	Dmgd	2	$	1,389.00	555.60
35	HEADLAMPS FAN	Dmgd.	2	$	689.00	275.60
36	HEADLIGHT HOSE-LH/RH	Not a	2	$	66.00	X
37	COMPENSATING PIECE	Not Nec	2	$	70.00	X
38	HEADLIGHT LIFT CYLINDER-LH/RH	Dmgd.	2	$	348.00	278.40
39	HEADLIGHT WASHER HOSE	Dmgd.		$	83.00	65.60
40	FRONT UBMPER AIR GUDIE GRILLE-LH/RH	Cracked	2	$	520.00	416.
	SUB-TOTAL SPARE PARTS	:		**$**	**27,301.00**	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

22348

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 3721 S

S/N	Parts Description				Damage Parts & Prices S/NETT		REMARKS
41	FRONT BUMPER SIDE GRILLE END COVER-LH/RH	Dmgd.	2	$	58.00	?	45.20
42	BONNET	Dented		$	4,295.00	✓	3436
43	BONNET ATTACHEMENT PARTS	Nil		$	84.00	✓	66.64
44	BONNET LID HINGE-LH/RH	Not Best.	2	$	146.00	?	116.16
45	GAS FILLED STRUT	Best.		$	121.00	✓	96.40
46	STOP BUFFER	Nil	2	$	17.00	✓	13.28
47	BOONNET IMPACT PROTECTION	Nil		$	92.00	✓	73.36
48	HEADLAMPS COVER-LH/RH	Cracked	2	$	178.00	✓	142.08
49	LED HEADLIGHT TRIM COVER-RH	Dmgd.		$	39.00	✓	30.64
50	LED HEADLIGHT LOCKING MECHANISM	Not Nec	2	$	14.00	?	X
51	BONNET STRIKER-LH/RH	Best	2	$	214.00	?	172
52	BONNET BOWDEN CABLE	Dmgd		$	50.00	?	40
53	BONNET LID LOCK WITH MICRO	Dmgd	2	$	383.00	?	310.40
54	BONNET LID LOCK CABLE	Dmgd		$	66.00	?	63.52
55	RELEASE LEVER	~		$	12.00	✓	9.44
56	AIR CONTINIONER STICKER	Nil		$	7.00	✓	4.80
57	SIGN ' CAUTION'	Nil		$	12.00	✓	9.28
58	LOCK CARRIER WITH RADIAOT	Cracked		TBC	1048	✓	838.40
59	FRONT BUMPER AIR GUDIE GRILLE-LH/RH	Repeated (Item 40)	2	$	520.00	X.	
60	SIDE MEMBER TRIM-LH/RH	Not Nec	2	$	852.00	X.	
	SUB-TOTAL SPARE PARTS		:	**$**	**7,160.00**		

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

6845

9208

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 3721 S

S/N	Parts Description				Damage Parts & Prices S/NETT	REMARKS
61	FRAME RAIL END LOWER BRACKET-LH/RH	Not new	2	$	116.00 ?	X
62	FRAME RAIL END BRACKET-LH/RH	Not new	2	$	92.00 ?	X
63	AIR DUCT-LH/RH	Cracked	2	$	48.00	37.28
64	RADIATOR SUPPORT AIR DUCT-LH/RH	Bent	2	$	70.00 ?	55.20
65	A/C CONDENSER	Dented		$	847.00	677.60
66	RADIATOR	Bent		$	630.00 ?	503.60
67	RADIATOR LOWER RUBBER BUSH	Nec	2	$	19.00 ?	17.44
68	COOLANT CONCENTRATE 1.5 LTR	ok	4	$	133.00	65.28
69	TWIN FAN RING	cracked		$	261.00 ?	209.60
70	RADIATOR FAN WITH CONTROL UNIT	Damaged		$	1,609.00 ?	1132
71	AIR FILTER	Not new		$	585.00 ?	X
72	AIR FILTER COVER	Not new		$	416.00 ?	X
73	INTAKE AIR DUCT	cracked		$	120.00	96
74	CHARGE AIR COOLER	Bent		$	797.00 ?	654.40
75	WATER DEFLECTOR STRIP-LH/RH	Damaged	2	$	164.00 ?	131.20
76	WATER BOX COVER	Not new		$	149.00 ?	X
77	AIR BAG UNIT FOR STEERING WHEL	Activated		$	3,211.00	2568.80
78	AIR BAG UNIT FOR PASSENGER SIDE			$	4,075.00	3260
79	HEAD AIR BAG UNIT-LH/RH		2	$	3,488.00	2790.40
80	AIR BAG CONTROL UNIT			$	2,258.00	1806.40
	TOTAL SPARE PARTS	:		**$**	**19,088.00**	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

14132

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 3721 S

S/N	Parts Description				Damage Parts & Prices S/NETT	REMARKS
81	AIR BAG CRASH SENSOR Activated	3	$	818.00	✓	654
82	ADAPTER CABLE LOOM Not we	2	$	91.00	?	X
83	CENTRAL PROTECTION Bent		$	470.00	?	376
84	THREE POINT SEAT BELT-LH/RH Activated	2	$	3,624.00	✓	2899.20
85	SEAT BELT HEIGHT ADJUSTER ~~not~~ Damged.	2	$	306.00	+	244.80 B
86	DASH BOARD torn		$	4,426.00	✓	3540.80
87	MOULDED HEADLINER Crumpled		$	3,284.00	✓	2627.20
88	A-PILLAR TRIM-LH/RH Bent	2	$	692.00	?	552.80
89	FRONT GRAB HANDLE FOLDING Not ne	2	$	248.00	?	X
90	REAR GRAB HANDLE FOLDING-LH/RH Dmgd	2	$	248.00	?	99.20
91	FRONT PLATE NO. Bent	S/N	$	25.00	✓	25
92	SUNDRIES Nil		$	1,000.00	?	320.08
	TOTAL SPARE PARTS	:	**$**	**78,628.00**		
	TOTAL LABOUR CHARGES	:	**$**	**34,904.00**		
	GRAND TOTAL	:	**$**	**113,532.00**		

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

12077

122061 20

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date:

Telefax

Name	:	Adrian Liang
Surveyed Date	:	27/09/18
Authorised Date	:	
Excess Cost	:	
Liability	:	
Remarks	:	Not Authorised, 21 days.

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd	**Estimate No.**	PA/OD/1121/2018/GW
78 Shenton Way	**Date**	16-Oct-18
#07-16 AIG Building	**Service Advisor**	CHANG
Singapore 079120	**Pages**	1 of 1
Attn: Mr. Adrian Ling - Motor Claims Dept	**Regn No**	SLN 3721 S
Tel: 6841 0055 / Fax: 6256 4315	**Model No**	Audi Q7 2.0 TFSI QU

Quantity	Description		Unit Price	Amount
Labours				
1	To renew damaged connector housings.	S/N	$ 600.00	✓
2	To renew rear seat belts and damaged pillar trims.	S/N	$ 800.00	✓
	TOTAL LABOURS	:	**$ 1,400.00**	
Parts				
1	REAR SEAT BELT - LH/RH	2	$ 1,917.00	1933.60
2	ROOF TRIM - REAR	1	$ 250.00	200
3	D-PILLAR TRIM - LH/RH	2	$ 848.00	678.40
4	FLATCONTACT HOUSING WITH CABLE	1	$ 168.00	134
5	ROUND CONNECTOR HSG WITH CABLE	1	$ 233.00	186.40
6	CONNECTOR HOUSING	1	$ 14.00	10.96
7	WIRE REPAIR SET	1	$ 21.00	16.16
8	CONNECTOR HOUSING new	2	$ 55.00	X
9	ADAPTER CABLE LOOM	1	$ 358.00	287
10	CONNECTOR HOUSING	1	$ 12.00	9.96
11	WIRE REPAIR SET	1	$ 44.00	34.90
12	CONNECTOR HOUSING	1	$ 16.00	12.32
13	OIL PRESSURE SWITCH end	1	$ 46.00	36.16
14	ROUND CONNECTOR HSG WITH CABLE	2	$ 148.00	119.68
15	BUTT CONNECTOR FOR WIRE	20	$ 180.00	144
16	ROUND CONNECTOR HSG WITH CABLE	2	$ 145.00	115.84
	TOTAL PARTS	:	**$ 4,455.00**	
	GRAND TOTAL	:	**$ 5,855.00**	

18/10/18

For Premium Automobiles Pte Ltd

PREMIUM AUTOMOBILES PTE LTD

Authorised Signature

3574 28

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd	**Estimate No.**	PA/OD/1121/2018/GW
78 Shenton Way	**Date**	10-Oct-18
#07-16 AIG Building	**Service Advisor**	CHANG
Singapore 079120	**Pages**	1 of 1
Attn: Mr. Adrian Ling - Motor Claims Dept	**Regn No**	SLN 3721 S
Tel: 6841 0055 / Fax: 6256 4315	**Model No**	Audi Q7 2.0 TFSI QU

Quantity	Description		Unit Price	Amount
Parts				
1	HEADLIGHT MOUNTING - LH/RH	2	$ 206.00 CRA	164
2	TOW EYE COVER		$ 34.00 SOL	26.48
3	BONNET HINGE COVER - LH/RH	2	$ 106.00 CRA	94.64
4	BONNET SOUND ABSORBER		$ 312.00 DE	249.60
5	FRONT BUMPER WIRING SET		$ 565.00 CRA	451.60
6	RADIATOR FAN WITH CONTROL UNIT Confirmed		$ 1,609.00 ?	1287.20
7	HORN - RH		$ 200.00 CRA	160
8	HORN CONNECTOR - RH		$ 28.00 CRA	21.76
	TOTAL PARTS	:	**$ 3,060.00**	
	GRAND TOTAL	:	**$ 3,060.00**	

For Premium Automobiles Pte Ltd

10/10 - by Rasul.

Authorised Signature

2018 28

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept **Tel: 6841 0055 / Fax: 6256 4315**	**Estimate No.** **Date** **Service Advisor** **Pages** **Regn No** **Model No**	PA/OD/1121/2018/GW 30-Oct-18 CHANG 1 of 1 SLN 3721 S Audi Q7 2.0 TFSI QU

Quantity	Description			Unit Price	Amount
Parts					
1	TRIM PLATE FOR SEALT BELT RH	NW	1	$ 1,917.00	$ 27.92
2	TRIM PLATE FOR SEALT BELT LH		1	$ 250.00	$ 27.92
		TOTAL PARTS	:	**$ 2,167.00**	$ 55.84
		GRAND TOTAL	:	**$ 2,167.00**	

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 3721 S

S/N	Parts Description			Damage Parts & Prices S/NETT	REMARKS
1	FRONT BUMPER Distorted		$	2,252.00	✓
2	FRONT BUMPER FIXING PARTS		$	382.00	✗
3	FRONT BUMPRE AIR GUIDE-LH/RH	2	$	114.00	? CRA ✓
4	FRONT BUMPER END CA-LH/RH ?	2	$	60.00	? SCR ✓
5	FRONT BUMPER LOWER CENTRE GRILLE Cracked		$	180.00	✓
6	FRONT BUMPER UNDERRUN BAR Bent		$	700.00	✓
7	FRONT BUMPER CLOSING ELEMENT ?		$	180.00	? CRA ✓
8	FRONT BUMPER SPOILER-LH/RH ?	2	$	366.00	? SCR ✓
9	RADIAOTOR GRILLE cracked		$	2,027.00	✓
10	FRONT BUMPER UPPER CLOSING ELEMENT		$	237.00	✗
11	RADIATOR GRILLE COVER ? Cracked		$	60.00	✓
12	RADIATOR GRILLE UPPER COVER		$	54.00	✓
13	RADIATOR GRILLE OVER CAP ? Distorted		$	89.00	✓
14	RADIATOR BRAKCET		$	9.00	✓
15	FRONT CAMERA Damaged		$	1,023.00	✓
16	ADAPTER CABLE LOOM ?		$	358.00	?
17	FRONT SENSOR ?	4	$	842.00	? NA ✓
18	FRONT SENSOR SEALRING ?	4	$	14.00	?
19	FOAM FILLER PIECE Cracked		$	147.00	✓
20	FRONT BUMPER CARRIER Bent		$	753.00	✓
	SUB-TOTAL SPARE PARTS :		**$**	**9,847.00**	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 3721 S

S/N	Parts Description			Damage Parts & Prices S/NETT	REMARKS
21	FRONT BUMPER SUPPORT-LH/RH	2	$	62.00	
22	FRONT BUMPER GUIDE SECTION-LH/RH ?	2	$	74.00	?
23	FRONT BUMPER COVER		$	112.00	
24	FRONT FENDER -LH/RH	2	$	2,844.00	
25	FRONT FENDER ATTACHEMENT PARTS	2	$	108.00	
26	FRONT FENDER BRACKET -LH.RH ?	2	$	112.00	?
27	FRONT FENDER UPPER BRACKET -LH/RH ?	2	$	106.00	?
28	FRONT FENDEER BRACE-LH/RH	2	$	179.00	
29	FRONT WHEEL HOUSING LINER-LH/RH	2	$	430.00	
30	WHEEL HOUSING LINER ATTACHEMENT PARTS	2	$	93.00	
31	FRONT WHEEL COVER-LH/RH	2	$	1,004.00	
32	LED HEADLIGHT	2	$	17,698.00	
33	HEADLIGHT CONTROL UNIT-LH/RH ?	2	$	1,314.00	?
34	HEADLIGHT POWER MODULE ?	2	$	1,389.00	?
35	HEADLAMPS FAN ?	2	$	689.00	?
36	HEADLIGHT HOSE-LH/RH	2	$	66.00	
37	COMPENSATING PIECE ?	2	$	70.00	?
38	HEADLIGHT LIFT CYLINDER-LH/RH ?	2	$	348.00	?
39	HEADLIGHT WASHER HOSE		$	83.00	
40	FRONT UBMPER AIR GUDIE GRILLE-LH/RH	2	$	520.00	
	SUB-TOTAL SPARE PARTS :			**$ 27,301.00**	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 3721 S

S/N	Parts Description			Damage Parts & Prices S/NETT	REMARKS
41	FRONT BUMPER SIDE GRILLE END COVER-LH/RH ?	2	$	58.00	?
42	BONNET Dented		$	4,295.00	✓
43	BONNET ATTACHEMENT PARTS		$	84.00	✓
44	BONNET LID HINGE-LH/RH	2	$	146.00	?
45	GAS FILLED STRUT Best.		$	121.00	✓
46	STOP BUFFER	2	$	17.00	✓
47	BOONNET IMPACT PROTECTION		$	92.00	✓
48	HEADLAMPS COVER-LH/RH Cracked	2	$	178.00	✓
49	LED HEADLIGHT TRIM COVER-RH Damaged.		$	39.00	✓
50	LED HEADLIGHT LOCKING MECHANISM ?	2	$	14.00	?
51	BONNET STRIKER-LH/RH ?	2	$	214.00	?
52	BONNET BOWDEN CABLE ?		$	50.00	?
53	BONNET LID LOCK WITH MICRO ?	2	$	383.00	?
54	BONNET LID LOCK CABLE ?		$	66.00	?
55	RELEASE LEVER		$	12.00	✓
56	AIR CONTINIONER STICKER		$	7.00	✓
57	SIGN 'CAUTION'		$	12.00	✓
58	LOCK CARRIER WITH RADIAOT Cracked		TBC		✓
59	FRONT BUMPER AIR GUDIE GRILLE-LH/RH Repeated (Item 40)	2	$	520.00	✗
60	SIDE MEMBER TRIM-LH/RH Not	2	$	852.00	✗
	SUB-TOTAL SPARE PARTS Nil		:	**$ 7,160.00**	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 3721 S

S/N	Parts Description			Damage Parts & Prices S/NETT	REMARKS
61	FRAME RAIL END LOWER BRACKET-LH/RH ?	2	$	116.00 ?	
62	FRAME RAIL END BRACKET-LH/RH ?	2	$	92.00 ?	
63	AIR DUCT-LH/RH cracked	2	$	48.00 ✓	
64	RADIATOR SUPPORT AIR DUCT-LH/RH ?	2	$	70.00 ? LRA ✓	
65	A/C CONDENSER Dented		$	847.00 ✓	
66	RADIATOR ?		$	630.00 ? M ✓	
67	RADIATOR LOWER RUBBER BUSH ?	2	$	19.00 ?	
68	COOLANT CONCENTRATE 1.5 LTR	4	$	133.00 ✓	
69	TWIN FAN RING ?		$	261.00 ?	
70	RADIATOR FAN WITH CONTROL UNIT ?		$	1,609.00 ?	
71	AIR FILTER ?		$	585.00 ?	
72	AIR FILTER COVER ?		$	416.00 ?	
73	INTAKE AIR DUCT cracked		$	120.00 ✓	
74	CHARGE AIR COOLER ?		$	797.00 M ✓	
75	WATER DEFLECTOR STRIP-LH/RH ?	2	$	164.00 ? ad ✓	
76	WATER BOX COVER ?		$	149.00 ?	
77	AIR BAG UNIT FOR STEERING WHEL		$	3,211.00 ✓	
78	AIR BAG UNIT FOR PASSENGER SIDE } Activated		$	4,075.00 ✓	
79	HEAD AIR BAG UNIT-LH/RH	2	$	3,488.00 ✓	
80	AIR BAG CONTROL UNIT		$	2,258.00 ✓	
	TOTAL SPARE PARTS :			**$ 19,088.00**	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 3721 S

S/N	Parts Description			Damage Parts & Prices S/NETT	REMARKS
81	AIR BAG CRASH SENSOR Activated	3	$	818.00	
82	ADAPTER CABLE LOOM ?	2	$	91.00	?
83	CENTRAL PROTECTION ?		$	470.00	?
84	THREE POINT SEAT BELT-LH/RH Activated	2	$	3,624.00	
85	SEAT BELT HEIGHT ADJUSTER new	2	$	306.00	
86	DASH BOARD torn		$	4,426.00	
87	MOULDED HEADLINER crumpled		$	3,284.00	
88	A-PILLAR TRIM-LH/RH ? de	2	$	692.00	?
89	FRONT GRAB HANDLE FOLDING ?	2	$	248.00	?
90	REAR GRAB HANDLE FOLDING-LH/RH ?	2	$	248.00	?
91	FRONT PLATE NO. Bent	S/N	$	25.00	
92	SUNDRIES ?		$	1,000.00	?
	TOTAL SPARE PARTS	:	**$**	**78,628.00**	
	TOTAL LABOUR CHARGES	:	**$**	**34,904.00**	
	GRAND TOTAL	:	**$**	**113,532.00**	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

18/10/18

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1121/2018/GW
Date	:	26-Sep-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian
You recommended 21 days
We took 33 days exclude 5 Sundays and 1 PH - jb - 12 Feb 19

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms. Wong Shin Yi
Address	:	Blk 711 Pasir Ris Street 72 #05-57 Singapore 510771
Telephone	:	HP +65 93374033
Type of Claim	:	Own Damage Claims
Policy No.	:	
Vehicle No	:	**SLN 3721 S**
Model Code	:	Audi Q7 2.0 TFSI Qu
Model / Year	:	Apr-17
Engine No	:	CYR 034825
Chassis No	:	WAUZZZ4M4HD044597
Mileage	:	-
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	22-Sep-18
Place of Accident	:	Along CTE BEF Balestier Road Exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLN 3721 S.

S/N	Nature of Jobs			Estimated Charges		
1	To tow and recover vehicle from scene of accident.			NA		
2	To remove, check and reinstall front wire harness for headlights, horns, dog lamps, outside temperature sensor, headlight washer assy front parking aid and front vehicle enviroment camera assy. Inspect for damges and renew accordingly.	S/N	$	580.00	$	*580.00*
3	To remove and renew, aircon condenser, turbocooler, radiaotors. Check electrical fans anc control unit.Pressuries cooling system. To carry out vacuum and regas.	S/N	$	1,400.00	$	*1,400.00*
4	To remove center console, instrument panels and closters. Renew dashboard, both frontal air bags, seat belts, pillar trims, roof lining, both curtain air bags, control unit and battery central protection.	S/N	$	3,600.00	$	*3,600.00*
5	To remove and reinstall engine assy with subframe to facillitate car-o-liner repairs.	S/N	$	3,200.00	*nil*	
6	To remove and reinstall front suspension assy with subframe to facillitate car-o-liner repairs	S/N	$	2,800.00	*nil*	
	SUB- TOTAL LABOUR CHARGES	:	**$**	**11,580.00**	***$***	***5,580.00***

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLN 3721 S.

S/N	Nature of Jobs			Estimated Charges
	c/f	S/N :	$	2,400.00
7	To place vehicle on car-o-liner.	S/N	$	10,000.00
8	To dismantle front bumper, bonnet and both front fender. Align both front chassis frames to specificaton of origin. Renew front lock carrier and align to position. Renew danaged panels. Re-organise front crash management components. Reinstall all parts removed. *(7 days inclusive both Headlamps)*	S/N	$	800.00
9	To dismantle both front door panel trims, remove and reinstall both mirror assy.		$	9,500.00
10	To respray front bumper, lower spoiler, both fenders, bonnet hinges , engine compartment, both A- pillars, both front wheel arch trims and both front doors. *(Bonnet omitted $600/- added)*	S/N	$	240.00
11	To carry out wheel alignment.	*S/N*	*$*	*1,400.00*
12	***Added labour charges - see attached 16 Oct 18***	S/N	$	384.00
13	To carry out diagnostic check.			
	TOTAL LABOUR CHARGES	:	**$**	**36,304.00**

$	5,580.00
nil	
$	5,600.00
$	800.00
$	4,600.00
nil	
$	1,400.00
$	384.00
$	**18,364.00**

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 3721 S

S/N	Parts Description			Damage Parts & Prices S/NETT		REMARKS
1	FRONT BUMPER		$	2,252.00	$	1,801.60
2	FRONT BUMPER FIXING PARTS		$	382.00		
3	FRONT BUMPRE AIR GUIDE-LH/RH	2	$	114.00	$	90.56
4	FRONT BUMPER END CA-LH/RH	2	$	60.00	$	47.84
5	FRONT BUMPER LOWER CENTRE GRILLE		$	180.00	$	143.60
6	FRONT BUMPER UNDERRUN BAR		$	700.00	$	559.60
7	FRONT BUMPER CLOSING ELEMENT		$	180.00	$	143.60
8	FRONT BUMPER SPOILER-LH/RH	2	$	366.00	$	292.80
9	RADIAOTOR GRILLE		$	2,027.00	$	1,621.60
10	FRONT BUMPER UPPER CLOSING ELEMENT		$	237.00	$	189.60
11	RADIATOR GRILLE COVER		$	60.00	$	47.52
12	RADIATOR GRILLE UPPER COVER		$	54.00	$	42.80
13	RADIATOR GRILLE OVER CAP		$	89.00	$	94.80
14	RADIATOR BRAKCET		$	9.00	$	6.72
15	FRONT CAMERA		$	1,023.00	$	818.40
16	ADAPTER CABLE LOOM		$	358.00		
17	FRONT SENSOR	4	$	842.00	$	673.60
18	FRONT SENSOR SEALRING	4	$	14.00		
19	FOAM FILLER PIECE		$	147.00	$	117.60
20	FRONT BUMPER CARRIER		$	753.00	$	602.40
	SUB-TOTAL SPARE PARTS :		**$**	**9,847.00**	$	7,294.64

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 3721 S

S/N	Parts Description			Damage Parts & Prices S/NETT		REMARKS
		c/f			$	7,294.64
21	FRONT BUMPER SUPPORT-LH/RH	2	$	62.00	$	48.64
22	FRONT BUMPER GUIDE SECTION-LH/RH	2	$	74.00	$	59.20
23	FRONT BUMPER COVER		$	112.00	$	89.60
24	FRONT FENDER -LH/RH	2	$	2,844.00	$	2,275.20
25	FRONT FENDER ATTACHEMENT PARTS	2	$	108.00	$	105.76
26	FRONT FENDER BRACKET -LH.RH	2	$	112.00		
27	FRONT FENDER UPPER BRACKET -LH/RH	2	$	106.00		
28	FRONT FENDEER BRACE-LH/RH	2	$	179.00	$	142.48
29	FRONT WHEEL HOUSING LINER-LH/RH	2	$	430.00		
30	WHEEL HOUSING LINER ATTACHEMENT PARTS	2	$	93.00		
31	FRONT WHEEL COVER-LH/RH	2	$	1,004.00	$	802.40
32	LED HEADLIGHT	2	$	17,698.00	$	14,158.40
33	HEADLIGHT CONTROL UNIT-LH/RH	2	$	1,314.00	$	525.60
34	HEADLIGHT POWER MODULE	2	$	1,389.00	$	555.60
35	HEADLAMPS FAN	2	$	689.00	$	275.60
36	HEADLIGHT HOSE-LH/RH	2	$	66.00		
37	COMPENSATING PIECE	2	$	70.00		
38	HEADLIGHT LIFT CYLINDER-LH/RH	2	$	348.00	$	278.40
39	HEADLIGHT WASHER HOSE		$	83.00	$	65.68
40	FRONT UBMPER AIR GUDIE GRILLE-LH/RH	2	$	520.00	$	416.00
	SUB-TOTAL SPARE PARTS :		**$**	**27,301.00**	$	27,093.20

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 3721 S

S/N	Parts Description			Damage Parts & Prices S/NETT		REMARKS
	c/f				$	*27,093.20*
41	FRONT BUMPER SIDE GRILLE END COVER-LH/RH	2	$	58.00	$	*45.20*
42	BONNET		$	4,295.00	$	*3,436.00*
43	BONNET ATTACHEMENT PARTS		$	84.00	$	*66.64*
44	BONNET LID HINGE-LH/RH	2	$	146.00	$	*116.16*
45	GAS FILLED STRUT		$	121.00	$	*96.40*
46	STOP BUFFER	2	$	17.00	$	*13.28*
47	BOONNET IMPACT PROTECTION		$	92.00	$	*73.36*
48	HEADLAMPS COVER-LH/RH	2	$	178.00	$	*142.08*
49	LED HEADLIGHT TRIM COVER-RH		$	39.00	$	*30.64*
50	LED HEADLIGHT LOCKING MECHANISM	2	$	14.00		
51	BONNET STRIKER-LH/RH	2	$	214.00	$	*172.00*
52	BONNET BOWDEN CABLE		$	50.00	$	*40.00*
53	BONNET LID LOCK WITH MICRO	2	$	383.00	$	*310.40*
54	BONNET LID LOCK CABLE		$	66.00	$	*63.52*
55	RELEASE LEVER		$	12.00	$	*9.44*
56	AIR CONTINIONER STICKER		$	7.00	$	*4.88*
57	SIGN ' CAUTION'		$	12.00	$	*9.28*
58	LOCK CARRIER WITH RADIAOT		$	1,048.00	$	*838.40*
59	FRONT BUMPER AIR GUDIE GRILLE-LH/RH	2	$	520.00		
60	SIDE MEMBER TRIM-LH/RH	2	$	852.00		
	SUB-TOTAL SPARE PARTS :		**$**	**8,208.00**	$	*32,560.88*

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 3721 S

S/N	Parts Description			Damage Parts & Prices S/NETT		REMARKS
		c/f			$	*32,560.88*
61	FRAME RAIL END LOWER BRACKET-LH/RH	2	$	116.00		
62	FRAME RAIL END BRACKET-LH/RH	2	$	92.00		
63	AIR DUCT-LH/RH	2	$	48.00	$	*37.28*
64	RADIATOR SUPPORT AIR DUCT-LH/RH	2	$	70.00	$	*55.20*
65	A/C CONDENSER		$	847.00	$	*677.60*
66	RADIATOR		$	630.00	$	*503.60*
67	RADIATOR LOWER RUBBER BUSH	2	$	19.00	$	*17.44*
68	COOLANT CONCENTRATE 1.5 LTR	4	$	133.00	$	*65.28*
69	TWIN FAN RING		$	261.00	$	*209.60*
70	RADIATOR FAN WITH CONTROL UNIT		$	1,609.00	$	*1,132.00*
71	AIR FILTER		$	585.00		
72	AIR FILTER COVER		$	416.00		
73	INTAKE AIR DUCT		$	120.00	$	*96.00*
74	CHARGE AIR COOLER		$	797.00	$	*654.40*
75	WATER DEFLECTOR STRIP-LH/RH	2	$	164.00	$	*131.20*
76	WATER BOX COVER		$	149.00		
77	AIR BAG UNIT FOR STEERING WHEL		$	3,211.00	$	*2,568.80*
78	AIR BAG UNIT FOR PASSENGER SIDE		$	4,075.00	$	*3,260.00*
79	HEAD AIR BAG UNIT-LH/RH	2	$	3,488.00	$	*2,790.40*
80	AIR BAG CONTROL UNIT		$	2,258.00	$	*1,806.40*
	TOTAL SPARE PARTS :		**$**	**19,088.00**	$	*46,566.08*

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 3721 S

S/N	Parts Description			Damage Parts & Prices S/NETT		REMARKS
		c/f			$	46,566.08
81	AIR BAG CRASH SENSOR	3	$	818.00	$	654.00
82	ADAPTER CABLE LOOM	2	$	91.00		
83	CENTRAL PROTECTION		$	470.00	$	376.00
84	THREE POINT SEAT BELT-LH/RH	2	$	3,624.00	$	2,899.20
85	SEAT BELT HEIGHT ADJUSTER	2	$	306.00	$	244.80
86	DASH BOARD		$	4,426.00	$	3,540.80
87	MOULDED HEADLINER		$	3,284.00	$	2,627.20
88	A-PILLAR TRIM-LH/RH	2	$	692.00	$	552.80
89	FRONT GRAB HANDLE FOLDING	2	$	248.00		
90	REAR GRAB HANDLE FOLDING-LH/RH	2	$	248.00	$	99.20
91	FRONT PLATE NO.	S/N	$	25.00	$	25.00
92	*Added parts 30 Oct 18*		$	2,167.00	$	55.84
93	*Added parts 16 Oct 18*		$	4,455.00	$	3,519.28
94	*Added parts 10 Oct 18*		$	3,060.00	$	2,445.28
95	SUNDRIES		$	1,000.00	$	320.08
	TOTAL SPARE PARTS	:	**$**	**89,358.00**	$	63,925.56
	TOTAL LABOUR CHARGES	:	**$**	**36,304.00**	$	18,364.00
	GRAND TOTAL	:	**$**	**125,662.00**	$	82,289.56

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept **Tel: 6841 0055 / Fax: 6256 4315**	**Estimate No.** **Date** **Service Advisor** **Pages** **Regn No** **Model No**	PA/OD/1121/2018/GW 10-Oct-18 CHANG 1 of 1 SLN 3721 S Audi Q7 2.0 TFSI QU

Quantity	Description		Unit Price	Amount
Parts				
1	HEADLIGHT MOUNTING - LH/RH	2	$ 206.00	$ *164.00*
2	TOW EYE COVER		$ 34.00	$ *26.48*
3	BONNET HINGE COVER - LH/RH	2	$ 106.00	$ *84.64*
4	BONNET SOUND ABSORBER		$ 312.00	$ *249.60*
5	FRONT BUMPER WIRING SET		$ 565.00	$ *451.60*
6	RADIATOR FAN WITH CONTROL UNIT		$ 1,609.00	$ *1,287.20*
7	HORN - RH		$ 200.00	$ *160.00*
8	HORN CONNECTOR - RH		$ 28.00	$ *21.76*
	TOTAL PARTS	:	**$ 3,060.00**	$ *2,445.28*
	GRAND TOTAL	:	**$ 3,060.00**	

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept **Tel: 6841 0055 / Fax: 6256 4315**	**Estimate No.** **Date** **Service Advisor** **Pages** **Regn No** **Model No**	PA/OD/1121/2018/GW 16-Oct-18 CHANG 1 of 1 SLN 3721 S Audi Q7 2.0 TFSI QU

Quantity	Description		Unit Price	Amount
Labours				
1	To renew damaged connector housings.	S/N	$ 600.00	$ 600.00
2	To renew rear seat belts and damaged pillar trims.	S/N	$ 800.00	$ 800.00
	TOTAL LABOURS	:	**$ 1,400.00**	**$ 1,400.00**
Parts				
1	REAR SEAT BELT - LH/RH	2	$ 1,917.00	$ 1,533.60
2	ROOF TRIM - REAR	1	$ 250.00	$ 200.00
3	D-PILLAR TRIM - LH/RH	2	$ 848.00	$ 678.40
4	FLATCONTACT HOUSING WITH CABLE	1	$ 168.00	$ 134.00
5	ROUND CONNECTOR HSG WITH CABLE	1	$ 233.00	$ 186.40
6	CONNECTOR HOUSING	1	$ 14.00	$ 10.96
7	WIRE REPAIR SET	1	$ 21.00	$ 16.16
8	CONNECTOR HOUSING	2	$ 55.00	
9	ADAPTER CABLE LOOM	1	$ 358.00	$ 288.00
10	CONNECTOR HOUSING	1	$ 12.00	$ 8.96
11	WIRE REPAIR SET	1	$ 44.00	$ 34.80
12	CONNECTOR HOUSING	1	$ 16.00	$ 12.32
13	OIL PRESSURE SWITCH	1	$ 46.00	$ 36.16
14	ROUND CONNECTOR HSG WITH CABLE	2	$ 148.00	$ 119.68
15	BUTT CONNECTOR FOR WIRE	20	$ 180.00	$ 144.00
16	ROUND CONNECTOR HSG WITH CABLE	2	$ 145.00	$ 115.84
	TOTAL PARTS	:	**$ 4,455.00**	**$ 3,519.28**
	GRAND TOTAL	:	**$ 5,855.00**	**$ 4,919.28**

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLN 3721 S

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1121/2019/KK

16 July 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Dear Sir,

RE: INSURANCE CLAIM FOR SLN 3721 S, Audi Q7 2.0 TFSI QU.

With reference to the above-mentioned vehicle, no. **SLN 3721 S** claimant, **Ms. Wong Shin Yi,** please find the related document per attached.

1. A copy of the Original invoice no. 85014023 – S$86,765.83.
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SLN 3721 S

Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 14:04

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85014023
Date : 15/07/2019
Order : SLN3721S
Term : 30

Account: A0006 (T 0)

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No: SLN3721S (V 33384) Regn Date: 28/04/2017 Mileage: 45929 WIP No.: 25921

Model: Q7 2.0 TFSI QU (252 bhp) 4MBOI Chassis: WAUZZZ4M4HD044597 Engine: CYR 034825 Dept: U

You have been assisted by :- UB-Jeffery Tan (R) (87)

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	25.00	1.00	25.00
Q	EXC	M: 8888 Insurance Excess/Liability	-1200.00	1.00	-1,200.00
S	BODYWORK	M: TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,FOG LAMPS, OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY,FRONT PARKING AID AND FRONT VEHICLE ENVIROMENT CAMERA ASSY.INSPECT FOR DAMAGE AND RENEW ACCORDINGLY.	580.00	1.00	580.00
S	BODYWORK	M: TO REMOVE AND RENEW AIRCON CONDENSER,TURBO COOLER,RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT.TO CARRY OUT VACUUM / REGAS AND TO PRESSURISE COOLING SYSTEM	1400.00	1.00	1,400.00
S	BODYWORK	M: TO REMOVE CENTER CONSOLE,INSTRUMENT PANELS AND CLOSTERS.RENEW DASHBOARD,BOTH FRONTAL AIRBAG,SEAT BELTS,PILLAR TRIMS,ROOF LINING, BOTH CURTAIN AIRBAG,CONTROL UNIT AND BATTERY CETRAL PROTECTION	3600.00	1.00	3,600.00
S	BODYWORK	M: TO DISMANTLE FRONT BUMPER,BONNET AND BOTH FRONT FENDER.ALIGN BOTH FRONT CHASSIS FRAME TO SPECIFICATION OF ORIGIN.RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.RENEW DAMAGED PANELS.REORGANISE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	5600.00	1.00	5,600.00
S	BODYWORK	M: TO DISMANTLE BOTH FRONT DOOR PANEL TRIMS, REMOVE AND REINSTALL BOTH MIRROR ASSY	800.00	1.00	800.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER,BONNET,LOWER SPOILER,	4600.00	1.00	4,600.00

Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 2 14:04

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85014023
Date : 15/07/2019
Order : SLN3721S
Term : 30

Account: A0006 (T 0)

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No: SLN3721S (V 33384) Regn Date: 28/04/2017 Mileage: 45929 WIP No.: 25921

Model: Q7 2.0 TFSI QU (252 bhp) 4MBOI Chassis: WAUZZZ4M4HD044597 Engine: CYR 034825 Dept: U

You have been assisted by :- UB-Jeffery Tan (R) (87)

		Details	Qty	Unit Price	Amount
		BOTH FRONT FENDERS,BOTH FRONT WHEEL ARCH TRIMS AND BOTH FRONT DOORS.			
S	BODYWORK	M:	384.00	1.00	384.00
		TO CARRY OUT DIAGNOSTIC CHECK			
S	BODYWORK	M:	600.00	1.00	600.00
		TO RENEW DAMAGED CONNECTOR HOUSINGS.			
S	BODYWORK	M:	800.00	1.00	800.00
		TO RENEW REAR SEAT BELTS AND DAMAGED PILLAR TRIMS			
X	A4M0098625	(A)(SK)MOUNT KIT(04/ Less 020%	2.00	66.10	105.76
X	A4M0098615	(A)(SK)ATT.PARTS(04/ Less 020%	1.00	83.30	66.64
X	A4M0805285A	(A)(SK)COVER(04/10/2 Less 020%	1.00	88.80	71.04
X	A4M0121283CE	(A)(SK)AIR DUCT(04/1 Less 020%	1.00	23.30	18.64
X	A4M0121284CE	(A)(SK)AIR DUCT(04/1 Less 020%	1.00	23.30	18.64
X	A4M0129510D	(A)(SK)AIR DUCT(04/1 Less 020%	1.00	120.00	96.00
X	A4M0880201N 6PS	(A)(SK)AIRBAG(TECH) Less 020%	1.00	3211.00	2,568.80
X	A4M0880204F	(A)(SK)AIRBAG(TECH) Less 020%	1.00	4075.00	3,260.00
X	A4M0880741H	(A)(G)AIRBAG(TECH) 0 Less 020%	1.00	1744.00	1,395.20
X	A4M0880742H	(A)(G)AIRBAG(TECH) 0 Less 020%	1.00	1744.00	1,395.20
X	A4M0959655E	(A)(SK)MODULE(TECH) Less 020%	1.00	2258.00	1,806.40
X	A4M0857705M V04	(A)(SK)SEAT BELT(TEC Less 020%	1.00	1812.00	1,449.60
X	A4M0857706L V04	(A)(SK)SEAT BELT 04/ Less 020%	1.00	1812.00	1,449.60
X	A4M2857001H 24A	(A)(G)DASHBOARD(TECH Less 020%	1.00	4426.00	3,540.80
X	A4M0867505 W01	(A)(SK)ROOFLINING(TE Less 020%	1.00	3284.00	2,627.20
X	A4M0853140B 9B9	(V)(G)CAP(04/10/2018 Less 020%	1.00	118.50	94.80
X	A4M0807283B	(A)(SK)GUIDE 09/10/2 Less 020%	1.00	37.00	29.60
X	A4M0807611D	(A)(SK)PLATE 09/10/2 Less 020%	1.00	179.50	143.60
X	A4M0807241B 4W3	(A)(SK)COVER 09/10/2 Less 020%	1.00	33.10	26.48
X	A4M0807749B	(A)(SK)COVER 09/10/2 Less 020%	1.00	29.90	23.92
X	A4M0807750B	(A)(SK) COVER 09/10/ Less 020%	1.00	29.90	23.92
X	A4M0805700A	(V)(GER)COVER 09/10/ Less 020%	1.00	38.30	30.64
X	A4M0823185D	(A)(SK) CATCH 09/10/ Less 020%	1.00	107.50	86.00
X	A4M0823186D	(A)(SK)CATCH 09/10/2 Less 020%	1.00	107.50	86.00
X	A4M0823509B	(A)(SK) LOCK 09/10/2 Less 020%	2.00	194.00	310.40

Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 3 14:04

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85014023

Date : 15/07/2019

Order : SLN3721S

Term : 30

Account: A0006 (T 0)

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No: SLN3721S (V 33384) Regn Date: 28/04/2017 Mileage: 45929 WIP No.: 25921

Model: Q7 2.0 TFSI QU (252 bhp) 4MB0I Chassis: WAUZZZ4M4HD044597 Engine: CYR 034825 Dept: U

You have been assisted by :- UB-Jeffery Tan (R) (87)

		Details		Qty	Unit Price	Amount
X	A4M0823531B	(A)(SK) CABLE 09/10/	Less 020%	1.00	79.40	63.52
X	A4M0823661D	(A)(SK)LEVER 09/10/2	Less 020%	1.00	11.80	9.44
X	A4M0820536A	(A)(SK) BRACKET 09/1	Less 020%	1.00	3.70	2.96
X	A4M0863825A	(A)(SK) SILENCER 09/	Less 020%	1.00	312.00	249.60
X	A4M0854327B 01C	(A)(SK) Strip 09/10/	Less 020%	1.00	82.00	65.60
X	A4M0854328B 01C	(A)(SK) Strip 09/10/	Less 020%	1.00	82.00	65.60
X	A4M0971095AF	(A)(SK) HARNESS 09/1	Less 020%	1.00	564.50	451.60
X	A4M0955970B	(A)(SK)HOSE 09/10/20	Less 020%	1.00	82.10	65.68
X	A4M0121285B	(A)(SK) AIR DUCT 09/	Less 020%	1.00	34.50	27.60
X	A4M0121286A	(A)(SK) AIR DUCT 09/	Less 020%	1.00	34.50	27.60
X	A8W0121207A	(A)(SK)COWL 09/10/20	Less 020%	1.00	262.00	209.60
X	A8W0959455K	(A)(SK)ELECTRIC F 09	Less 020%	1.00	1415.00	1,132.00
X	A8W0959455B	(A)(SK)ELECTRIC F 09	Less 020%	1.00	1609.00	1,287.20
X	A7P0121276	(A)(SK) GROMMET 09/1	Less 020%	2.00	8.20	13.12
X	A4M0951210	(A)(SK) HORN 09/10/2	Less 020%	1.00	200.00	160.00
X	A4M0821169B	(A)(SK) SEAL 09/10/2	Less 020%	1.00	52.90	42.32
X	A4M0821170B	(A)(SK) SEAL 09/10/2	Less 020%	1.00	52.90	42.32
X	A4M0823629	(A)(SK) COVER 09/10/	Less 020%	1.00	4.20	3.36
X	A4M0823630	(A)(SK) COVER 09/10/	Less 020%	1.00	4.20	3.36
X	A8V0973803	(V)(GER) HOUSING 10/	Less 020%	1.00	13.70	10.96
X	A4M0955101A	CYLINDER	Less 020%	1.00	174.00	139.20
X	A4M0955102A	CYLINDER	Less 020%	1.00	174.00	139.20
X	A4M0867245F W01	(A)(SK)LINING	Less 020%	1.00	424.00	339.20
X	A4M0867246F W01	(A)(SK)LINING	Less 020%	1.00	424.00	339.20
X	A4M0857811B V04	(A)(SK)SEAT BELT	Less 020%	1.00	958.50	766.80
X	A4M0857812B V04	(A)(SK)SEAT BELT	Less 020%	1.00	958.50	766.80
X	A4M0867839D W01	(A)(SK)TRIMPANLEG	Less 020%	1.00	250.00	200.00
X	A8X0971259	(V)(G)HOUSING(TECH)	Less 020%	1.00	233.00	186.40
X	A8D0973822	(V)(SK)HOUSING(TECH)	Less 020%	1.00	11.20	8.96
X	A4M0971192F	(V)(SK)HARNESS(TECH)	Less 020%	1.00	360.00	288.00
X	A8W1971581	(V)(G)HOUSING(TECH)	Less 020%	1.00	74.80	59.84
X	A8R0857608D EP5	(V)(SK)HANDLE	Less 020%	1.00	124.00	99.20
X	A8W1971581B	(V)(SK)HOUSING	Less 020%	1.00	72.40	57.92
X	A8W1971581B	(V)(G)HOUSING	Less 020%	1.00	72.40	57.92

Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 4 14:04

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85014023

Date : 15/07/2019

Order : SLN3721S

Term : 30

Account: A0006 (T 0)

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No: SLN3721S (V 33384) Regn Date: 28/04/2017 Mileage: 45929 WIP No.: 25921

Model: Q7 2.0 TFSI QU (252 bhp) 4MBOI Chassis: WAUZZZ4M4HD044597 Engine: CYR 034825 Dept: U

You have been assisted by :- UB-Jeffery Tan (R) (87)

		Details		Qty	Unit Price	Amount
X	A4M0867233F WOI	(A)(SK)LINING(22/10/	Less 020%	1.00	345.50	276.40
X	A4M0867234F WOI	(A)(SK)LINING(22/10/	Less 020%	1.00	345.50	276.40
X	A8W0915459G	(A)(SK)FUSE UNIT(22/	Less 020%	1.00	470.00	376.00
X	A8W1971581	(V)(G)HOUSING(18/10/	Less 020%	2.00	74.80	119.68
X	A4M0133615B	(V)(SK)PIN	Less 020%	2.00	5.40	8.64
X	A4M0857186 EP5	006518/(V)(SK)TRIM	Less 020%	1.00	34.90	27.92
X	A4M0857185 EP5	006518/(V)(SK)TRIM	Less 020%	1.00	34.90	27.92
X	A4M0133615	006518/(V)(SK)PIN	Less 020%	2.00	5.40	8.64
X	AN 10752401	006518/BOLT	Less 020%	2.00	1.70	2.72
X	A4M0807233C	PLATE	Less 020%	1.00	237.00	189.60
X	A4M0853651J MX3	GRILLE	Less 020%	1.00	2027.00	1,621.60
X	A4M0941774D	(A)(SK)HEADLIGHT(04/	Less 020%	1.00	8849.00	7,079.20
X	A4M0941773D	HEADLIGHT	Less 020%	1.00	8849.00	7,079.20
X	A4M0821105D	(A)(SK)FENDER LH(04/	Less 020%	1.00	1422.00	1,137.60
X	A4M0853717A GRU	COVER	Less 020%	1.00	501.50	401.20
X	A4M0853718A GRU	COVER	Less 020%	1.00	501.50	401.20
X	A4M0821106D	FENDER RH	Less 020%	1.00	1422.00	1,137.60
X	A4M0807081	COVER	Less 020%	1.00	112.00	89.60
X	A4M0807733D KA8	UNDERRUN	Less 020%	1.00	699.50	559.60
X	A4M0816421B	CONDENSER	Less 020%	1.00	847.00	677.60
X	A8W0121251AK	RADIATOR	Less 020%	1.00	629.50	503.60
X	A4M0145805H	(V)(SK)(LAST)COOLER	Less 020%	1.00	818.00	654.40
X	A4M0805594B	(A)(SK)CARRIER(04/10	Less 020%	1.00	1048.00	838.40
X	A4M0807550D	FOAM INSER	Less 020%	1.00	147.00	117.60
X	A4M0807109C	(A)(SK)BRACKET(04/10	Less 020%	1.00	753.00	602.40
X	AG A13040M2	PREMIX-COOLANT	Less 020%	4.00	20.40	65.28
X	A4M0823029A	(A)(SK)HOOD(04/10/20	Less 020%	1.00	4295.00	3,436.00
X	A4M0807065C GRU	COVER	Less 020%	1.00	2252.00	1,801.60
X	A000979026EA	WIRES (TECH)	Less 020%	1.00	43.50	34.80
X	A3D0260749C	WASHER	Less 020%	2.00	3.80	6.08
X	A4E0260749A	WASHER	Less 020%	2.00	3.20	5.12
X	EC-801Y4910J-EP P2	ERP LABEL/STICKER 2G	Less 020%	1.00	4.00	3.20
X	A4M0121275A	MOUNTING	Less 020%	2.00	7.80	12.48
X	A4M0121268A	MOUNTING	Less 020%	2.00	10.90	17.44

Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 5 14:04

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85014023
Date : 15/07/2019
Order : SLN3721S
Term : 30

Account: A0006 (T 0)

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No: SLN3721S (V 33384) Regn Date: 28/04/2017 Mileage: 45929 WIP No.: 25921

Model: Q7 2.0 TFSI QU (252 bhp) 4MB01 Chassis: WAUZZZ4M4HD044597 Engine: CYR 034825 Dept: U

You have been assisted by :- UB-Jeffery Tan (R) (87)

		Details		Qty	Unit Price	Amount
X	A4M0807158D	(A)(SK) AIR DUCT 09/	Less 020%	1.00	56.60	45.28
X	A4M0807333	(A)(SK)SUPPORT(04/10	Less 020%	1.00	30.40	24.32
X	A4M0807334	SUPPORT	Less 020%	1.00	30.40	24.32
X	A4M0807157D	(A)(SK)AIR DUCT 09/1	Less 020%	1.00	56.60	45.28
X	A4M0821132C	SUPPORT	Less 020%	1.00	89.30	71.44
X	A4M0807284B	GUIDE	Less 020%	1.00	37.00	29.60
X	A4M0823301	(A)(SK)HINGE 09/10/2	Less 020%	1.00	72.60	58.08
X	A4M0823302	(A)(SK) HINGE 09/10/	Less 020%	1.00	72.60	58.08
X	A4M0805607	(A)(SK) MOUNTING 09/	Less 020%	1.00	102.50	82.00
X	A4M0805608	(A)(SK)MOUNTING 09/1	Less 020%	1.00	102.50	82.00
X	A4M0821131C	(A)(SK) SUPPORT (09/	Less 020%	1.00	88.80	71.04
X	A4M0121095	BOLT	Less 020%	2.00	2.20	3.52
X	A7P0121365	SLEEVE	Less 020%	2.00	7.20	11.52
X	A4M0857819	(V)(SK)Adjuster(TECH	Less 020%	2.00	153.00	244.80
X	A4M0853231B	BRACKET	Less 020%	1.00	8.40	6.72
X	A4M0853169B	(V)(G)COVER(04/10/20	Less 020%	1.00	53.50	42.80
X	A4H0823543	COVER	Less 020%	1.00	8.60	6.88
X	A4M0854451	CLIP	Less 020%	6.00	2.10	10.08
X	A191853586C	GROMMET	Less 020%	26.00	2.20	45.76
X	A8T0823433B	(A)(SK)BUMPER(04/10/	Less 020%	2.00	8.30	13.28
X	A4M0805163	CLIP	Less 020%	10.00	2.10	16.80
X	A7P6853910A	CLAMP	Less 020%	2.00	4.00	6.40
X	A8X0867189	CLIP	Less 020%	10.00	0.70	5.60
X	A4M0823529E	(A)(SK) BOWD CABLE 0	Less 020%	1.00	50.00	40.00
X	A4M0805286A	COVER	Less 020%	1.00	88.80	71.04
X	A4M0807151A 9B9	(A)(SK) COVER 09/10/	Less 020%	1.00	28.10	22.48
X	A4M0807062E GRU	(A)(SK) FR.SPOILER 0	Less 020%	1.00	183.00	146.40
X	A4M0807061E GRU	FR.SPOILER	Less 020%	1.00	183.00	146.40
X	A5Q0980546A	(A)(SK)CAMERA(04/10/	Less 020%	1.00	1023.00	818.40
X	A4M0807152A 9B9	(A)(SK) COVER 09/10/	Less 020%	1.00	28.40	22.72
X	A4E0955998	GROMMET	Less 020%	1.00	4.20	3.36
X	A4M0807682T 4W3	(A)(SK)GRILL(04/10/2	Less 020%	1.00	260.00	208.00
X	A4M0807681T 4W3	GRILL	Less 020%	1.00	260.00	208.00
X	A5Q0919275C GRU	Sensor	Less 020%	4.00	210.50	673.60

Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 6 14:04

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85014023

Date : 15/07/2019

Order : SLN3721S

Term : 30

Account: A0006 (T 0)

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No: SLN3721S (V 33384) Regn Date: 28/04/2017 Mileage: 45929 WIP No.: 25921

Model: Q7 2.0 TFSI QU (252 bhp) 4MBOI Chassis: WAUZZZ4M4HD044597 Engine: CYR 034825 Dept: U

You have been assisted by :- UB-Jeffery Tan (R) (87)

		Details		Qty	Unit Price	Amount
X	A3C8971582	(V)(G)HOUSING(TECH)	Less 020%	1.00	167.50	134.00
X	A038919081K	SWITCH	Less 020%	1.00	45.20	36.16
X	A4M0959651	(A)(SK)SENSOR(TECH)	Less 020%	3.00	272.50	654.00
X	A000979940	CONNECTOR (WHITE)	Less 020%	20.00	9.00	144.00
X	A3C0973737	HOUSING	Less 020%	1.00	27.20	21.76
X	A3C0973737	HOUSING (TECH)	Less 020%	1.00	27.20	21.76
X	A8P0973722	HOUSING	Less 020%	1.00	35.00	28.00
X	A4D0971992	HOUSING(TECH)	Less 020%	1.00	15.40	12.32
X	A000979020EA	WIRES(TECH)	Less 020%	1.00	20.20	16.16
X	A8K0010520A	PLATE	Less 020%	1.00	11.60	9.28
X	A4M0010515C	(V)(G)STICKER(04/10/	Less 020%	1.00	6.10	4.88
X	A4M0010515C	(V)(GER) STICKER 10/	Less 020%	1.00	6.10	4.88
X	A4M0907397AD	(A)(SK)CTRL UNIT 09/	Less 020%	1.00	657.00	525.60
X	A7PP941572ABZ00	(A)(SK) POWER MOD 09	Less 020%	1.00	694.50	555.60
X	A8U0907463A	(A)(SK) FAN 09/10/20	Less 020%	1.00	344.50	275.60
X	AWHT001308	NUT	Less 020%	4.00	1.20	3.84
X	AWHT004750	RIVET	Less 020%	5.00	2.30	9.20
X	AN 01713113	FUSE(20A)	Less 020%	3.00	1.80	4.32
X	AN 90798808	NUT	Less 020%	4.00	1.10	3.52
X	AN 91186001	(A)(SK) BOLT 09/10/2	Less 020%	4.00	1.60	5.12
X	A4M0823359B	(A)(SK)GASFILSTRU(04	Less 020%	1.00	120.50	96.40
X	A4M0853037C	(A)(SK)COVER(04/10/2	Less 020%	1.00	59.40	47.52
X	A4M0807647B 4W3	GRILLE	Less 020%	1.00	179.50	143.60
X	A4M0823126	(A)(SK)PROTECTION(04	Less 020%	1.00	91.70	73.36

Parts	63,900.56
Labour	0.00
Sublet	18,389.00
Menus	0.00
Lubricant	0.00

Sub-Total	81,089.56
7% GST	5,676.27
Grand Total	86,765.83

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Your Ref: SLN 3721 S

Norah Khai — from
6768 9828 — Telephone +65-
6841 1183 — Telefax +65-
Mobile +65-
Body Repair — Our department
Your Claim Ref
PA/OD/1121/2018/JT — Our Ref
Nov 2018 — Date

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model	:	Audi Q7 2.0 TFSI qu
Vehicle Chassis No.	:	WAUZZZ4M4HD044597
Vehicle Regn No.	:	**SLN 3721 S**
Vehicle Mileage	:	
Vehicle Owner	:	Ms. Wong Shin Yi
Certificate No	:	2100507396-01
Policy Excess	:	**$1,284.00 (incl. of GST)**
Accident Date	:	22nd September 2018
Place	:	Along CTE before Balistier Road exit
Repair Cost	:	$ 86,765.83
WIP No.	:	25921
Repairer's Name	:	Premium Automobiles Pte Ltd

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : _____

Time : _____

Date : 13/11/2018

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Sep 2018		28 Sep 2018 14:07 Edit Adj Rpt	**S$82,289.56** Edit Estimates	**S$82,289.56** View Rpt		**Pending for Survey Report** Cancel Case

Main | Reference | Claim Details | Documents | Show All

CLAIM SUBFOLDER DETAILS **[Created by insurer]**

Insured:	**WONG SHIN YI**, ID: S7832967Z, Tel: +6593374033, Email: WONG.SHINYI@GMAIL.COM		
Vehicle Reg. No.:	**SLN3721S**	Date of Loss:	22/09/2018 09:00 - :59 [**16** Months and **25** Days From LTA Reg Date (Man Yr)]
Claim Type:	**OD** / 1913342376SG	Policy/Cover Note No.:	2100507396 (Comprehensive) Coverage: 28/04/2018 - 27/04/2019
		Excess:	S$1,200.00
Repairer:	**Premium Automobiles Pte Ltd (UBI)** 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	**AIG Asia Pacific Insurance Pte. Ltd. (SG)** - Tel: 65-6419-3000 ... [Handled by **Mohd Zawaye, Norsazani**] Norsazani.Zawaye@aig.com		
Adjuster:	**LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **ADRIAN LING**] ... [**Final Rpt** due 09/10/2018]		
Driver/Custodian:	WONG SHIN YI (39 / Female) , NRIC: S7832967Z, Tel: +6593374033 Email: WONG.SHINYI@GMAIL.COM		

ASSOCIATED MAIL RECEIVED View All | Compose Case Mail

- AIG_SG (03/07/2019): **Alert - Adj Mandate Approved (S$82289.56) - SLN3721S - Claim Handler: Mohd Zaway...**
- AIG_SG (13/02/2019): **Alert - Adj Mandate Maintained - SLN3721S - Claim Handler: Mohd Zawaye, Norsazan...**
- AIG_SG (23/10/2018): **Alert - Adj Mandate Maintained - SLN3721S - Claim Handler: Mohd Zawaye, Norsazan...**
- AIG_SG (01/10/2018): **Alert - Adj Mandate Approved (S$85000.00) - SLN3721S - Claim Handler: Mohd Zaway...**
- AIG_SG (01/10/2018): **SLN3721S / OD / 22/09/2018 / Coverage & Excess update**

ALL ASSOCIATED TASKS View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?

No results.

Claim Documents

***SLN3721S (1913342376SG)**
OD
Sep 22 2018 9:00AM
[WONG SHIN YI]
Premium Automobiles Pte Ltd

Upload Documents | Upload Photos | Compose New Letter | Upload Video | Upload Audio

View: View in Browser

Assessment Reports — 1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/09/18 16:28	**Adjuster Immediate Advice**	1	Load HTM	
2	22/10/18 12:08	**Adjuster Immediate Advice**	1	Load HTM	

Photos/Images — 3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/09/18 16:05	**General View**	1	Load JPG	☑
2	28/09/18 16:05	**General View**	1	Load JPG	☑
3	28/09/18 16:05	**General View**	1	Load JPG	☑
4	28/09/18 16:05	**General View**	1	Load JPG	☑
5	28/09/18 16:05	**General View**	1	Load JPG	☑
6	28/09/18 16:05	**General View**	1	Load JPG	☑
7	28/09/18 16:05	**General View**	1	Load JPG	☑
8	28/09/18 16:05	**General View**	1	Load JPG	☑
9	28/09/18 16:05	**General View**	1	Load JPG	☑
10	28/09/18 16:05	**General View**	1	Load JPG	☑
11	28/09/18 16:05	**General View**	1	Load JPG	☑
12	28/09/18 16:05	**General View**	1	Load JPG	☑
13	28/09/18 16:05	**General View**	1	Load JPG	☑
14	28/09/18 16:05	**General View**	1	Load JPG	☑
15	28/09/18 16:05	**General View**	1	Load JPG	☑
16	28/09/18 16:05	**General View**	1	Load JPG	☑
17	28/09/18 16:05	**General View**	1	Load JPG	☑
18	28/09/18 16:05	**General View**	1	Load JPG	☑
19	28/09/18 16:05	**General View**	1	Load JPG	☑
20	28/09/18 16:05	**General View**	1	Load JPG	☑
21	28/09/18 16:05	**General View**	1	Load JPG	☑
22	28/09/18 16:05	**General View**	1	Load JPG	☑
23	28/09/18 16:05	**General View**	1	Load JPG	☑
24	28/09/18 16:05	**General View**	1	Load JPG	☑
25	28/09/18 16:05	**General View**	1	Load JPG	☑
26	28/09/18 16:05	**General View**	1	Load JPG	☑
27	28/09/18 16:05	**General View**	1	Load JPG	☑
28	28/09/18 16:05	**General View**	1	Load JPG	☑
29	28/09/18 16:05	**General View**	1	Load JPG	☑
30	28/09/18 16:05	**General View**	1	Load JPG	☑
31	28/09/18 16:05	**General View**	1	Load JPG	☑
32	28/09/18 16:05	**General View**	1	Load JPG	☑
33	28/09/18 16:05	**General View**	1	Load JPG	☑
34	28/09/18 16:05	**General View**	1	Load JPG	☑

Assessment Reports			1 per page		☑
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
35	28/09/18 16:05	General View		Load JPG	☑
36	28/09/18 16:06	General View		Load JPG	☑
37	28/09/18 16:06	General View		Load JPG	☑
38	28/09/18 16:06	General View		Load JPG	☑
39	28/09/18 16:06	General View		Load JPG	☑
40	28/09/18 16:06	General View		Load JPG	☑
41	28/09/18 16:06	General View		Load JPG	☑
42	28/09/18 16:06	General View		Load JPG	☑
43	28/09/18 16:06	General View		Load JPG	☑
44	28/09/18 16:06	General View		Load JPG	☑
45	28/09/18 16:06	General View		Load JPG	☑
46	28/09/18 16:06	General View		Load JPG	☑
47	28/09/18 16:06	General View		Load JPG	☑
48	28/09/18 16:06	General View		Load JPG	☑
49	28/09/18 16:06	General View		Load JPG	☑
50	28/09/18 16:06	General View		Load JPG	☑
51	28/09/18 16:06	General View		Load JPG	☑
52	28/09/18 16:06	General View		Load JPG	☑
53	28/09/18 16:06	General View		Load JPG	☑
54	28/09/18 16:06	General View		Load JPG	☑
55	28/09/18 16:06	General View		Load JPG	☑
56	28/09/18 16:06	General View		Load JPG	☑
57	28/09/18 16:06	General View		Load JPG	☑
58	28/09/18 16:06	General View		Load JPG	☑
59	28/09/18 16:06	General View		Load JPG	☑
60	28/09/18 16:06	General View		Load JPG	☑
61	28/09/18 16:06	General View		Load JPG	☑
62	28/09/18 16:06	General View		Load JPG	☑
63	28/09/18 16:06	General View		Load JPG	☑
64	28/09/18 16:06	General View		Load JPG	☑
65	28/09/18 16:06	General View		Load JPG	☑
66	28/09/18 16:06	General View		Load JPG	☑
67	28/09/18 16:06	General View		Load JPG	☑
68	28/09/18 16:06	General View		Load JPG	☑
69	28/09/18 16:06	General View		Load JPG	☑
70	28/09/18 16:06	General View		Load JPG	☑
71	28/09/18 16:06	General View		Load JPG	☑
72	28/09/18 16:06	General View		Load JPG	☑
73	28/09/18 16:06	General View		Load JPG	☑
74	28/09/18 16:06	General View		Load JPG	☑
75	28/09/18 16:06	General View		Load JPG	☑
76	28/09/18 16:06	General View		Load JPG	☑
77	28/09/18 16:06	General View		Load JPG	☑
78	28/09/18 16:06	General View		Load JPG	☑
79	28/09/18 16:06	General View		Load JPG	☑
80	28/09/18 16:06	General View		Load JPG	☑
81	28/09/18 16:06	General View		Load JPG	☑
82	28/09/18 16:06	General View		Load JPG	☑
83	28/09/18 16:06	General View		Load JPG	☑
84	28/09/18 16:06	General View		Load JPG	☑

Assessment Reports			1 per page		☑
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
85	28/09/18 16:06	General View	1	Load JPG	☑
86	28/09/18 16:06	General View	1	Load JPG	☑
87	28/09/18 16:06	General View	1	Load JPG	☑
88	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
89	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
90	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
91	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
92	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
93	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
94	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
95	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
96	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
97	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
98	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
99	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
100	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
101	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
102	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
103	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
104	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
105	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
106	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
107	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
108	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
109	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
110	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
111	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
112	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
113	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
114	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
115	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
116	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
117	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
118	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
119	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
120	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
121	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
122	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
123	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
124	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
125	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
126	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
127	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
128	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
129	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
130	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
131	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
132	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
133	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
134	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑

Assessment Reports			1 per page		☑
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
135	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
136	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
137	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
138	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
139	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
140	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
141	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
142	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
143	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
144	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
145	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
146	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
147	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
148	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
149	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
150	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
151	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
152	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
153	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
154	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
155	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
156	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
157	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
158	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
159	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
160	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
161	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
162	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
163	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
164	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
165	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
166	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
167	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
168	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
169	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
170	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
171	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
172	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
173	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
174	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
175	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
176	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
177	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
178	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
179	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
180	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
181	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
182	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
183	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
184	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑

Assessment Reports			1 per page		☑
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
185	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
186	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
187	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
188	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
189	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
190	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
191	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
192	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
193	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
194	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
195	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
196	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
197	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
198	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
199	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
200	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
201	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
202	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
203	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
204	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
205	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
206	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
207	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
208	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
209	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
210	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
211	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
212	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
213	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
214	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
215	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
216	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
217	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
218	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
219	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
220	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
221	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
222	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
223	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
224	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
225	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
226	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
227	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
228	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
229	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
230	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
231	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
232	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
233	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑
234	13/02/19 15:52	Reinspection Photo	1	Load JPG	☑

Assessment Reports			1 per page		☑
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
235	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
236	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
237	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
238	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
239	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
240	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
241	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
242	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
243	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
244	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
245	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
246	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
247	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
248	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
249	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
250	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
251	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
252	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
253	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
254	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
255	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
256	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
257	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
258	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
259	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
260	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
261	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
262	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
263	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
264	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
265	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
266	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
267	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
268	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
269	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
270	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
271	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
272	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
273	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
274	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
275	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
276	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
277	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
278	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
279	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
280	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
281	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
282	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
283	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑
284	13/02/19 15:52	**Reinspection Photo**	1	Load JPG	☑

Assessment Reports			1 per page		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
285	13/02/19 15:52	Reinspection Photo		Load JPG	
286	08/05/19 17:59	Reinspection Photo		Load JPG	
287	08/05/19 17:59	Reinspection Photo		Load JPG	
288	08/05/19 17:59	Reinspection Photo		Load JPG	
289	08/05/19 17:59	Reinspection Photo		Load JPG	

Documentation			1 per page		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/09/18 16:10	Certificate of Insurance		Load PDF	
2	28/09/18 16:10	Driver's Driving License		Load PDF	
3	28/09/18 16:10	Marked estimate		Load PDF	
4	28/09/18 16:10	Singapore Accident Statement		Load PDF	
5	22/10/18 13:58	SUPPLEMANTARY		Load PDF	
6	28/05/19 15:43	Supplementary		Load PDF	
7	25/07/19 11:31	Workshop Invoice		Load PDF	
8	25/07/19 11:31	Discharge Voucher		Load PDF	

Linked Accident Report Documents

View View in Browser

Assessment Reports			1 per page		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	22/09/18 11:45	Accident Statement		Load HTM	

Photos/Images			3 per page		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	22/09/18 11:42	Accident Photo		Load JPG	
2	22/09/18 11:42	Accident Photo		Load JPG	
3	22/09/18 11:42	Accident Photo		Load JPG	
4	22/09/18 11:42	Accident Photo		Load JPG	
5	22/09/18 11:42	Accident Photo		Load JPG	
6	22/09/18 11:42	Accident Photo		Load JPG	
7	22/09/18 11:42	Accident Photo		Load JPG	
8	22/09/18 11:42	Accident Photo		Load JPG	
9	22/09/18 11:42	Accident Photo		Load JPG	
10	22/09/18 11:42	Accident Photo		Load JPG	
11	22/09/18 11:42	Accident Photo		Load JPG	
12	22/09/18 11:42	Accident Photo		Load JPG	
13	22/09/18 11:42	Accident Photo		Load JPG	
14	22/09/18 11:42	Accident Photo		Load JPG	
15	22/09/18 11:42	Accident Photo		Load JPG	
16	22/09/18 11:42	Accident Photo		Load JPG	
17	22/09/18 11:42	Accident Photo		Load JPG	
18	22/09/18 11:42	Accident Photo		Load JPG	
19	22/09/18 11:42	Accident Photo		Load JPG	

Documentation			1 per page		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	22/09/18 11:30	Sketch Plan		Load JPG	
2	22/09/18 11:30	Sketch Plan #2		Load JPG	

Documents Checklist

DOCUMENTS CHECKLIST Reset | Save | Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18017655/ATBE2
Date: 25/07/2019

REFERENCE

Insured/Claimant:	WONG SHIN YI	Policy No:	2100507396		
Date of Loss:	22/09/2018	Nature of Claim:	OD	Claim No:	1913342376SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	**SLN3721S**		
Make & Model:	AUDI Q7, 2.0 TFSI QU (A)	Engine No:	CYR034825
Reg. Date:	28/04/2017 (Man. Year: 2017)	Chassis No:	WAUZZZ4M4HD044597
Colour:	Black	Odometer:	32771 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S$232,000.00		
Sum Insured (S$):	**Market Value/New Car Price**		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	255/55 R19	Rear Tyre Size:	255/55 R19
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	85,757.20	63,925.56	21,831.64	25.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	36,304.00	18,364.00	17,940.00	49.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S$)	**122,061.20**	**82,289.56**	**39,771.64**	**32.58**
- Excess (S$)	1,200.00	1,200.00	0.00	0.00
(S$)	120,861.20	81,089.56	39,771.64	32.91
+ GST 7.00/7.00% (S$)	8,460.28	5,676.27	2,784.01	32.91
Nett Amount (S$)	**129,321.48**	**86,765.83**	**42,555.65**	**32.91**

INSPECTION

Date of Assignment:	28/09/2018		
Date Inspected:	27/09/2018	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	33.0 days		

Adjuster: ADRIAN LING **Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,252.00 FS	*1,801.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	382.00 FS	*- FS
3	2		*FRONT BUMPER AIR GUIDE - LH / RH	Deformed	114.00 FS	*90.56 FS
4	2		*FRONT BUMPER END CA - LH / RH	Necessary	60.00 FS	*47.84 FS
5	1		*FRONT BUMPER LOWER CENTRE GRILLE	Cracked	180.00 FS	*143.60 FS
6	1		*FRONT BUMPER UNDERRUN BAR	Deformed	700.00 FS	*559.60 FS
7	1		*FRONT BUMPER CLOSING ELEMENT	Torn	180.00 FS	*143.60 FS
8	2		*FRONT BUMPER SPOILER - LH / RH	Damaged	366.00 FS	*292.80 FS
9	1		*RADIATOR GRILLE	Cracked	2,027.00 FS	*1,621.60 FS
10	1		*FRONT BUMPER UPPER CLOSING ELEMENT	Damaged	237.00 FS	*189.60 FS
11	1		*RADIATOR GRILLE COVER	Cracked	60.00 FS	*47.52 FS
12	1		*RADIATOR GRILLE UPPER COVER	Cracked	54.00 FS	*42.80 FS
13	1		*RADIATOR GRILLE OVER CAP	Distorted	94.80 FS	*94.80 FS
14	1		*RADIATOR BRACKET	Distorted	9.00 FS	*6.72 FS
15	1		*FRONT CAMERA	Damaged	1,023.00 FS	*818.40 FS
16	1		*ADAPTER CABLE LOOM	Not Necessary	358.00 FS	*- FS
17	4		*FRONT SENSOR	Damaged	842.00 FS	*673.60 FS
18	4		*FRONT SENSOR SEALRING	Not Necessary	14.00 FS	*- FS
19	1		*FOAM FILLER PIECE	Cracked	147.00 FS	*117.60 FS
20	1		*FRONT BUMPER CARRIER	Bent	753.00 FS	*602.40 FS
21	2		*FRONT BUMPER SUPPORT - LH / RH	Damaged	62.00 FS	*48.64 FS
22	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Necessary	74.00 FS	*59.20 FS
23	1		*FRONT BUMPER COVER	Cracked	112.00 FS	*89.60 FS
24	2		*FRONT FENDER - LH / RH	Buckled	2,844.00 FS	*2,275.20 FS
25	2		*FRON FENDER ATTACHEMENT PARTS	Necessary	108.00 FS	*105.76 FS
26	2		*FRONT FENDER BRACKET - LH / RH	Not Necessary	112.00 FS	*- FS
27	2		*FRONT FENDER UPPER BRACKET - LH / RH	Not Necessary	106.00 FS	*- FS
28	2		*FRONT FENDER BRACE - LH / RH	Bent	179.00 FS	*142.48 FS
29	2		*FRONT WHEEL HOUSING LINER - LH / RH	Not Necessary	430.00 FS	*- FS
30	2		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	93.00 FS	*- FS
31	2		*FRONT WHEEL COVER - LH / RH	Necessary	1,004.00 FS	*802.40 FS
32	2		*LED HEADLIGHT	Cracked	17,698.00 FS	*14,158.40 FS
33	2		*HEADLIGHT CONTROL UNIT - LH / RH	Damaged	1,314.00 FS	*525.60 FS
34	2		*HEADLIGHT POWER MODULE	Damaged	1,389.00 FS	*555.60 FS
35	2		*HEADLAMPS FAN	Damaged	689.00 FS	*275.60 FS
36	2		*HEADLIGHT HOSE - LH / RH	Not Necessary	66.00 FS	*- FS
37	2		*COMPENSATING PIECE	Not Necessary	70.00 FS	*- FS
38	2		*HEADLIGHT LIFT CYLINDER - LH / RH	Damaged	348.00 FS	*278.40 FS
39	1		*HEADLIGHT WASHER HOSE	Damaged	83.00 FS	*65.68 FS
40	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Cracked	520.00 FS	*416.00 FS
41	2		*FRONT BUMPER SIDE GRILLE END COVER LH / RH	Damaged	58.00 FS	*45.20 FS
42	1		*BONNET	Dented	4,295.00 FS	*3,436.00 FS
43	1		*BONNET ATTACHEMENT PARTS	Necessary	84.00 FS	*66.64 FS
44	2		*BONNET LID HINGE - LH / RH	Bent	146.00 FS	*116.16 FS
45	1		*GAS FILLED STRUT	Bent	121.00 FS	*96.40 FS
46	2		*STOP BUFFER	Necessary	17.00 FS	*13.28 FS
47	1		*BONNET IMPACT PROTECTION	Necessary	92.00 FS	*73.36 FS
48	2		*HEADLAMPS COVER - LH / RH	Cracked	178.00 FS	*142.08 FS
49	1		*LED HEADLIGHT TRIM COVER - RH	Damaged	39.00 FS	*30.64 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	2		*LED HEADLIGHT LOCKING MECHANISM	Not Necessary	14.00 FS	*- FS
51	2		*BONNET STRIKER - LH / RH	Bent	214.00 FS	*172.00 FS
52	1		*BONNET BOWDEN CABLE	Damaged	50.00 FS	*40.00 FS
53	2		*BONNET LID LOCK WITH MICRO	Damaged	383.00 FS	*310.40 FS
54	1		*BONNET LID LOCK CABLE	Damaged	66.00 FS	*63.52 FS
55	1		*RELEASE LEVER	Necessary	12.00 FS	*9.44 FS
56	1		*SIGN CAUTION	Necessary	12.00 FS	*9.28 FS
57	1		*LOCK CARRIER WITH RADIAOT	Cracked	1,048.00 FS	*838.40 FS
58	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Repeated	520.00 FS	*- FS
59	2		*SIDE MEMBER TRIM - LH / RH	Not Necessary	852.00 FS	*- FS
60	2		*FRAME RAIL END LOWER BRACKET - LH / RH	Not Necessary	116.00 FS	*- FS
61	2		*FRAME RAIL END BRACKET - LH / RH	Not Necessary	92.00 FS	*- FS
62	2		*AIR DUCT - LH / RH	Cracked	48.00 FS	*37.28 FS
63	2		*RADIATOR SUPPORT AIR DUCT - LH / RH	Deformed	70.00 FS	*55.20 FS
64	1		*A/C CONDENSER	Dented	847.00 FS	*677.60 FS
65	1		*RADIATOR	Bent	630.00 FS	*503.60 FS
66	2		*RADIATOR LOWER RUBBER BUSH	Necessary	19.00 FS	*17.44 FS
67	4		*COOLANT CONCENTRATE 1.5 LTR	Necessary	133.00 FS	*65.28 FS
68	1		*TWIN FAN RING	Cracked	261.00 FS	*209.60 FS
69	1		*RADIATOR FAN WITH CONTROL UNIT	Damaged	1,609.00 FS	*1,132.00 FS
70	1		*AIR FILTER	Not Necessary	585.00 FS	*- FS
71	1		*AIR FILTER COVER	Not Necessary	416.00 FS	*- FS
72	1		*INTAKE AIR DUCT	Cracked	120.00 FS	*96.00 FS
73	1		*CHARGE AIR COOLER	Bent	797.00 FS	*654.40 FS
74	2		*WATER DEFLECTOR STRIP - LH / RH	Damaged	164.00 FS	*131.20 FS
75	1		*WATER BOX COVER	Not Necessary	149.00 FS	*- FS
76	1		*AIR BAG UNIT FOR STEERING WHEL	Activated	3,211.00 FS	*2,568.80 FS
77	1		*AIR BAG UNIT FOR PASSENGER SIDE	Activated	4,075.00 FS	*3,260.00 FS
78	2		*HEAD AIR BAG UNIT - LH / RH	Activated	3,488.00 FS	*2,790.40 FS
79	1		*AIR BAG CONTROL UNIT	Activated	2,258.00 FS	*1,806.40 FS
80	3		*AIR BAG CRASH SENSOR	Activated	818.00 FS	*654.00 FS
81	2		*ADAPTER CABLE LOOM	Not Necessary	91.00 FS	*- FS
82	1		*CENTRAL PROTECTION	Deformed	470.00 FS	*376.00 FS
83	2		*THREE POINT SEAT BELT - LH / RH	Activated	3,624.00 FS	*2,899.20 FS
84	2		*SEAT BELT HEIGHT ADJUSTER	Damaged	306.00 FS	*244.80 FS
85	1		*DASH BOARD	Torn	4,426.00 FS	*3,540.80 FS
86	1		*MOULDED HEADLINER	Crumpled	3,284.00 FS	*2,627.20 FS
87	2		*A-PILLAR TRIM - LH / RH	Deformed	692.00 FS	*552.80 FS
88	2		*FRONT GRAB HANDLE FOLDING	Not Necessary	248.00 FS	*- FS
89	2		*REAR GRAB HANDLE FOLDING - LH / RH	Damaged	248.00 FS	*99.20 FS
90	1		*FRONT PLATE NO.	Bent	25.00 FS	*25.00 FS
91	1		*SUNDRIES	Necessary	1,000.00 FS	*320.08 FS
92	2		*REAR SEAT BELT - LH / RH	Activated	1,533.60 FS	*1,533.60 FS
93	1		*ROOF TRIM - REAR	Deformed	200.00 FS	*200.00 FS
94	2		*D-PILLAR TRIM - LH / RH	Deformed	678.40 FS	*678.40 FS
95	1		*FLATCONTACT HOUSING WITH CABLE	Distorted	134.00 FS	*134.00 FS
96	1		*ROUND CONNECTOR HSG WITH CABLE	Distorted	186.40 FS	*186.40 FS
97	1		*CONNECTOR HOUSING	Cracked	10.96 FS	*10.96 FS
98	1		*SET WIRE REPAIR	Necessary	16.16 FS	*16.16 FS
99	2		*CONNECTOR HOUSING	Not Necessary	55.00 FS	*- FS
100	1		*ADAPTER CABLE LOOM	Distorted	288.00 FS	*288.00 FS
101	1		*CONNECTOR HOUSING	Cracked	8.96 FS	*8.96 FS
102	1		*SET WIRE REPAIR	Necessary	34.80 FS	*34.80 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
103	1		*CONNECTOR HOUSING	Necessary	12.32 FS	*12.32 FS
104	1		*OIL PRESSURE SWITCH	Damaged	36.16 FS	*36.16 FS
105	2		*ROUND CONNECTOR HSG WITH CABLE	Cracked	119.68 FS	*119.68 FS
106	20		*BUTT CONNECTOR FOR WIRE	Necessary	144.00 FS	*144.00 FS
107	2		*ROUND CONNECTOR HSG WITH CABLE	Distorted	115.84 FS	*115.84 FS
108	2		*HEADLIGHT MOUNTING - LH / RH	Cracked	164.00 FS	*164.00 FS
109	1		*TOW EYE COVER	Scratched	26.48 FS	*26.48 FS
110	2		*BONNET HINGE COVER - LH / RH	Cut	84.64 FS	*84.64 FS
111	1		*SET FRONT BUMPER WIRING	Cut	451.60 FS	*451.60 FS
112	1		*RADIATOR FAN WITH CONTROL UNIT	Cracked	1,287.20 FS	*1,287.20 FS
113	1		*HORN - RH	Cracked	160.00 FS	*160.00 FS
114	1		*HORN CONNECTOR - RH	Cracked	21.76 FS	*21.76 FS
115	1		*TRIM PLATE FOR SEALT BELT RH	Necessary	27.92 FS	*27.92 FS
116	1		*TRIM PLATE FOR SEALT BELT LH	Necessary	27.92 FS	*27.92 FS
117	1		*AIR CONTINIONER STICKER	Necessary	7.00 FS	*4.88 FS
118	1		*BONNET SOUND ABSORBER	Deformed	249.60 FS	*249.60 FS
				Total Parts (S$)	**85,757.20**	**63,925.56**

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY FRONT PARKING AID AND FRONT VEHICLE ENVIROMENT CAMERA ASSY. INSPECT FOR DAMAGES AND RENEW ACCORDINGLY	New	580.00	580.00
2	TO REMOVE AND RENEW, AIRCON CONDENSER, TURBOCOOLER, RADIATORS. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURIES COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,400.00	1,400.00
3	TO REMOVE CENTER CONSOLE, INSTRUMENT PANELS AND CLOSTERS. RENEW DASHBOARD, BOTH FRONTAL AIR BAGS, SEAT BELTS, PILLAR TRIMS, ROOF LINING, BOTH CURTAIN AIR BAGS, CONTROL UNIT AND BATTERY CENTRAL PROTECTION	New	3,600.00	3,600.00
4	TO REMOVE AND REINSTALL ENGINE ASSY WITH SUBFRAME TO FACILITATE CAR-O-LINER REPAIRS	New	3,200.00	0.00
5	TO REMOVE AND REINSTALL FRONT SUSPENSION ASSY WITH SUBFRAME TO FACILITATE CAR-O-LINER REPAIRS	New	2,800.00	0.00
6	TO PLACE VEHICLE ON CAR-O-LINER	New	2,400.00	0.00
7	TO DISMANTLE FRONT BUMPER, BONNET AND BOTH FRONT FENDER. ALIGN BOTH FRONT CHASSIS FRAMES TO SPECIFICATION OF ORIGIN. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW DAMAGED PANELS. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	10,000.00	5,600.00
8	TO DISMANTLE BOTH FRONT DOOR PANEL TRIMS, REMOVE AND REINSTALL BOTH MIRROR ASSY	New	800.00	800.00
9	TO RESPRAY FRONT BUMPER, LOWER SPOILER, BOTH FENDERS, BONNET HINGES, ENGINE COMPARTMENT, BOTH A-PILLARS, BOTH FRONT WHEEL ARCH TRIMS AND BOTH FRONT DOORS	New	9,500.00	4,600.00
10	TO CARRY OUT WHEEL ALIGNMENT	New	240.00	0.00
11	TO CARRY OUT DIAGNOSTIC CHECK	New	384.00	384.00
12	TO RENEW DAMAGED CONNECTOR HOUSINGS	New	600.00	600.00
13	TO RENEW REAR SEAT BELTS AND DAMAGED PILLAR TRIMS	New	800.00	800.00
		Gross Labour Cost (S$)	**36,304.00**	**18,364.00**

Report was unsubmitted during this print-out.

< END OF ESTIMATES >