LIM TAN MOTOR

ESTIMATE TO REPAIR

SURVEYOR NAME	:
DATE OF SURVEY	: 17 OCT 2018
TIME OF SURVEY	:

VEHICLE NO. : SKW 3272 K
MAKE : MAZDA
MODEL : 2 5-DOOR HATCHBACK 1.5L SP.6EAT
YEAR : 2015
CHASSIS NO : JM6DJ2HAA01100508

DATE : 10-Oct-18
DATE OF ACCIDENT : 8-Oct-18
THIRD PARTY REF : SLJ 905 U / AIG

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper				$ 850.80
2 pcs	Rear Bumper Side Retainer		$ 25.90		$ 51.80
1 pc	Rear End Panel				$ 380.20
1 pc	Rear End Panel Garnish				$ 73.30
1 pc	Tailgate				$ 911.10
1 pc	Tailgate Lock				$ 202.10
1 pc	Tailgate Rubber				$ 160.50
1 pc	Tailagte Centre Emblem				$ 58.20
1 pc	Tailgate MAZDA 2 Emblem				$ 55.50
1 pc	Tailagte SKYACTV Emblem				$ 64.70
					$ 2,808.20
	Less 20%				$ 561.64
					$ 2,246.56
1 tube	Rear Windscreen Sealant	S.Nett			$ 40.00
1 pc	Rear Number Plate	S.Nett			$ 40.00
1 set	Rear Bumber Sensor	S.Nett			$ 200.00
	To putty and spray painting.				$ 800.00
	To transfer tailgate fittings.				$ 80.00
	To remove and refix rear windscreen glass.				$ 120.00
	To anti-rust.				$ 60.00
	Labour Charges.				$ 700.00
TG-RA/-	**TOTAL**				**$ 4,286.56**

Not Authorised
I.B.I
Resurvey B4 paint
5 days

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Lim Tan Motor Pte Ltd
Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
Tel:65-64520893 Fax:65-64589127 Website : www.LTM.sg
Co.Reg No.199307277D GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd