CHUNNI MOTOR WORK PTE LTD

I ee Koll

REPAIR ESTIMATE*

1/1

VEHICLE NO : SHD 7110D **DATE : 25.10.2018**

MAKE : **TEL : 6542 5119**

MODEL : HYUNDAI i40 **FAX : 6542 6039**

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Aircon Pulley broken			$ 120.00
	Fan Idler Pulley broken			$ 179.70
	Oil Sump broken			$ 435.60
	Actuator - Swirl Control crack			$ 814.60
	5 Litre Engine Oil new			$ 180.00
	SUB TOTAL			**$ 1,729.90**
	LESS 20%			**$ ~~345.98~~**
	DISCOUNTED TOTAL			**$ 1,383.92**

25/10/2018

LKK Auto

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.