PANG SCOOTER SERVICE

Blk 1006 Bukit Merah Lane 2 #01-06 Singapore 159762
Tel : 6271 4618 Fax : 6273 2632

ESTIMATE REPAIR

BIKE NO.: **JNW 3705**

DATE ACCIDENT : **15.08.2018**

MAKE / MODEL : **YAMAHA/LC 135**

S/No	DESCRIPTION	AMOUNT	
1	FORK ASSY	$ bt	385.00
2	HANDLER BAR	$ bt	85.00
3	HANDLER BRACKET	$?	65.00
4	UNDLER BRACKET	$?	185.00
5	F PANEL BRACKET	$?	65.00
6	STEERING CON	$?	110.00
7	F WHEEL RIM	$?	395.00
8	F BAKE DISC	$?	185.00
9	F WHEEL SHAFT	$?	35.00
10	HEADLIGHT	$ cra	110.00
11	METER ASSY	$?	380.00
12	SIGNAL LIGHT	$ cut	90.00
13	MIRROR	$ bro	65.00
14	BRAKE LEVER	$ cut	25.00
15	RADIATOR COMP	$?	285.00
16	RADIATOR FAN	$?	110.00
17	EXP ASSY	$?	395.00
18	R/H REAR FOOTREST BRACKET	$ bro	85.00
19	SWIM ARM ASSY	$?	295.00
20	SWIM BUSH SET	$?	65.00
21	F FENDER	$ cra	85.00
22	HEADLIGHT COVER	$ cra	65.00
23	HANDLER COVER	$ cut	65.00
24	FRONT CENTRE PANEL	$ cut	110.00
25	FRONT PANEL	$ de	90.00
26	L/H SIDE PANEL	$ cra	95.00
27	R/H PANEL	$ cra	95.00
28	R/H SIDE COVER	$ cra	150.00
29	PRESS BODY	$ 200.	350.00
30	COOLANT	$?	35.00
31	F FOOTREST BAR	$ bt	95.00
32	BRAKE PEDAL	$ dd	65.00
	TRANSPORT	$ 60.	80.00
	LABOUR	$ 250	500.00
	Total	$	5,295.00

Tanjilin 97495749
"WP"
2/11/18 @
sur@lkkauto.com.
Repairing new parts.
06 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party surveyor on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: