Accident Photo

Accident Photo

Accident Photo



CERTIFICATE OF INSURANCE

AIG

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder	: LIM OI LENG	Vehicle No.	: SGX9476S
Period of Insurance	: 22 Dec 2017 To 21 Dec 2018	Policy No.	: 2100494647-01
Engine No.	: CHZ146455	Endorsement No.	: 000000000172488
Chassis No.	: WAUZZZ8V0H1019099	Issued Date	: 10 Jan 2018

ABOUT THE COVER

Make/Model	: AUDI A3 Sedan 1.0 TFSI S tronic	Sum Insured	: Market Value	First Year of Registration	: 2016
Engine Capacity/Tonnage	: 999.00 CC	Off Peak Car	: No	Insuring with COE/PARF	: Yes
Driver Restriction	: NA				

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of $3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings

EXCESS

Section 1
Fire - $0 Own Damage - $600 Theft - $0 Flood Cover - $0

Section 2
Property Damage - $0

Windscreen : $100

Named Driver and Excess (where applicable)

LIM OI LENG - $600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125216

PREMIUM LEASING - CW
281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938
Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

Co. Reg. No. 201008048 | Copyright © 2016 AIG Asia Pacific Insurance Pte. Ltd.

IOUR AIG AUTO HOTLINE: +65 6338 6200

ORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

at can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Writ/Summons/Correspondences from third party(ies) to AIG immediately.

no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

f the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number **(65) 6419-3000** for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within **5** working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the **original** insurance policy and schedule issued by AIG, a copy of the Accident Report from **Audi Customer Service Centre** must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.
Activation Hotline: 67428888
501 Guillemard Road Singapore 399840
Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc).

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is IMPORTANT and MUST be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1286/2018/GW
Date	:	13-Nov-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms. Lim Oi Leng
Address	:	36 Chuan Close Singapore 554909
Telephone	:	HP +65 85118798
Type of Claim	:	Own Damage Claim
Policy No.	:	2100494647-01
Vehicle No	:	**SGX 9476 S**
Model Code	:	A3 Sedan 1.0 TFSI
Model / Year	:	Dec-16
Engine No	:	CHZ 146455
Chassis No	:	WAUZZZ8V0H1019099
Mileage	:	35197 KM
Date In	:	12-Nov-18
Liability	:	
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	10-Nov-18
Place of Accident	:	Junct of Mountbatten Rd &Tanjong Katong Rd South

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGX 9476 S

S/N	Nature of Jobs		Estimated Charges	
1	To remove and transfer front wire hartness for headlights, horns outside temperature sensor and headlight washer assy.	S/N	$ 360.00	
2	To remove and renew aircon condenser, additional radiator, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N	$ 1,000.00	?
3	To dismantle and renew front bumper, rhs front fender, rhs headlight and bonnet. Renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.		$ ~~4,500.00~~ 3750	1750.
4	To respray front bumper, rhs front fender, bonnet and hinges.		$ ~~2,500.00~~	1650
5	To renew rhs front rim and carry out wheel alignment.	S/N	$ 280.00	
6	To carry out diagnostic check.	S/N	$ 192.00	
	TOTAL LABOUR CHARGES	:	**$ 8,832.00**	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGX 9476 S

S/N	Parts Description			Damage Parts & Prices S/NETT	REMARKS
1	FRONT BUMPER Distorted		$	1,739.00	1391.20
2	FRONT BUMPER FIXING PARTS Not new		$	161.00	
3	FRONT BUMPER GUIDE SECTION-LH/RH Rst Dmgd.	2	$	66.00	25.84
4	FRONT BUMPER GRILLE-CENTER Cracked		$	140.00	112
5	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE Cracked		$	160.00	368
6	FRONT BUMPER CLOSING ELEMENT-RH Bnd		$	254.00	203.20
7	FRONT BUMPER COVER TRIM-RH Dehond		$	140.00	111.60
8	FRONT WHEEL HOUSING LINER-RH Not new		$	32.00	
9	RADIATOR GRILLE cracked		$	1,239.00	991.20
10	RADIATOR GRILLE CLOSING ELEMENT Bnd		$	167.00	133.20
11	FRONT AIR GUIDE GRILLE-RH cut		$	164.00	131.20
12	FOAM FILLER PIECE Dehond		$	162.00	129.60
13	FRONT BUMPER SIDE REINFORCEMENT Bent.		$	633.00	506
14	FRONT BUMOPER COVER Dehond.	2	$	210.00	83.60
16	AIR CONDITIONER STICKER ?		$	7.00	4.88
17	SIGN"CAUTION"		$	12.00	9.28
18	FRONT FENDER-RH Buckled		$	746.00	596.80
19	FRONT FENDER ATTACHMENT PARTS-RH Not New.		$	62.00	
20	FRONT FENDER BRACKET-RH Bent		$	34.00	26.64
	SUB- SPARE PARTS CHARGES	:	**$**	**6,128.00**	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGX 9476 S

S/N	Parts Description			Damage Parts & Prices S/NETT	REMARKS
21	FRONT FENDER BRACE-RH Bent.		$	84.00	? 87.04 ✓
22	FRONT WHEEL HOUSING LINER-RH NP new		$	151.00	✗
23	WHEEL HOUSING LINER ATTACHMENT PARTS NP new		$	77.00	✗
24	BONNET Dented		$	2,755.00	✓ 2304
25	BONNET ATTACHMENT PARTS NP new		$	141.00	? ✗
26	BONNET LID HINGE-LH/RH NP new	2	$	106.00	✗
27	BONNET STOP BUFFER	2	$	9.00	✗
28	BONNET CATCH LATCH LOCK NP new		$	78.00	✗
29	BONNET STRIKER-LH/RH	2	$	192.00	✗.
30	BONNET EDGE PROTECTION New		$	24.00	✓ 18.88
31	BONNET CATCH HOOK		$	55.00	✗
32	BONNET LID LOCK WITH MIRCRO NP New	2	$	353.00	✗
33	BONNET BOWDEN CABLE-CENTER		$	50.00	✗
34	BONNET BOWDEN CABLE COVER		$	9.00	✗.
35	SIGNAL HORN-LOW TONE Damaged.		$	177.00	? 141.60 ✓
36	LED HEADLIGHT-RH Cracked		$	4,888.00	✓ 3910.40
37	LED HEADLIGHT POWER MODULE-RH		$	665.00	✗
38	LED HEADLIGHT CONTROL UNIT NP New		$	486.00	✗
39	LED WITH HEAT SINK		$	625.00	✗.
40	LED HEADLIGHT LIFT CYLINDER-RH ~~Broken~~		$	123.00	? ✗
	SUB- SPARE PARTS CHARGES	:		**$ 11,048.00**	

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGX 9476 S

S/N	Parts Description			Damage Pa S/NETT
41	HOSE Not Nec		$	57.00 ✗
42	LOCK CARRIER MOUNTING Bruised		$	638.00 ? 510 ✓
43	AIR GUIDE-LH/RH Not Deformed	2	$	40.00 ? 15.92 ✓
44	COOLANT CONCENTRATE Not Nec	4	$	133.00 ? ✗
45	A/C CONDENSOR WITH FLUID RESERVOIR New		$	468.00 ✗
46	COOLER FOR COOLANT New		$	828.00 ✗
47	ADDIONAL COOLER AND COOLANT New		$	797.00 ✗
48	RADIATOR FAN WITH FAN RING New		$	1,425.00 ✗
49	FRONT ALUMINIUM RIM-RH New		$	659.00 ✗
50	RUBBER VALVE New	4	$	12.00 ✗
51	FRONT NO. PLATE Bent	S/N	$	25.00 ✓
52	SUNDRIES Nec.		$	800.00 ? 38.40 ✓
	TOTAL SPARE PARTS	:	**$**	**23,058.00**
	TOTAL LABOUR CHARGES	:	**$**	**8,832.00**
	GRAND TOTAL	:	**$**	**31,890.00**

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

32098.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Telefax

Name : Adrian Ling
Surveyed Date : 13/11/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, OG Pays.

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGX 9476 S

S/N	Parts Description		Damage Parts & Prices S/NETT	REMARKS
1	FRONT BUMPER Distorted		$ 1,739.00	
2	FRONT BUMPER FIXING PARTS not in		$ 161.00	
3	FRONT BUMPER GUIDE SECTION-LH/RH	2	$ 66.00	
4	FRONT BUMPER GRILLE-CENTER cracked		$ 140.00	
5	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE cracked		$ 160.00	
6	FRONT BUMPER CLOSING ELEMENT-RH		$ 254.00	
7	FRONT BUMPER COVER TRIM-RH Detached		$ 140.00	
8	FRONT WHEEL HOUSING LINER-RH		$ 32.00	
9	RADIATOR GRILLE cracked		$ 1,239.00	
10	RADIATOR GRILLE CLOSING ELEMENT		$ 167.00	
11	FRONT AIR GUIDE GRILLE-RH		$ 164.00	
12	FOAM FILLER PIECE Detached		$ 162.00	
13	FRONT BUMPER SIDE REINFORCEMENT		$ 633.00	
14	FRONT BUMOPER COVER	2	$ 210.00	
16	AIR CONDITIONER STICKER		$ 7.00	
17	SIGN"CAUTION"		$ 12.00	
18	FRONT FENDER-RH Buckled		$ 746.00	
19	FRONT FENDER ATTACHMENT PARTS-RH		$ 62.00	
20	FRONT FENDER BRACKET-RH Bent		$ 34.00	
	SUB- SPARE PARTS CHARGES	:	$ 6,128.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

horn bracket

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGX 9476 S

S/N	Parts Description		Damage Parts & Prices S/NETT	REMARKS
21	FRONT FENDER BRACE-RH		$ 84.00	
22	FRONT WHEEL HOUSING LINER-RH		$ 151.00	
23	WHEEL HOUSING LINER ATTACHMENT PARTS		$ 77.00	
24	BONNET		$ 2,755.00	
25	BONNET ATTACHMENT PARTS		$ 141.00	
26	BONNET LID HINGE-LH/RH	2	$ 106.00	
27	BONNET STOP BUFFER	2	$ 9.00	
28	BONNET CATCH LATCH LOCK		$ 78.00	
29	BONNET STRIKER-LH/RH	2	$ 192.00	
30	BONNET EDGE PROTECTION		$ 24.00	
31	BONNET CATCH HOOK		$ 55.00	
32	BONNET LID LOCK WITH MIRCRO	2	$ 353.00	
33	BONNET BOWDEN CABLE-CENTER		$ 50.00	
34	BONNET BOWDEN CABLE COVER		$ 9.00	
35	SIGNAL HORN-LOW TONE		$ 177.00	
36	LED HEADLIGHT-RH		$ 4,888.00	
37	LED HEADLIGHT POWER MODULE-RH		$ 665.00	
38	LED HEADLIGHT CONTROL UNIT		$ 486.00	
39	LED WITH HEAT SINK		$ 625.00	
40	LED HEADLIGHT LIFT CYLINDER-RH		$ 123.00	
	SUB- SPARE PARTS CHARGES	:	**$ 11,048.00**	

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, S ngapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGX 9476 S

S/N	Parts Description			Damage Pa S/NETT
41	HOSE		$	57.00
42	LOCK CARRIER MOUNTING		$	638.00
43	AIR GUIDE-LH/RH	2	$	40.00
44	COOLANT CONCENTRATE	4	$	133.00
45	A/C CONDENSOR WITH FLUID RESERVOIR		$	468.00
46	COOLER FOR COOLANT		$	828.00
47	ADDIONAL COOLER AND COOLANT		$	797.00
48	RADIATOR FAN WITH FAN RING		$	1,425.00
49	FRONT ALUMINIUM RIM-RH		$	659.00
50	RUBBER VALVE	4	$	12.00
51	FRONT NO. PLATE	S/N	$	25.00
52	SUNDRIES		$	800.00
	TOTAL SPARE PARTS	:	$	23,058.00
	TOTAL LABOUR CHARGES	:	$	8,832.00
	GRAND TOTAL	:	$	31,890.00

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

16/11/18

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1286/2018/GW
Date	:	13-Nov-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian
We took 9 days with added repairs
jb - 11 Dec 18

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms. Lim Oi Leng
Address	:	36 Chuan Close Singapore 554909
Telephone	:	HP +65 85118798
Type of Claim	:	Own Damage Claim
Policy No.	:	2100494647-01
Vehicle No	:	**SGX 9476 S**
Model Code	:	A3 Sedan 1.0 TFSI
Model / Year	:	Dec-16
Engine No	:	CHZ 146455
Chassis No	:	WAUZZZ8V0H1019099
Mileage	:	35197 KM
Date In	:	12-Nov-18
Liability	:	
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	10-Nov-18
Place of Accident	:	Junct of Mountbatten Rd &Tanjong Katong Rd South

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGX 9476 S

S/N	Nature of Jobs		Estimated Charges		
1	To remove and transfer front wire hartness for headlights, horns outside temperature sensor and headlight washer assy.	S/N	$ 360.00	$	360.00
2	To remove and renew aircon condenser, additional radiator, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N	$ 1,000.00	$	1,000.00
3	To dismantle and renew front bumper, rhs front fender, rhs headlight and bonnet. Renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed. *(Lock carrier replaced)*		$ 4,500.00	$	3,250.00
4	To respray front bumper, rhs front fender, bonnet and hinges.		$ 2,500.00	$	1,650.00
5	To renew rhs front rim and carry out wheel alignment.	S/N	$ 280.00	$	280.00
6	To carry out diagnostic check.	S/N	$ 192.00	$	192.00
	TOTAL LABOUR CHARGES	:	**$ 8,832.00**	$	6,732.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGX 9476 S

S/N	Parts Description			Damage Parts & Prices S/NETT		REMARKS
1	FRONT BUMPER		$	1,739.00	$	*1,391.20*
2	FRONT BUMPER FIXING PARTS		$	161.00		
3	FRONT BUMPER GUIDE SECTION-LH/RH	2	$	66.00	$	*25.84*
4	FRONT BUMPER GRILLE-CENTER		$	140.00	$	*112.00*
5	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE		$	160.00	$	*368.00*
6	FRONT BUMPER CLOSING ELEMENT-RH		$	254.00	$	*203.20*
7	FRONT BUMPER COVER TRIM-RH		$	140.00	$	*111.60*
8	FRONT WHEEL HOUSING LINER-RH		$	32.00		
9	RADIATOR GRILLE		$	1,239.00	$	*991.20*
10	RADIATOR GRILLE CLOSING ELEMENT		$	167.00	$	*133.20*
11	FRONT AIR GUIDE GRILLE-RH		$	164.00	$	*131.20*
12	FOAM FILLER PIECE		$	162.00	$	*129.60*
13	FRONT BUMPER SIDE REINFORCEMENT		$	633.00	$	*506.00*
14	FRONT BUMOPER COVER	2	$	210.00	$	*83.60*
16	AIR CONDITIONER STICKER		$	7.00	$	*4.88*
17	SIGN"CAUTION"		$	12.00	$	*9.28*
18	FRONT FENDER-RH		$	746.00	$	*596.80*
19	FRONT FENDER ATTACHMENT PARTS-RH		$	62.00		
20	FRONT FENDER BRACKET-RH		$	34.00	$	*26.64*
	SUB- SPARE PARTS CHARGES	:	**$**	**6,128.00**	$	*4,824.24*

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGX 9476 S

S/N	Parts Description		Damage Parts & Prices S/NETT		REMARKS
				$	*4,824.24*
21	FRONT FENDER BRACE-RH	$	84.00	$	*67.04*
22	FRONT WHEEL HOUSING LINER-RH	$	151.00		
23	WHEEL HOUSING LINER ATTACHMENT PARTS	$	77.00		
24	BONNET	$	2,755.00	$	*2,204.00*
25	BONNET ATTACHMENT PARTS	$	141.00		
26	BONNET LID HINGE-LH/RH	2 $	106.00		
27	BONNET STOP BUFFER	2 $	9.00		
28	BONNET CATCH LATCH LOCK	$	78.00		
29	BONNET STRIKER-LH/RH	2 $	192.00		
30	BONNET EDGE PROTECTION	$	24.00	$	*18.88*
31	BONNET CATCH HOOK	$	55.00		
32	BONNET LID LOCK WITH MIRCRO	2 $	353.00		
33	BONNET BOWDEN CABLE-CENTER	$	50.00		
34	BONNET BOWDEN CABLE COVER	$	9.00		
35	SIGNAL HORN-LOW TONE	$	177.00	$	*141.60*
36	LED HEADLIGHT-RH	$	4,888.00	$	*3,910.40*
37	LED HEADLIGHT POWER MODULE-RH	$	665.00		
38	LED HEADLIGHT CONTROL UNIT	$	486.00		
39	LED WITH HEAT SINK	$	625.00		
40	LED HEADLIGHT LIFT CYLINDER-RH	$	123.00		
	SUB- SPARE PARTS CHARGES :	**$**	**11,048.00**	**$**	***11,166.16***

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGX 9476 S

S/N	Parts Description			Damage Parts & Prices S/NETT		REMARKS
					$	11,166.16
41	HOSE		$	57.00		
42	LOCK CARRIER MOUNTING		$	638.00	$	510.00
43	AIR GUIDE-LH/RH	2	$	40.00	$	15.92
44	COOLANT CONCENTRATE	4	$	133.00		
45	A/C CONDENSOR WITH FLUID RESERVOIR		$	468.00		
46	COOLER FOR COOLANT		$	828.00		
47	ADDIONAL COOLER AND COOLANT		$	797.00		
48	RADIATOR FAN WITH FAN RING		$	1,425.00		
49	FRONT ALUMINIUM RIM-RH		$	659.00		
50	RUBBER VALVE	4	$	12.00		
51	FRONT NO. PLATE	S/N	$	25.00	$	25.00
52	SUNDRIES		$	800.00	$	38.40
	TOTAL SPARE PARTS	:	**$**	**23,058.00**	$	11,755.48
	TOTAL LABOUR CHARGES	:	**$**	**8,832.00**	$	6,732.00
	GRAND TOTAL	:	**$**	**31,890.00**	$	18,487.48

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SGX 9476 S

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1286/2019/NH

9 October 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Dear Sir,

RE: INSURANCE CLAIM FOR SGX 9476 S, Audi A3 SEDAN 1.0 TFSI.

With reference to the above-mentioned vehicle, no. **SGX 9476 S,** claimant, **Ms. Lim Oi Leng,** please find the related document per attached.

1. A copy of the Original invoice no. 85014325 – S$19,139.60.
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SGX 9476 S

Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 11:52

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice No: 85014325
Date : 07/10/2019
Order : SGX9476S
Term : 30

Account: A0006 (T 0)

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No: SGX9476S (V 31720) Regn Date: 22/12/2016 Mileage: 47154 WIP No.: 31655

Model: A3 SEDAN 1.0 TFSI 8VMANG Chassis: WAUZZZ8V0H1019099 Engine: CHZ 146455 Dept: U

You have been assisted by :- UB-Jeffery Tan (R) (87)

		Details		Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE		25.00	1.00	25.00
Q	EXC	M: 8888 Insurance Excess/Liability		-600.00	1.00	-600.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY		360.00	1.00	360.00
S	BODYWORK	M: TO REMOVE AND REINSTALL AIRCON CONDENSER, RADIATOR,ADDITIONAL RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT.PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS		1000.00	1.00	1,000.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER,RHS FRONT FENDER,RHS HEADLIGHT AND BONNET.RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED		3250.00	1.00	3,250.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER,RHS FRONT FENDER AND BONNET		1650.00	1.00	1,650.00
S	BODYWORK	M: TO CARRY OUT WHEEL ALIGNMENT		280.00	1.00	280.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK		192.00	1.00	192.00
X	A8V3853651AA3FZ	GRILLE	Less 020%	1.00	1239.00	991.20
X	A8V0941774D	HEADLIGHT	Less 020%	1.00	4888.00	3,910.40
X	A8V5821106A	FENDER	Less 020%	1.00	746.00	596.80
X	A8V5807233B	PLATE	Less 020%	1.00	460.00	368.00
X	A8V0805588A	(SK)CARRIER	Less 020%	1.00	637.50	510.00
X	A8V0807550A	FOAM INSER	Less 020%	1.00	162.00	129.60
X	A8V4807109C	BEAM	Less 020%	1.00	632.50	506.00
X	A8V5823029A	HOOD	Less 020%	1.00	2755.00	2,204.00

Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 2 11:52

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice No: 85014325
Date : 07/10/2019
Order : SGX9476S
Term : 30

Account: A0006 (T 0)

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No: SGX9476S (V 31720) Regn Date: 22/12/2016 Mileage: 47154 WIP No.: 31655

Model: A3 SEDAN 1.0 TFSI 8VMANG Chassis: WAUZZZ8V0H1019099 Engine: CHZ 146455 Dept: U

You have been assisted by :- UB-Jeffery Tan (R) (87)

		Details		Qty	Unit Price	Amount
X	A8V5807065R GRU	COVER	Less 020%	1.00	1739.00	1,391.20
X	A8V0823126B	EDGING	Less 020%	1.00	23.60	18.88
X	A8V5807184	GUIDE	Less 020%	1.00	32.30	25.84
X	A8V5821468B	BRACKET	Less 020%	1.00	33.30	26.64
X	A8V5807320	(SK)PLATE	Less 020%	1.00	254.00	203.20
X	A8V0821136C	SUPPORT	Less 020%	1.00	83.80	67.04
X	A8V5807534A	COVERSTRIP	Less 020%	1.00	139.50	111.60
X	A8V5807647B 9B9	GRILLE	Less 020%	1.00	140.00	112.00
X	A8V5807682M 9B9	GRILL	Less 020%	1.00	164.00	131.20
X	A8K0010520A	PLATE	Less 020%	1.00	11.60	9.28
X	A8V0010515A	STICKER	Less 020%	1.00	6.10	4.88
X	A8V0951210D	(SK)HORN	Less 020%	1.00	177.00	141.60
X	A8V0121284K	AIR DUCT	Less 020%	1.00	19.90	15.92
X	A8V3853949	(SK)PLATE	Less 020%	1.00	166.50	133.20
X	A8V4807217F	(SK)COVER	Less 020%	1.00	104.50	83.60
X	AN 0161857	POP-RIVET	Less 020%	5.00	2.90	11.60
X	AN 0161857	POP-RIVET	Less 020%	5.00	2.90	11.60
X	AN 91022001	NUT	Less 020%	2.00	1.40	2.24
X	AN 91166901	BOLT	Less 020%	10.00	1.30	10.40
X	AWHT005609	BOLT	Less 020%	2.00	1.60	2.56

Parts	11,730.48
Labour	0.00
Sublet	6,757.00
Menus	0.00
Lubricant	0.00

Sub-Total	17,887.48
7% GST	1,252.12
Grand Total	19,139.60

PREMIUM AUTOMOBILES PTE LTD

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Your Ref: SGX 9476 S

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1286/2018/JT
Nov 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model	:	Audi A3 Sedan 1.0 TFSI 8V
Vehicle Chassis No.	:	WAUZZZ8V0H1019099
Vehicle Regn No.	:	**SGX 9476 S**
Vehicle Mileage	:	47154 KM
Vehicle Owner	:	Ms. Lim Oi Leng
Certificate No	:	2100494647-01
Policy Excess	:	$642.00 (Inclusive GST)
Accident Date	:	10th November 2018
Place	:	Junc. of Mountbatten Rd & Tanjong Katong Rd South
Repair Cost	:	$ 19,139.60
WIP No.	:	31655
Repairer's Name	:	Premium Automobiles Pte Ltd

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : _____

Time : _____

Date : _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Nov 2018		13 Nov 2018 09:39 Edit Adj Rpt	**S$18,487.48** Edit Estimates	**S$18,487.48** View Rpt		**Pending for Survey Report** Cancel Case

Main | Reference | Claim Details | Documents | Show All

CLAIM SUBFOLDER DETAILS **[Created by insurer]**

Insured:	**LIM OI LENG**, ID: S1585865F, Tel: +6585118798, Email: CELINE3Q@YAHOO.COM		
Vehicle Reg. No.:	**SGX9476S**	Date of Loss:	10/11/2018 00:00 - :59 [**22** Months and **19** Days From LTA Reg Date (Man Yr)]
Claim Type:	**OD** / 2313987226SG	Policy/Cover Note No.:	2100494647 (Comprehensive)
		Excess:	S$600.00
Repairer:	**Premium Automobiles Pte Ltd (UBI)** 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	**AIG Asia Pacific Insurance Pte. Ltd. (SG)** - Tel: 65-6419-3000 ... [Handled by **Mohd Zawaye, Norsazani**] Norsazani.Zawaye@aig.com		
Adjuster:	**LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **ADRIAN LING**] ... [**Final Rpt** due 22/11/2018]		
Driver/Custodian:	LIM OI LENG (55 / Female) , NRIC: S1585865F, Tel: +6585118798 Email: CELINE3Q@YAHOO.COM		

ASSOCIATED MAIL RECEIVED View All | Compose Case Mail

- AIG_SG (30/09/2019): **Alert - Adj Mandate Approved (S$18487.48) - SGX9476S - Claim Handler: Mohd Zaway...**
- AIG_SG (27/05/2019): **Alert - Adj Mandate Maintained - SGX9476S - Claim Handler: Mohd Zawaye, Norsazan...**
- AIG_SG (07/02/2019): **Alert - Adj Mandate Maintained - SGX9476S - Claim Handler: Mohd Zawaye, Norsazan...**
- AIG_SG (31/01/2019): **Alert - Adj Mandate Maintained - SGX9476S - Claim Handler: Mohd Zawaye, Norsazan...**
- AIG_SG (14/11/2018): **Alert - Adj Mandate Approved (S$16448.00) - SGX9476S - Claim Handler: Mohd Zaway...**
- AIG_SG (14/11/2018): **SGX9476S / OD / 10/11/2018 / Coverage & Excess update**

ALL ASSOCIATED TASKS View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?

No results.

Claim Documents

***SGX9476S (2313987226SG)**
OD
Nov 10 2018 12:00AM
[LIM OI LENG]
Premium Automobiles Pte Ltd

Upload Documents | Upload Photos | Compose New Letter | Upload Video | Upload Audio

View: View in Browser

Assessment Reports

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/11/18 16:49	**Adjuster Immediate Advice**		Load HTM	
2	24/12/18 11:35	**Adjuster Immediate Advice**		Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/11/18 16:27	**General View**		Load JPG	
2	13/11/18 16:27	**Chassis Number**		Load JPG	
3	13/11/18 16:27	**General View**		Load JPG	
4	13/11/18 16:27	**General View**		Load JPG	
5	13/11/18 16:27	**General View**		Load JPG	
6	13/11/18 16:27	**General View**		Load JPG	
7	13/11/18 16:27	**General View**		Load JPG	
8	13/11/18 16:27	**General View**		Load JPG	
9	13/11/18 16:27	**General View**		Load JPG	
10	13/11/18 16:27	**General View**		Load JPG	
11	13/11/18 16:27	**General View**		Load JPG	
12	13/11/18 16:27	**General View**		Load JPG	
13	13/11/18 16:27	**General View**		Load JPG	
14	13/11/18 16:27	**General View**		Load JPG	
15	13/11/18 16:27	**General View**		Load JPG	
16	13/11/18 16:27	**General View**		Load JPG	
17	13/11/18 16:27	**General View**		Load JPG	
18	13/11/18 16:27	**General View**		Load JPG	
19	13/11/18 16:27	**General View**		Load JPG	
20	13/11/18 16:27	**General View**		Load JPG	
21	13/11/18 16:27	**General View**		Load JPG	
22	13/11/18 16:27	**General View**		Load JPG	
23	13/11/18 16:27	**General View**		Load JPG	
24	13/11/18 16:27	**General View**		Load JPG	
25	13/11/18 16:27	**General View**		Load JPG	
26	13/11/18 16:27	**General View**		Load JPG	
27	13/11/18 16:27	**General View**		Load JPG	
28	13/11/18 16:27	**General View**		Load JPG	
29	13/11/18 16:27	**General View**		Load JPG	
30	13/11/18 16:27	**General View**		Load JPG	
31	13/11/18 16:27	**General View**		Load JPG	
32	13/11/18 16:27	**General View**		Load JPG	
33	13/11/18 16:27	**General View**		Load JPG	
34	13/11/18 16:27	**General View**		Load JPG	
35	13/11/18 16:27	**General View**		Load JPG	
36	13/11/18 16:27	**General View**		Load JPG	
37	13/11/18 16:27	**General View**		Load JPG	

Assessment Reports 1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
38	13/11/18 16:27	**General View**		Load JPG	
39	13/11/18 16:27	**General View**		Load JPG	
40	13/11/18 16:27	**General View**		Load JPG	
41	13/11/18 16:27	**General View**		Load JPG	
42	18/12/18 19:21	**Reinspection Photo**		Load JPG	
43	18/12/18 19:21	**Reinspection Photo**		Load JPG	
44	18/12/18 19:21	**Reinspection Photo**		Load JPG	
45	18/12/18 19:21	**Reinspection Photo**		Load JPG	
46	18/12/18 19:21	**Reinspection Photo**		Load JPG	
47	18/12/18 19:21	**Reinspection Photo**		Load JPG	
48	18/12/18 19:21	**Reinspection Photo**		Load JPG	
49	18/12/18 19:21	**Reinspection Photo**		Load JPG	
50	18/12/18 19:21	**Reinspection Photo**		Load JPG	
51	18/12/18 19:21	**Reinspection Photo**		Load JPG	
52	18/12/18 19:21	**Reinspection Photo**		Load JPG	
53	18/12/18 19:21	**Reinspection Photo**		Load JPG	
54	18/12/18 19:21	**Reinspection Photo**		Load JPG	
55	18/12/18 19:21	**Reinspection Photo**		Load JPG	
56	18/12/18 19:21	**Reinspection Photo**		Load JPG	
57	18/12/18 19:21	**Reinspection Photo**		Load JPG	
58	18/12/18 19:21	**Reinspection Photo**		Load JPG	
59	18/12/18 19:21	**Reinspection Photo**		Load JPG	
60	18/12/18 19:21	**Reinspection Photo**		Load JPG	
61	18/12/18 19:21	**Reinspection Photo**		Load JPG	
62	18/12/18 19:21	**Reinspection Photo**		Load JPG	
63	18/12/18 19:21	**Reinspection Photo**		Load JPG	
64	18/12/18 19:21	**Reinspection Photo**		Load JPG	
65	18/12/18 19:21	**Reinspection Photo**		Load JPG	
66	18/12/18 19:21	**Reinspection Photo**		Load JPG	
67	18/12/18 19:21	**Reinspection Photo**		Load JPG	
68	18/12/18 19:21	**Reinspection Photo**		Load JPG	
69	18/12/18 19:21	**Reinspection Photo**		Load JPG	
70	18/12/18 19:21	**Reinspection Photo**		Load JPG	
71	18/12/18 19:21	**Reinspection Photo**		Load JPG	
72	18/12/18 19:21	**Reinspection Photo**		Load JPG	
73	18/12/18 19:21	**Reinspection Photo**		Load JPG	
74	18/12/18 19:21	**Reinspection Photo**		Load JPG	
75	18/12/18 19:21	**Reinspection Photo**		Load JPG	

Documentation 1 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/11/18 14:35	**Singapore Accident Statement**		Load PDF	
2	13/11/18 14:35	**Police Report**		Load PDF	
3	13/11/18 14:35	**Certificate of Insurance**		Load PDF	
4	13/11/18 14:35	**Driver's Driving License**		Load PDF	
5	13/11/18 16:25	**ESTIMATE**		Load PDF	
6	24/12/18 11:28	**REVISED ESTIMATE**		Load PDF	
7	18/10/19 11:15	**DISCHARGE VOUCHER**		Load PDF	
8	18/10/19 11:15	**WORKSHOP INVOICE**		Load PDF	

Linked Accident Report Documents

View View in Browser

Assessment Reports 1 per page

No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print

Assessment Reports 1 per page

No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	12/11/18 17:26	**Accident Statement**		Load HTM	

Photos/Images 3 per page

No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	12/11/18 14:00	**Police Report**		Load JPG	
2	12/11/18 14:00	**Police Report**		Load JPG	
3	12/11/18 14:00	**Police Report**		Load JPG	
4	12/11/18 14:00	**Police Report**		Load JPG	
5	12/11/18 17:18	**SKETCH ATTACHMENT**		Load JPG	
6	12/11/18 17:18	**SKETCH ATTACHMENT**		Load JPG	
7	12/11/18 17:25	**Accident Photo**		Load JPG	
8	12/11/18 17:25	**Accident Photo**		Load JPG	
9	12/11/18 17:25	**Accident Photo**		Load JPG	
10	12/11/18 17:25	**Accident Photo**		Load JPG	
11	12/11/18 17:25	**Accident Photo**		Load JPG	
12	12/11/18 17:25	**Accident Photo**		Load JPG	
13	12/11/18 17:25	**Accident Photo**		Load JPG	
14	12/11/18 17:25	**Accident Photo**		Load JPG	
15	12/11/18 17:25	**Accident Photo**		Load JPG	
16	12/11/18 17:25	**Accident Photo**		Load JPG	
17	12/11/18 17:25	**Accident Photo**		Load JPG	
18	12/11/18 17:25	**Accident Photo**		Load JPG	

Documentation 1 per page

No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	12/11/18 14:15	**Sketch Plan**		Load JPG	
2	12/11/18 14:15	**Sketch Plan #2**		Load JPG	

Documents Checklist

DOCUMENTS CHECKLIST Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18020447/AQBS2
Date: 18/10/2019

REFERENCE

Insured/Claimant:	LIM OI LENG	Policy No:	2100494647		
Date of Loss:	10/11/2018	Nature of Claim:	OD	Claim No:	2313987226SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	**SGX9476S**		
Make & Model:	AUDI A3, 999cc TFSI S-TRONIC (A)	Engine No:	CHZ146455
Reg. Date:	22/12/2016 (Man. Year: 2016)	Chassis No:	WAUZZZ8V0H1019099
Colour:	White	Odometer:	35197 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S$90,000.00		
Sum Insured (S$):	**Market Value/New Car Price**		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,266.00	11,755.48	11,510.52	49.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,832.00	6,732.00	2,100.00	23.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S$)	**32,098.00**	**18,487.48**	**13,610.52**	**42.40**
- Excess (S$)	600.00	600.00	0.00	0.00
(S$)	31,498.00	17,887.48	13,610.52	43.21
+ GST 7.00/7.00% (S$)	2,204.86	1,252.12	952.74	43.21
Nett Amount (S$)	**33,702.86**	**19,139.60**	**14,563.26**	**43.21**

INSPECTION

Date of Assignment:	13/11/2018		
Date Inspected:	12/11/2018	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	9.0 days		

Adjuster: ADRIAN LING **Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,739.00 FS	*1,391.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	161.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION-LH/RH	O/s Damaged	66.00 FS	*25.84 FS
4	1		*FRONT BUMPER GRILLE-CENTER	Cracked	140.00 FS	*112.00 FS
5	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	Cracked	368.00 FS	*368.00 FS
6	1		*FRONT BUMPER CLOSING ELEMENT-RH	Damaged	254.00 FS	*203.20 FS
7	1		*FRONT BUMPER COVER TRIM-RH	Deformed	140.00 FS	*111.60 FS
8	1		*FRONT WHEEL HOUSING LINER-RH	Not Necessary	32.00 FS	*- FS
9	1		*RADIATOR GRILLE	Cracked	1,239.00 FS	*991.20 FS
10	1		*RADIATOR GRILLE CLOSING ELEMENT	Damaged	167.00 FS	*133.20 FS
11	1		*FRONT AIR GUIDE GRILLE-RH	Cut	164.00 FS	*131.20 FS
12	1		*FOAM FILLER PIECE	Deformed	162.00 FS	*129.60 FS
13	1		*FRONT BUMPER SIDE REINFORCEMENT	Bent	633.00 FS	*506.00 FS
14	2		*FRONT BUMPER COVER	Deformed	210.00 FS	*83.60 FS
15	1		*AIR CONDITIONER STICKER	Necessary	7.00 FS	*4.88 FS
16	1		*SIGN CAUTION	Necessary	12.00 FS	*9.28 FS
17	1		*FRONT FENDER-RH	Buckled	746.00 FS	*596.80 FS
18	1		*FRONT FENDER ATTACHMENT PARTS-RH	Not Necessary	62.00 FS	*- FS
19	1		*FRONT FENDER BRACKET-RH	Bent	34.00 FS	*26.64 FS
20	1		*FRONT FENDER BRACE-RH	Bent	84.00 FS	*67.04 FS
21	1		*FRONT WHEEL HOUSING LINER-RH	Not Necessary	151.00 FS	*- FS
22	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	77.00 FS	*- FS
23	1		*BONNET	Dented	2,755.00 FS	*2,204.00 FS
24	1		*BONNET ATTACHMENT PARTS	Not Necessary	141.00 FS	*- FS
25	2		*BONNET LID HINGE-LH/RH	Not Necessary	106.00 FS	*- FS
26	2		*BONNET STOP BUFFER	Not Necessary	9.00 FS	*- FS
27	1		*BONNET CATCH LATCH LOCK	Not Necessary	78.00 FS	*- FS
28	2		*BONNET STRIKER-LH/RH	Not Necessary	192.00 FS	*- FS
29	1		*BONNET EDGE PROTECTION	Necessary	24.00 FS	*18.88 FS
30	1		*BONNET CATCH HOOK	Not Necessary	55.00 FS	*- FS
31	2		*BONNET LID LOCK WITH MIRCRO	Not Necessary	353.00 FS	*- FS
32	1		*BONNET BOWDEN CABLE-CENTER	Not Necessary	50.00 FS	*- FS
33	1		*BONNET BOWDEN CABLE COVER	Not Necessary	9.00 FS	*- FS
34	1		*SIGNAL HORN-LOW TONE	Damaged	177.00 FS	*141.60 FS
35	1		*LED HEADLIGHT-RH	Cracked	4,888.00 FS	*3,910.40 FS
36	1		*LED HEADLIGHT POWER MODULE-RH	Not Necessary	665.00 FS	*- FS
37	1		*LED HEADLIGHT CONTROL UNIT	Not Necessary	486.00 FS	*- FS
38	1		*LED WITH HEAT SINK	Not Necessary	625.00 FS	*- FS
39	1		*LED HEADLIGHT LIFT CYLINDER-RH	Not Necessary	123.00 FS	*- FS
40	1		*HOSE	Not Necessary	57.00 FS	*- FS
41	1		*LOCK CARRIER MOUNTING	Cracked	638.00 FS	*510.00 FS
42	1		*AIR GUIDE-LH/RH	O/s Deformed	40.00 FS	*15.92 FS
43	4		*COOLANT CONCENTRATE	Not Necessary	133.00 FS	*- FS
44	1		*A/C CONDENSOR WITH FLUID RESERVOIR	Not Necessary	468.00 FS	*- FS
45	1		*COOLER FOR COOLANT	Not Necessary	828.00 FS	*- FS
46	1		*ADDIONAL COOLER AND COOLANT	Not Necessary	797.00 FS	*- FS
47	1		*RADIATOR FAN WITH FAN RING	Not Necessary	1,425.00 FS	*- FS
48	1		*FRONT ALUMINIUM RIM-RH	Not Necessary	659.00 FS	*- FS
49	4		*RUBBER VALVE	Not Necessary	12.00 FS	*- FS
50	1		*FRONT NO PLATE	Bent	25.00 FS	*25.00 FS
51	1		*SUNDRIES	Necessary	800.00 FS	*38.40 FS
				Total Parts (S$)	**23,266.00**	**11,755.48**

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,PUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND RENEW AIRCON CONDENSER,ADDITIONAL RADIATOR,RADIATOR,CHECK ELECTRICAL FANS AND CONTROL UNIT.PRESSURISE COOLING SYSTEM.TO CARRY OUT VACUUM AND REGAS	New	1,000.00	1,000.00
3	TO DISMANTLE AND RENEW FRONT BUMPER,RHS FRONT FENDER,RHS HEADLIGHT AND BONNET.RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	4,500.00	3,250.00
4	TO RESPRAY FRONT BUMPER,RHS FRONT FENDER,BONNET AND HINGES	New	2,500.00	1,650.00
5	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
		Gross Labour Cost (S$)	**8,832.00**	**6,732.00**

Report was unsubmitted during this print-out.

< END OF ESTIMATES >