Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 692B

AAD1811-103

Not Authorised
L/Susp & Bolt.

Vehicle No.:	**SHF 692B**
Chassis No.:	VF1ABL15AUC281168
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	12.11.2018
Third Party Insurer :	**QBE**

		PART	LIST	
1	1	BUMPER COVER REAR	$ Buy/Rel 1,108.46	✓
2	1	BUMPER LOWER REAR	$ Rel/Ret 768.84	✓
3	1	BUMPER BRACKET CTR REAR	$ Sch 113.47	
4	1	BUMEPR BRACKET SIDE RH REAR	$ Sch 135.97	
5	1	BUMEPR RETAINER RH REAR	$ Sch 44.99	
6	1	BUMPER REFLECTOR RH	$ Sch 43.61	
7	1	BUMEPR BRACKET SIDE LH REAR	$ Sch 135.97	
8	1	BUMPER RETAINER LH REAR	$ Sch 44.99	
9	1	BUMPER REFLECTOR LH	$ Sch 43.61	
10	1	BUMPER BEAM REAR	$ R 777.52	
11	1	BUMPER BEAM BRACKET LH REAR	$ R 225.95	
12	1	BUMPER BEAM BRACKET RH REAR	$ R 225.95	X
13	1	OUTER PANEL REAR (End Panel)	$ R 1,471.77	
14	1	OUTER PANEL REAR (End Panel)TRIM	$ Sch 404.56	
15	1	TAILLAMP RH	$ Sch 552.55	
16	1	TAILLAMP PANEL RH	$ R 986.70	
17	1	TAILLAMP LH	$ Sch 552.55	
18	1	TAILLAMP PANEL LH	$ R 986.70	
19	1	BOOT REAR	$ R 2,872.68	
20	1	BOOT FINISHER	$ Sch 470.06	
21	1	BOOT WHEATERSTRIP	$ Sch 323.05	
22	1	BOOT REFLECTOR LAMP LH	$ Sch 493.35	
23	1	BOOT REFLECTOR LAMP RH	$ Sch 493.35	
24	1	BOOT BADGE 'RENAULT'	$ NA 225.36	
25	1	BOOT BADGE	$ NA 225.36	
26	1	BOOT STRUT LH	$ Sch 276.08	
27	1	BOOT STRUT RH	$ Sch 276.08	
28	1	BOOT HINGE LH	$ R 367.84	
29	1	BOOT HINGE RH	$ R 367.84	

Trans-cab Auto Services Pte Ltd AAD1811-103

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 692B

30	1 BOOT INNER TRIM	$	Sn	586.45 X
31	1 BOOT SWITCH	$	Sn	168.13 X
32	1 BOOT LOCK	$	R	202.67 X
33	1 BOOT LOCK CATCH	$	R	74.40 X
		$		**16,046.87**
		10%	**$**	**7.44**
			$	**16,039.43**

Specical Nett

1	1SET PARKING AID	$	Sn	700.00 X
2	1SET REAR BUMPER CLIP	$	Sn	66.00 —
3	1SET BUMPER BRACKET CTR CLIP	$	Sn	33.00 —
4	1SET BUMPER BRACKET SIDE CLIP RH RR	$	Sn	10.00 X
5	1SET BUMEPR RETAINER RH CLIP RR	$	Sn	20.00 X
6	1SET BUMEPR BRACKET SIDE CLIP LH RR	$	Sn	10.00 X
7	1SET BUMEPR RETAINER CLIP LH RR	$	Sn	20.00 X
8	1SET BUMPER LOWER REAR RIVET	$	Sn	22.00 X
9	1SET BUMPER LOWER REAR CLIP	$	Sn	66.00 —
10	1 EXHAUST MOUNTING REAR	$	Sn	17.82 X
11	2 REAR WINDSCREEN SELANT	$	Sn	80.00 X
12	1 WINDSCREEN MOULDING	$	Sn	100.00 X
13	1 REAR WINDSCREEN INNER SPONGE SEAL	$	Sn	100.00 X
		TOTAL	**$**	**1,244.82**
		TOTAL PARTS	**$**	**17,284.25**

LABOUR

Putty And Spray Painting Of The Affected Portion.	$	3,000.00	220
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	$	2,200.00	200

Trans-cab Auto Services Pte Ltd **AAD1811-103**

No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel No. : 6287 6666 Fax No. : 6257 1330
CO./GST Reg. No. 201019626G
SHF 692B

To Rust-Proofing Of The Affected Areas.	$	170.00	X
To reinstall rear bumper parking sensor.	$	170.00	60
To transfer of bootlid fittings, attachments and perform water seepage test.	$	170.00	X
To repair and realign rear exhaust pipe.	$	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	$	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	$	170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	$	170.00	X
To check steering geometry and computer wheel alignment	$	220.00	X
TOTAL	**$**	**6,610.00**	
Over All Total	**$**	**39,933.69**	

(LUMP SUM)
Repair Days ~~10~~ **DAYS**
2 days

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: