PREMIER AUTOMOTIVE SERVICES PTE LTD

15-Nov-18

ESTIMATE REPAIR BILL FOR HYUNDAI I30A REGN NO: SHB 8358 K

1 pc	Rear n/s fender		$ 1,525.73
1 pc	Rear n/s fender inner shield		$ 205.29
1 pc	Rear bumper n/s side bracket		$ 32.50
1pc	Rear bumper		$ 811.11
1 pc	Rear bumper n/s reflector	✗	$ 107.50
1 pc	fuel cap	✗ repair	$ 34.10
1 pc	rim	✗ repair	$ 246.00
			$ 2,962.23
		Less 20%	$ 592.45
			$ 2,369.78

Stamp: LKK Auto Co... the Repairer ...
• To resurvey b...
• To display dam...
• Parts prices a...
• Third party surve...
• No illegal modifi...wed
• Supplementary item(s)...
is subject to final approval...
Acknowledged by Repairer
Signature:
Date:

(handwritten) 15/11/18 1330hr   4 Days   P'P   Before Paint photo

S/NETT

1 set	Rear bumper clips		$ 48.00
1 set	Bootlid stickers		$ 100.00
1 set	n/s door sticker		$ 100.00
1 pc	Rear n/s fender sticker		$ 60.00

Sundry		$ ~~50.00~~ 20
To dismantle / refit reverse sensor to new bumper and reset to the same		$ ~~120.00~~ 30
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		$ ~~180.00~~ 50
To dismantle and fit the rear n/s fender quarter glass to facilitate repair on the rear n/s fender		$ ~~80.00~~ 50
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the rear n/s fender. Including knock-out, straighten, repair, reshape and adjust of the same etc		$ ~~1,000.00~~ 600
To putty and spray painting on rear bumper, rear n/s fender, rear n/s door, tailgate lower garnish, n/s rocker panel ✗		$ ~~1,000.00~~ 720
To apply rustproofing on the repaired and replaced panels.		$ ~~150.00~~ 50
		$ 5,257.78

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.