6741 8432A Catherine

Allswell Motor Traders

25 Defu Lane 9. Singapore 539266
Tel : +65 6679 1146 email:ben@allswellmotor.com.sg

accounts@allswellmotor.

(3rd party claim against FCI insured)

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Estimate repair

Vehicle No.	: SLG7490T	Submitted by	: Ben
Make & Model	: Toyota AXIO 1.5	COE expiry	: 11-10-2026
Chassis No.	: hybrid	Engine No.	:
Date of survey	: 22/11/18		

S/No	Part Description	Qty	Unit Price	Price	Disposition by
01	Rear bumper	01	$1,219.00	✓	DD ✓
02	Rear boot	01	$1,312.00	✓	DD ✓
03	End panel	01	~~$795.60~~		~~NA~~
04.	End panel top trim	01	$193.00	✓	DL ✓
~~05~~	~~boot hinges 2x~~	~~01+01~~	~~$179.00~~		~~NA~~
~~06~~	~~boot lock and cover~~	~~01+01~~	~~$269.50~~		~~NA~~ BT
07	LH rear lamp	01	$735.30	✓	BR ✓
08.	RH rear lamp	01	$735.30	✓	BR ✓
~~09~~	~~Reinforcement bar~~	~~01~~	~~$490.00~~		~~NA~~ – NN
10.	Boot weatherweld	01	$190.00	✓	TA ✓
11	LH / RH rear fender @ $650.00 each	02	$1,300.00		~~No repair~~ – NN
				4654.1	
	Special nett		@ 25%		
01	Clips for bumper, lamp & etc 01 pkt / $40.00	01	$40.00	3490.575	NEC ✓
	Labour Description				
01	Dismantle / Assembly of affected parts	01	$1,000.00	800/h	
02	Panel beating / welding of end panel, LH / RH fender	01	$1,200.00		
03	Spray painting of affected parts including, spray paint, anti-rust, polish & wash	01	$1,200.00	– 6 hrs	
			13.4.10		
			Total	3944.46	

Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.

4/S 3,000/2

Days of Repair 5

14/12/18.

TGLim 23/11/18

10858.20