22/03/2002

ASS. REC. BY: | REF: CS3 / CTL18B1665 / Ycbs | Special Instruction:

Surveyor: Rosli

ASSIGNMENT (Office)

From (Person): Irene Tay of CTL Date/Time: 30112018 4.34 pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBE 3326R Insured: SKW 726M

at Workshop m/s Han Car Tel:

of Blk 1001 bukit merah Lane 3 # 01-49

Policy No: DMPCSN 306297 1800 Claim No: SNM18D05551C02

Sum Insured: Excess:

Make of Veh: D.O.A. 26112018

(Client's Record)

CA / REV / REP. / REV 24 HRS wpi H.O.D. Endorsement:

Date/Time: 03122018 1030am Person Contacted: Vehicle **IN / OUT**

Date/Time	Action/Instruction (X) Estimate
	GBE 3326R - NA/CTL18D21348 / Z4 DOA: 26112018
	SKW 726M - X
	~~Range $3,000/- 4000/-~~
	TGLM 12/12/18

ASS. REC. BY: | REF: Y | Rosl

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBK 3326 R

at Workshop m/s HOM CAR

of BLK 1001 #01-49 BT MERAH LANE 3

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: GBK 3326 R Yr Regn: Oct / 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: TOYOTA PRIMA c.c 2982

Colour SILVER A/C: Insured / Std / NI / NA

Sp.Reading 113221 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KDY231R-021321

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : NIL / S/Rim / STD A/Rim or

Tyre Size: F: 195/R15C

R: 165/R13C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6/6 mm	L/Bal.	6/6 mm
D.O.A.		D.O.I.	03/12/2018

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
02/06/2018	1130am (TPO)
	CANOPY ALIGNMENT OUT
	Range 4600/2 – 5,300/2
	TGLim 12/12/18

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format : PRS

Lump Sum / I.B.I: ($)

Survey Fee:

Transportation: ___S + RS___SI

Photos

Others

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Nov 2018		30 Nov 2018 16:34 Assign				***New Assignment*** Cancel Case

Main | Reference | Claim Details | Documents | Show All

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:			
Main Claimant:	**LIAN HIN PTE LTD**		
Vehicle Reg. No.:	**GBE3326R**	Date of Loss:	26/11/2018 10:00 - :59
Claim Type:	**TP** / SNM18D05551C02	Policy/Cover Note No.:	DMPCSN3062971800
Vehicle Reg. No. (Insured):	**SKW726M**	Policy No. (Claimant):	
		Excess:	S$0.00
Repairer:	**Han Car Repairs (HQ)** BLK 1001 BUKIT MERAH LANE 3 #01-49 ALEXANDRA VILLAGE, 159718 Alexandra - Tel: 62710275		
Handling Insurer:	**China Taiping Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: 6389 6111 ... [Handled by **Irene Tay Hui Ping** - 638986192]		
Adjuster:	**LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [**Final Rpt** due 11/12/2018]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED View All | Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?

No results.

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details

Vehicle No. :	GBE3326R
Vehicle Type :	A50 - Goods (Closed) Van/Van Panel (Delivery)
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	TOYOTA
Vehicle Model :	DYNA 3.0 DIESEL TURBO M/T 2WD LORRY
Chassis No. :	KDY2318021321
Propellant :	Diesel
Engine No. :	1KD2551045
Engine Capacity :	2982 cc
Maximum Power Output :	-
Maximum Laden Weight :	3425 kg
Unladen Weight :	1760 kg
Year Of Manufacture :	2015
Original Registration Date :	23 Oct 2015
Lifespan Expiry Date :	22 Oct 2035
COE Category :	C - Goods Vehicle & Bus
PQP Paid :	$18,909.00
COE Expiry Date :	22 Oct 2025
Road Tax Expiry Date :	22 Apr 2019
Inspection Due Date :	22 Oct 2019
Intended Transfer Date :	21 Dec 2018
CO2 Emission :	170.00 (g/km)
CEV/VES Rebate Utilised Amount :	-
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S$)	GST Amount (S$)	Amount After GST (S$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			**25.00**

You may print this page for reference.

OK Print

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	6186N
Vehicle Details	
Vehicle No.:	GBE3326R
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Dec 2018
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 3.0 DIESEL TURBO M/T 2WD LORRY
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	1KD2551045
Chassis No.:	KDY2318021321
Maximum Power Output:	-
Open Market Value:	$31,329.00
Original Registration Date:	23 Oct 2015
First Registration Date:	23 Oct 2015
Transfer Count:	2
Actual ARF Paid:	$1,567.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	$0.00
Intended COE Rebate Details	
COE Expiry Date:	22 Oct 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	$18,909.00
COE Rebate Amount:	$12,926.00
Total Rebate Amount:	**$12,926.00**

The information contained herein is correct as at 21 Dec 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Nov 2018		30 Nov 2018 16:34 Edit Adj Rpt	**S$0.00** Edit Estimates	**S$0.00** View Rpt		**Pending for Survey Report** Cancel Case

Main | Reference | Claim Details | Documents | Show All

CLAIM SUBFOLDER DETAILS **[Created by insurer]**

Insured:	-, Co. Reg. No.: -		
Main Claimant:	**LIAN HIN PTE LTD**		
Vehicle Reg. No.:	**GBE3326R**	Date of Loss:	26/11/2018 10:00 - :59 [**37** Months and **3** Days From LTA Reg Date (Man Yr)]
Claim Type:	**TP** / SNM18D05551C02	Policy/Cover Note No.:	DMPCSN3062971800
Vehicle Reg. No. (Insured):	**SKW726M**	Policy No. (Claimant):	
		Excess:	S$0.00
Repairer:	**Han Car Repairs (HQ)** BLK 1001 BUKIT MERAH LANE 3 #01-49 ALEXANDRA VILLAGE, 159718 Alexandra - Tel: 62710275		
Handling Insurer:	**China Taiping Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: 6389 6111 ... [Handled by **Irene Tay Hui Ping** - 638986192]		
Adjuster:	**LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **ROSLI BIN ABDUL WAHAB**] ... [**Final Rpt** due 11/12/2018]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED View All | Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?

No results.

Claim Documents

***GBE3326R (SNM18D05551C02)**
[SKW726M]
TP
LIAN HIN PTE LTD
Nov 26 2018 10:00AM
[-]
Han Car Repairs

Upload Documents | Upload Photos | Compose New Letter

View: View in Browser

Photos/Images — 3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/12/18 14:42	**General View**	1	Load PDF	
2	07/12/18 14:47	**Photographs of Damaged Parts**	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST — Reset | Save | Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18021665/YCBS2
Date: 26/12/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3062971800		
Claimant Vehicle No :	GBE3326R	**Insured Vehicle No :**	SKW726M		
Date of Loss:	26/11/2018	Nature of Claim:	TP	Claim No:	SNM18D05551C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	**GBE3326R**		
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Engine No:	1KD2551045
Reg. Date:	23/10/2015 (Man. Year: 2015)	Chassis No:	KDY2318021321
Colour:	Silver	Odometer:	113221 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S$):	**Market Value/New Car Price**		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/R15C	Rear Tyre Size:	165/R13 (D)
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6/6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S$)	**0.00**	**0.00**	**0.00**	

INSPECTION

Date of Assignment: 30/11/2018

Date Inspected: 03/12/2018 Inspected At:

Han Car Repairs (HQ)
BLK 1001 BUKIT MERAH LANE 3 #01-49
ALEXANDRA VILLAGE
Singapore 159718

Estimated Period of Repair: 6.0 days

Adjuster: ROSLI BIN ABDUL WAHAB **Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF $4,600.00 - $5,300.00

REPAIR DETAILS

Reference

Part Source:		(Last Synchronised: 26 Dec 2018)
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE3326R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >