RICO60 AUTO SERVICES

Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VECHICLE NUM:	PC 6671 T
MAKE & MODEL:	TOYOTA HIACE
MILEAGE:	
TYRE:	
CHASSIS NUM:	

4/5

6 by. not Agent 5/10/18

ATTN:

NO.	DESCRIPTION - PARTS		QTY	PRICE
1	FRONT BONNET	n X	1	
2	FRONT BONNET LOGO	new —	1	
3	FRONT BONNET HINGE L+R	nn X	2	
4	FRONT BONNET RUBBER	nn X	1	
5	FRONT BONNET LOCK	nn X	1	
6	FRONT GRILLE ASSY	RA X	1	
7	FRONT BUMPER	D/S —	1	
8	FRONT BUMPER BEAM	DD/Bep —	1	
9	FRONT BUMPER REINFORCEMENT BAR	RX	1	
10	FRONT BUMPER RETAINER L+R	O/Scne 1PC	2	
11	FRONT BUMPER BRACKET L+R	nn X	2	
12	FRONT BUMPER TOWING COVER	nn X	1	
13	FRONT BUMPER FOG LAMP	nR X	2	
14	FRONT BUMPER FOG LAMP GARNISH	Scn —	2	
15	FRONT HEADLAMP L+R	O/S Bro 1PC	2	
16	FRONT HEADLAMP PANEL RH	n X	1	
17	SIDE PANEL RH	Bue —	1	
18	FRONT SUPPORT PANEL	n X	1	
19	FRONT BRACE PANEL	nn X	1	
20	WIRE HARNESS	nn X	1	
20	AIR CON CONDENSER	nn X	1	
21	RADIATOR	nn X	1	
22	RADIATOR SPARE TANK	nn X	1	
23	TURBO COOLER	nn X	1	
24	WASHER TANK	nn X	1	
25	WASHER TANK MOTOR	nn X	1	
26	FRONT DOOR RH	DD/Bel —	1	
27	FRONT DOOR HINGE UP AND DOWN	nn X	2	
28	FRONT DOOR CHECKER	nn X	1	
29	FRONT DOOR WINDOW MOULDING	nn X	1	
30	FRONT DOOR LOWER STEP PANEL	n X	1	
31	FRONT DOOR LOWER STEP PANEL GARNISH	Tw... —	1	
32	REAR FENDER RH	B.d500 —	1	
33	REAR FENDER GLASS MOULDING RH	nn X	1	
34	REAR FENDER DOOR RAILING RH	Bel —	1	
	Air Cleaner box 500 —			
		SUBTOTAL		$ -
		LESS 25%		$ -
		PARTS TOTAL		$ -

	SPECIAL NETT		QTY	PRICE
	RADIATOR COOLANT	11 X	1	$ 120.00
	FRONT BUMPER CLIPS	30	10	$ 100.00
	FRONT BUMPER LOWER SPOILER	800	1	$ 4,000.00
	REAR FENDER SEALANT	~~40~~ 11 X	1	$ 120.00
	REAR FENDER GLASS SEALANT	40	1	$ 120.00
	SPECIAL NETT TOTAL			$ 4,460.00

	LABOUR		QTY	PRICE
1	TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD ,KNOCK&REALIGN	1100	1	$ 3,000.00
	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	1000	1	$ 3,000.00
	TO RUST PROOF ACCIDENT AFFECTED AREA	80	1	$ 120.00
	TO RNR FRONT DOOR MECHANISM	60	1	$ 200.00
	TO RNR A/C CONDENSOR ASSY AND REFILL GAS	11 X	1	$ 250.00
	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	20	1	$ 150.00
	TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD	11 X	1	$ 250.00
	TO RNR REAR FENDER DOOR RAILING AND CHECK FUNCTION	80	1	$ 120.00
	LABOUR TOTAL			$ 7,090.00
	GRAND TOTAL COST			$ 11,550.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: