Surveyor: Tan [illegible] | REF: ASMLAXAJ | 284/71 (2)-1 | Gra

ASSIGNMENT

From | Date: 16.01.2019

Estimated Cost:

OD / TP (circled) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLX 2285

at Workshop m/s: Cycle & Carriage

of: 188 Pandan Loop.

Insured:

Policy No:

Claims No.

Sum Insured: | Excess:

(Client's Record)

Make of Veh: Yik.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: $185K

IDAC Accident Rport: | Consistent? : Yes or No

GIA / PR Seen: | Consistent? : Yes or No

Est. Repairs: days | Res.: Yes or No

Lum Sum: % | 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: | Person Contacted: Yik

Veh No: SLX2285 | Yr Regn: 2018 Feb.

Type: M/Car (circled) / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Mercedes Benz E200 | c.c 1991

Colour: Silver | A/C: Insured / Std / NI / NA

Sp.Reading: 27427 | T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD2130422A339050

Gen. Cond: Good (circled) / Fair / Poor / Burnt

Steering: Inorder (circled) / Jammed / Leaked / Burnt or

Brake: Inorder (circled) / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim (circled) / STD A/Rim or

Tyre Size: F: 245/45R18

R: " "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR (circled) / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	4 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	16/1/19

Survey held at: CRC Pandan Loop

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Frt o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? 1) | ☐ : Preli. Report | ☐ : Final Report

Date/Time, File Return to? 2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:) __S + RS __SI

Add Fee: ☐ : Site Insp ($ | ☐ Interview ($) Photos | ☐ Tech. Invs ($) Others | ☐ Weekend ($)

TOTAL

Report Format :

Lump Sum / I.B.I: ($)